

DOCUMENT SUBMISSION STATUS: FF

NOTE:

THIS IS A TYPICAL LIST, WILL ALSO BE USED FOR UNIT 2.

|      |            |             |       |         |          |          |
|------|------------|-------------|-------|---------|----------|----------|
|      |            |             |       |         |          |          |
|      |            |             |       |         |          |          |
|      |            |             |       |         |          |          |
| 1    | 2014.09.12 | FOR FINAL   | YXP   | HW      | ZYQ      |          |
| 0    | 2014.05.26 | FOR FINAL   | YXP   | HW      | ZYQ      |          |
| REV. | DATE       | DESCRIPTION | DRAWN | CHECKED | APPROVED | APPROVED |

|                                                                                                                                             |  |  |                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |  |  |  |
|---------------------------------------------------------------------------------------------------------------------------------------------|--|--|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|--|
| <b>OWNER</b><br><br><b>VIETNAM OIL AND GAS GROUP (PVN)</b> |  |  | <b>OWNER'S CONSULTANT</b><br><div style="display: flex; justify-content: space-around; align-items: center;"> <div style="text-align: center;"> <br/> <b>FICHTNER</b><br/>             GmbH &amp; Co. KG         </div> <div style="text-align: center;"> <br/> <b>PVPOWER PCC</b> </div> </div> |  |  |  |
|---------------------------------------------------------------------------------------------------------------------------------------------|--|--|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|--|

|                                                                                                                                                                                |  |  |                                                                                                                                                                                                 |  |  |  |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|--|
| <b>EPC CONTRACTOR</b><br><br><b>PETROVIETNAM CONSTRUCTION JOINT STOCK CORPORATION (PVC)</b> |  |  | <b>EPC CONSTRUCTOR'S CONSULTANT</b><br><div style="text-align: center;"> <br/> <b>WORLEYPARSONS</b> </div> |  |  |  |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|--|

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |  |  |  |  |  |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|--|--|--|
| <b>POWER ISLAND PACKAGE SUPPLIER</b><br><div style="display: flex; justify-content: space-around; align-items: center;"> <div style="text-align: center;"> <br/> <b>SOJITZ CORPORATION</b> </div> <div style="text-align: center;"> <br/> <b>DAELIM INDUSTRIAL CO., LTD.</b> </div> </div> |  |  |  |  |  |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|--|--|--|

|                                                                                                             |  |  |  |  |  |
|-------------------------------------------------------------------------------------------------------------|--|--|--|--|--|
| <b>PROJECT TITLE</b><br><p style="text-align: center;"><b>THAI BINH 2 THERMAL POWER PLANT 2 x 600MW</b></p> |  |  |  |  |  |
|-------------------------------------------------------------------------------------------------------------|--|--|--|--|--|

|                                                                                                                                              |  |  |  |  |  |
|----------------------------------------------------------------------------------------------------------------------------------------------|--|--|--|--|--|
| <b>DRAWING / DOCUMENT TITLE</b><br><p style="text-align: center;"><b>ASSEMBLY LIST FOR TIER 4 OF THE BOILER STRUCTURAL SUPPORT STEEL</b></p> |  |  |  |  |  |
|----------------------------------------------------------------------------------------------------------------------------------------------|--|--|--|--|--|

|                                                                                                                                                                              |             |                |                                                                                       |            |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|----------------|---------------------------------------------------------------------------------------|------------|
| <div>BIP SUPPLIER:</div> <div></div> <div>BABCOCK &amp; WILCOX BEIJING COMPANY LTD.</div> | FUNCTION    | NAME           | SIGN                                                                                  | DATE       |
|                                                                                                                                                                              | DRWN        | Yang Xiaopeng  |  | 2014.09.12 |
|                                                                                                                                                                              | CHKD        | Huang Wei      |  | 2014.09.12 |
|                                                                                                                                                                              | APPD        | Zhang Yongqian |  | 2014.09.12 |
| DOCUMENT NO: TB2-SDC.VP101-01UHA-A-M1A-LST-0010                                                                                                                              | No of page: |                | Scale                                                                                 | Rev.1      |



|                  |                                                                    |
|------------------|--------------------------------------------------------------------|
| P.O NO.          | 110180-1600-101-001-A01                                            |
| ITEM NO.         | UHA                                                                |
| ITEM DESCRIPTION | BOILER STRUCTURAL SUPPORT STEEL                                    |
| DOCUMENT NO.     | TB2-SDC.VP101-01UHA-A-M1A-LST-0010                                 |
| DOCUMENT TITLE   | ASSEMBLY LIST FOR TIER 4 OF THE BOILER<br>STRUCTURAL SUPPORT STEEL |
| REV NO.          | 1                                                                  |

### **Daelim's Approval Status**

|                                                                                                                                                                         |                                           |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------|
| <b>Daelim Industrial Co., Ltd.</b>                                                                                                                                      |                                           |
| <b>Job No.</b>                                                                                                                                                          | <b>110180</b>                             |
|                                                                                                                                                                         | <b>A - APPROVED</b>                       |
|                                                                                                                                                                         | <b>B - APPROVED WITH COMMENTS</b>         |
|                                                                                                                                                                         | <b>C - RETURNED FOR CORRECTION</b>        |
|                                                                                                                                                                         | <b>D - REJECTED</b>                       |
|                                                                                                                                                                         | <b>N - NOT APPLICABLE(REFERENCE ONLY)</b> |
| <b>SIGNED BY :</b>                                                                                                                                                      | <b>DATE :</b>                             |
| <b>DIC'S PERMISSION TO PROCEED OR REVIEW TAKEN ON VENDOR<br/>PRINTS SHALL NOT RELIEVE VENDOR FROM ITS RESPONSIBILITIES<br/>OR LIABILITIES UNDER THE PURCHASE ORDER.</b> |                                           |

**BIP SUPPLIER:**



**BABCOCK & WILCOX BEIJING COMPANY LTD.**



**ASSEMBLY LIST FOR TIER 4 OF THE BOILER STRUCTURAL SUPPORT STEEL**

| No. | DRAWING_NO.                        | ASSEMBLY_M.     | PIECE_NO.    | QTY. | SIZE             | LEN. (mm) | WEIGHT (kg) | TOTAL_W(kg) | REV. | REMARK |
|-----|------------------------------------|-----------------|--------------|------|------------------|-----------|-------------|-------------|------|--------|
| 1   | TB2-SDC.VP101-00UHA-A-M1A-DTE-2646 | BD 2. 5/12. 5-4 | PN1622140183 | 1    | BH448*480*14*24  | 14500     | 3350. 65    | 3350. 65    | 0    |        |
| 2   | TB2-SDC.VP101-00UHA-A-M1A-DTE-2647 | BD 3. 5/13. 5-4 | PN1622140184 | 1    | BH480*620*20*40  | 14500     | 6857. 39    | 6857. 39    | 0    |        |
| 3   | TB2-SDC.VP101-00UHA-A-M1A-DTE-2648 | BD 4. 5/14. 5-4 | PN1622140185 | 1    | BH472*560*14*36  | 14500     | 5456. 77    | 5456. 77    | 0    |        |
| 4   | TB2-SDC.VP101-00UHA-A-M1A-DTE-2649 | BD 5. 5/15. 5-4 | PN1622140186 | 1    | BH472*560*14*36  | 14500     | 5340. 64    | 5340. 64    | 0    |        |
| 5   | TB2-SDC.VP101-00UHA-A-M1A-DTE-2650 | BD 5/15-4       | PN1622140187 | 1    | BH460*600*14*30  | 14500     | 4829. 32    | 4829. 32    | 0    |        |
| 6   | TB2-SDC.VP101-00UHA-A-M1A-DTE-2651 | BD 6. 5/16. 5-4 | PN1622140188 | 1    | BH480*620*20*40  | 14500     | 6743. 76    | 6743. 76    | 0    |        |
| 7   | TB2-SDC.VP101-00UHA-A-M1A-DTE-2652 | BD 7. 5/17. 5-4 | PN1622140189 | 1    | BH448*480*14*24  | 14500     | 3350. 65    | 3350. 65    | 0    |        |
| 8   | TB2-SDC.VP101-00UHA-A-M1A-DTE-2653 | BE 2. 5/12. 5-4 | PN1622140190 | 1    | BH460*420*14*30  | 14430     | 3664. 82    | 3664. 82    | 0    |        |
| 9   | TB2-SDC.VP101-00UHA-A-M1A-DTE-2654 | BE 3. 5/13. 5-4 | PN1622140191 | 1    | BH640*920*30*80  | 14640     | 19149. 71   | 19149. 71   | 0    |        |
| 10  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2655 | BE 6. 5/16. 5-4 | PN1622140192 | 1    | BH640*920*30*80  | 14640     | 19149. 71   | 19149. 71   | 0    |        |
| 11  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2656 | BE 7. 5/17. 5-4 | PN1622140193 | 1    | BH460*420*14*30  | 14430     | 3664. 82    | 3664. 82    | 0    |        |
| 12  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2657 | BF 2. 5/12. 5-4 | PN1622140194 | 1    | BH460*420*14*30  | 14430     | 3664. 82    | 3664. 82    | 0    |        |
| 13  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2658 | BF 3. 5/13. 5-4 | PN1622140195 | 1    | BH640*1000*30*80 | 14640     | 20700. 87   | 20700. 87   | 0    |        |
| 14  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2659 | BF 6. 5/16. 5-4 | PN1622140196 | 1    | BH640*1000*30*80 | 14640     | 20700. 87   | 20700. 87   | 0    |        |
| 15  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2660 | BF 7. 5/17. 5-4 | PN1622140197 | 1    | BH460*420*14*30  | 14430     | 3664. 82    | 3664. 82    | 0    |        |
| 16  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2661 | BG 2. 5/12. 5-4 | PN1622140198 | 1    | BH460*540*14*30  | 14500     | 4539. 5     | 4539. 5     | 0    |        |
| 17  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2662 | BG 3. 5/13. 5-4 | PN1622140199 | 1    | BH640*920*30*80  | 14640     | 19149. 72   | 19149. 72   | 0    |        |
| 18  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2663 | BG 6. 5/16. 5-4 | PN1622140200 | 1    | BH640*920*30*80  | 14640     | 19149. 72   | 19149. 72   | 0    |        |
| 19  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2664 | BG 7. 5/17. 5-4 | PN1622140201 | 1    | BH460*540*14*30  | 14500     | 4539. 5     | 4539. 5     | 0    |        |
| 20  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2665 | BH 2. 5/12. 5-4 | PN1622140202 | 1    | BH460*580*14*30  | 14500     | 4712. 51    | 4712. 51    | 0    |        |
| 21  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2666 | BH 3. 5/13. 5-4 | PN1622140203 | 1    | BH480*600*20*40  | 14500     | 6530. 19    | 6530. 19    | 0    |        |
| 22  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2667 | BH 5/15-4       | PN1622140204 | 1    | BH620*700*30*70  | 14710     | 13479. 25   | 13479. 25   | 0    |        |
| 23  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2668 | BH 6. 5/16. 5-4 | PN1622140205 | 1    | BH480*600*20*40  | 14500     | 6530. 19    | 6530. 19    | 0    |        |
| 24  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2669 | BH 7. 5/17. 5-4 | PN1622140206 | 1    | BH460*580*14*30  | 14500     | 4712. 51    | 4712. 51    | 0    |        |
| 25  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2670 | BI 2. 5/12. 5-4 | PN1622140207 | 1    | BH448*480*14*24  | 14430     | 3319. 79    | 3319. 79    | 0    |        |
| 26  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2671 | BI 3. 5/13. 5-4 | PN1622140208 | 1    | BH480*640*20*40  | 14500     | 6935. 13    | 6935. 13    | 0    |        |
| 27  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2672 | BI 5/15-4       | PN1622140209 | 1    | BH500*780*20*50  | 14570     | 10222. 9    | 10222. 9    | 0    |        |
| 28  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2673 | BI 6. 5/16. 5-4 | PN1622140210 | 1    | BH480*640*20*40  | 14500     | 6935. 13    | 6935. 13    | 0    |        |
| 29  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2674 | BI 7. 5/17. 5-4 | PN1622140211 | 1    | BH448*480*14*24  | 14430     | 3319. 79    | 3319. 79    | 0    |        |
| 30  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2675 | BJ 2. 5/12. 5-4 | PN1622140212 | 1    | BH440*440*14*20  | 14430     | 2710. 9     | 2710. 9     | 0    |        |
| 31  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2676 | BJ 3. 5/13. 5-4 | PN1622140213 | 1    | BH460*480*14*30  | 14500     | 4006. 39    | 4006. 39    | 0    |        |
| 32  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2677 | BJ 5/15-4       | PN1622140214 | 1    | BH480*600*20*40  | 14500     | 6530. 2     | 6530. 2     | 0    |        |
| 33  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2678 | BJ 6. 5/16. 5-4 | PN1622140215 | 1    | BH460*480*14*30  | 14500     | 4006. 39    | 4006. 39    | 0    |        |
| 34  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2679 | BJ 7. 5/17. 5-4 | PN1622140216 | 1    | BH440*440*14*20  | 14430     | 2710. 9     | 2710. 9     | 0    |        |
| 35  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2680 | 4VB-1           | PN1622140217 | 1    | BH300*400*12*20  | 13386. 3  | 2118. 8     | 2118. 8     | 0    |        |
| 36  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2681 | 4VB-2           | PN1622140218 | 1    | BH300*340*10*20  | 5407. 8   | 756. 39     | 756. 39     | 0    |        |
| 37  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2682 | 4VB-3           | PN1622140219 | 1    | BH300*500*14*30  | 3856. 6   | 1158. 31    | 1158. 31    | 0    |        |
| 38  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2683 | 4VB-4           | PN1622140220 | 1    | BH300*380*12*20  | 9648. 9   | 1462. 48    | 1462. 48    | 0    |        |
| 39  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2684 | 4VB-5           | PN1622140221 | 1    | BH300*380*12*20  | 9968. 9   | 1508. 5     | 1508. 5     | 0    |        |
| 40  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2685 | 4VB-6           | PN1622140222 | 1    | BH300*400*12*24  | 11640. 1  | 2114. 42    | 2114. 42    | 0    |        |
| 41  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2686 | 4VB-7           | PN1622140223 | 1    | BH300*400*12*24  | 11710. 1  | 2126. 63    | 2126. 63    | 0    |        |
| 42  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2687 | 4VB-8           | PN1622140224 | 1    | BH300*440*12*24  | 4509. 1   | 983. 29     | 983. 29     | 0    |        |
| 43  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2688 | 4VB-9           | PN1622140225 | 1    | BH300*400*12*20  | 13386. 3  | 2118. 8     | 2118. 8     | 0    |        |
| 44  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2689 | 4VB-10          | PN1622140226 | 1    | BH300*440*12*24  | 4815. 8   | 1058. 73    | 1058. 73    | 0    |        |
| 45  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2690 | 4VB-11          | PN1622140227 | 1    | BH300*340*10*20  | 5375. 8   | 729. 17     | 729. 17     | 0    |        |
| 46  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2691 | 4VB-12          | PN1622140228 | 1    | BH300*340*10*20  | 5390. 8   | 731. 83     | 731. 83     | 0    |        |
| 47  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2692 | 4VB-13          | PN1622140229 | 1    | BH300*400*12*24  | 11640. 1  | 2114. 42    | 2114. 42    | 0    |        |
| 48  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2693 | 4VB-14          | PN1622140230 | 1    | BH300*480*14*30  | 2180. 1   | 591. 14     | 591. 14     | 0    |        |
| 49  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2694 | 4VB-15          | PN1622140231 | 2    | BH300*360*10*20  | 5586. 3   | 841. 86     | 1683. 72    | 0    |        |
| 50  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2695 | 4VB-16          | PN1622140232 | 1    | BH300*340*10*20  | 5237. 9   | 734. 78     | 734. 78     | 0    |        |
| 51  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2696 | 4VB-17          | PN1622140233 | 1    | BH300*360*12*24  | 1962. 5   | 371. 66     | 371. 66     | 0    |        |
| 52  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2697 | 4VB-18          | PN1622140234 | 1    | BH300*340*10*20  | 5350. 7   | 748. 3      | 748. 3      | 0    |        |
| 53  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2698 | 4VB-19          | PN1622140235 | 2    | BH300*340*10*20  | 6299. 6   | 870. 95     | 1741. 9     | 0    |        |
| 54  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2699 | 4VB-20          | PN1622140236 | 2    | HW250*250*9*14   | 5092. 5   | 408. 3      | 816. 59     | 0    |        |
| 55  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2700 | 4VB-21          | PN1622140237 | 1    | BH300*480*14*30  | 3055      | 929. 01     | 929. 01     | 0    |        |
| 56  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2701 | 4VB-22          | PN1622140238 | 1    | BH300*340*10*20  | 5237. 9   | 734. 78     | 734. 78     | 0    |        |
| 57  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2702 | 4VB-23          | PN1622140239 | 1    | BH300*420*12*24  | 12823. 1  | 2382. 57    | 2382. 57    | 0    |        |
| 58  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2703 | 4VB-24          | PN1622140240 | 1    | BH300*400*12*24  | 3987. 3   | 757. 58     | 757. 58     | 0    |        |
| 59  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2704 | 4VB-25          | PN1622140241 | 1    | HW300*300*10*15  | 5628      | 554. 01     | 554. 01     | 0    |        |
| 60  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2705 | 4VB-26          | PN1622140242 | 1    | BH300*420*12*24  | 4974. 9   | 1010. 1     | 1010. 1     | 0    |        |
| 61  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2706 | 4VB-27          | PN1622140243 | 2    | BH300*340*10*20  | 5237. 9   | 735. 94     | 1471. 87    | 0    |        |
| 62  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2707 | 4VB-28          | PN1622140244 | 1    | HW300*300*10*15  | 5516. 1   | 543. 61     | 543. 61     | 0    |        |
| 63  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2708 | 4VB-29          | PN1622140245 | 1    | HW200*200*8*12   | 5072      | 297. 65     | 297. 65     | 0    |        |
| 64  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2709 | 4VB-30          | PN1622140246 | 1    | HW200*200*8*12   | 4304      | 242. 59     | 242. 59     | 0    |        |
| 65  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2710 | 4VB-31          | PN1622140247 | 1    | HW250*250*9*14   | 5092. 5   | 408. 3      | 408. 3      | 0    |        |
| 66  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2711 | 4VB-32          | PN1622140248 | 1    | HW250*250*9*14   | 5092. 5   | 408. 3      | 408. 3      | 0    |        |
| 67  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2712 | 4VB-33          | PN1622140249 | 1    | HW250*250*9*14   | 5075. 1   | 407. 04     | 407. 04     | 0    |        |



|     |                                    |         |              |   |                 |         |         |         |   |  |
|-----|------------------------------------|---------|--------------|---|-----------------|---------|---------|---------|---|--|
| 68  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2713 | 4VB-34  | PN1622140250 | 1 | BH300*400*12*24 | 3490    | 986.78  | 986.78  | 0 |  |
| 69  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2714 | 4VB-35  | PN1622140251 | 1 | HW250*250*9*14  | 4965.2  | 399.09  | 399.09  | 0 |  |
| 70  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2715 | 4VB-36  | PN1622140252 | 1 | HW250*250*9*14  | 4623    | 374.32  | 374.32  | 0 |  |
| 71  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2716 | 4VB-37  | PN1622140253 | 1 | HW250*250*9*14  | 5011.1  | 402.41  | 402.41  | 0 |  |
| 72  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2717 | 4VB-38  | PN1622140254 | 1 | BH300*420*12*24 | 4975.3  | 1010.17 | 1010.17 | 0 |  |
| 73  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2718 | 4VB-39  | PN1622140255 | 1 | BH300*340*10*20 | 6075.2  | 842.42  | 842.42  | 0 |  |
| 74  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2719 | 4VB-40  | PN1622140256 | 1 | BH300*500*14*30 | 2903.9  | 834.3   | 834.3   | 0 |  |
| 75  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2720 | 4VB-41  | PN1622140257 | 1 | BH300*440*12*24 | 4509.1  | 983.29  | 983.29  | 0 |  |
| 76  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2721 | 4VB-42  | PN1622140258 | 1 | HW300*300*10*15 | 5720    | 561.76  | 561.76  | 0 |  |
| 77  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2722 | 4VB-43  | PN1622140259 | 1 | BH300*360*12*20 | 4913.7  | 768.12  | 768.12  | 0 |  |
| 78  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2723 | 4VB-44  | PN1622140260 | 1 | BH300*420*12*24 | 4975.3  | 1010.17 | 1010.17 | 0 |  |
| 79  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2724 | 4VB-45  | PN1622140261 | 1 | BH300*360*12*20 | 4920.1  | 769     | 769     | 0 |  |
| 80  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2725 | 4VB-46  | PN1622140262 | 1 | BH300*360*12*20 | 4320.5  | 825.23  | 825.23  | 0 |  |
| 81  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2726 | 4VB-47  | PN1622140263 | 2 | BH300*340*10*20 | 5545    | 774.99  | 1549.98 | 0 |  |
| 82  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2727 | 4VB-48  | PN1622140264 | 1 | HW300*300*10*15 | 5253.6  | 528.7   | 528.7   | 0 |  |
| 83  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2728 | 4VB-49  | PN1622140265 | 1 | HW300*300*10*15 | 5253.6  | 528.7   | 528.7   | 0 |  |
| 84  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2729 | 4VB-50  | PN1622140266 | 1 | HW300*300*10*15 | 5260.2  | 528.15  | 528.15  | 0 |  |
| 85  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2730 | 4VB-51  | PN1622140267 | 1 | HW300*300*10*15 | 5943    | 596.96  | 596.96  | 0 |  |
| 86  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2731 | 4VB-52  | PN1622140268 | 1 | HW300*300*10*15 | 5400.1  | 546.47  | 546.47  | 0 |  |
| 87  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2732 | 4VB-53  | PN1622140269 | 1 | BH300*360*12*24 | 4546.5  | 962.81  | 962.81  | 0 |  |
| 88  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2733 | 4VB-54  | PN1622140270 | 1 | HW250*250*9*14  | 4965.2  | 399.09  | 399.09  | 0 |  |
| 89  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2734 | 4VB-55  | PN1622140271 | 1 | HW250*250*9*14  | 4623    | 374.32  | 374.32  | 0 |  |
| 90  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2735 | 4VB-56  | PN1622140272 | 1 | HW250*250*9*14  | 5011.1  | 402.41  | 402.41  | 0 |  |
| 91  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2736 | 4VB-57  | PN1622140273 | 1 | BH300*340*10*20 | 6074.2  | 841.13  | 841.13  | 0 |  |
| 92  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2737 | 4VB-58  | PN1622140274 | 1 | BH300*420*12*24 | 6476.8  | 1283.45 | 1283.45 | 0 |  |
| 93  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2738 | 4VB-59  | PN1622140275 | 1 | BH300*340*10*20 | 5407.8  | 756.39  | 756.39  | 0 |  |
| 94  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2739 | 4VB-60  | PN1622140276 | 2 | BH300*340*10*20 | 5573    | 776.44  | 1552.88 | 0 |  |
| 95  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2740 | 4VB-61  | PN1622140277 | 1 | BH300*420*12*24 | 12823.1 | 2382.57 | 2382.57 | 0 |  |
| 96  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2741 | 4VB-62  | PN1622140278 | 1 | HW300*300*10*15 | 5720    | 561.76  | 561.76  | 0 |  |
| 97  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2742 | 4VB-63  | PN1622140279 | 1 | HW250*250*9*14  | 5075.1  | 407.04  | 407.04  | 0 |  |
| 98  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2743 | 4VB-64  | PN1622140280 | 1 | HW300*300*10*15 | 5757.2  | 565.22  | 565.22  | 0 |  |
| 99  | TB2-SDC.VP101-00UHA-A-M1A-DTE-2744 | 4VB-65  | PN1622140281 | 1 | BH300*380*12*20 | 1591.8  | 306.65  | 306.65  | 0 |  |
| 100 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2745 | 4VB-66  | PN1622140282 | 1 | BH300*400*12*24 | 3490    | 986.78  | 986.78  | 0 |  |
| 101 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2746 | 4VB-67  | PN1622140283 | 1 | BH300*380*12*20 | 1591.8  | 306.65  | 306.65  | 0 |  |
| 102 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2747 | 4VB-68  | PN1622140284 | 1 | BH300*360*12*20 | 2124.7  | 364.63  | 364.63  | 0 |  |
| 103 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2748 | 4VB-69  | PN1622140285 | 1 | HW300*300*10*15 | 5757.2  | 565.22  | 565.22  | 0 |  |
| 104 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2749 | 4VB-70  | PN1622140286 | 2 | HW300*300*10*15 | 6320.2  | 626.72  | 1253.43 | 0 |  |
| 105 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2750 | 4VB-71  | PN1622140287 | 2 | HW300*300*10*15 | 5760    | 574.63  | 1149.25 | 0 |  |
| 106 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2751 | 4VB-72  | PN1622140288 | 1 | BH300*440*12*24 | 5292.6  | 1079.41 | 1079.41 | 0 |  |
| 107 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2752 | 4VB-73  | PN1622140289 | 1 | BH300*440*12*24 | 5300.5  | 1080.91 | 1080.91 | 0 |  |
| 108 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2753 | 4VB-74  | PN1622140290 | 1 | BH300*360*10*20 | 5661.8  | 819.14  | 819.14  | 0 |  |
| 109 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2754 | 4VB-75  | PN1622140291 | 1 | BH300*480*14*30 | 4321.7  | 1378.26 | 1378.26 | 0 |  |
| 110 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2755 | 4VB-76  | PN1622140292 | 1 | HW300*300*10*15 | 5020.1  | 496.68  | 496.68  | 0 |  |
| 111 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2756 | 4VB-77  | PN1622140293 | 7 | HW300*300*10*15 | 4513.2  | 553.25  | 3872.77 | 0 |  |
| 112 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2757 | 4VB-78  | PN1622140294 | 2 | BH300*340*10*20 | 6365.1  | 877.17  | 1754.33 | 0 |  |
| 113 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2758 | 4VB-79  | PN1622140295 | 1 | BH300*380*12*20 | 9648.9  | 1462.48 | 1462.48 | 0 |  |
| 114 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2759 | 4VB-80  | PN1622140296 | 1 | BH300*380*12*20 | 9968.9  | 1508.5  | 1508.5  | 0 |  |
| 115 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2760 | 4VB-81  | PN1622140297 | 1 | BH300*440*12*24 | 5326.9  | 1085.91 | 1085.91 | 0 |  |
| 116 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2761 | 4VB-82  | PN1622140298 | 1 | BH300*440*12*24 | 5300.5  | 1080.91 | 1080.91 | 0 |  |
| 117 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2762 | 4VB-83  | PN1622140299 | 1 | BH300*440*12*24 | 4815.8  | 1058.73 | 1058.73 | 0 |  |
| 118 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2763 | 4VB-84  | PN1622140300 | 1 | BH300*340*10*20 | 6074.2  | 841.13  | 841.13  | 0 |  |
| 119 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2764 | 4VB-85  | PN1622140301 | 2 | BH300*340*10*20 | 5040.9  | 685.82  | 1371.63 | 0 |  |
| 120 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2765 | 4VB-86  | PN1622140302 | 1 | BH300*360*12*20 | 1839.8  | 325.45  | 325.45  | 0 |  |
| 121 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2766 | 4VB-87  | PN1622140303 | 1 | BH300*420*12*24 | 6569.8  | 1300.37 | 1300.37 | 0 |  |
| 122 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2767 | 4VB-88  | PN1622140304 | 1 | BH300*360*12*20 | 4320.5  | 825.23  | 825.23  | 0 |  |
| 123 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2768 | 4VB-89  | PN1622140305 | 1 | BH300*400*12*24 | 3700    | 1727.71 | 1727.71 | 0 |  |
| 124 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2769 | 4VB-90  | PN1622140306 | 1 | BH300*360*10*20 | 5671.8  | 820.48  | 820.48  | 0 |  |
| 125 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2770 | 4VB-91  | PN1622140307 | 1 | HW300*300*10*15 | 5020.1  | 496.68  | 496.68  | 0 |  |
| 126 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2771 | 4VB-92  | PN1622140308 | 1 | HW300*300*10*15 | 5933.8  | 596.09  | 596.09  | 0 |  |
| 127 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2772 | 4VB-93  | PN1622140309 | 1 | BH300*400*14*30 | 3700    | 2172.35 | 2172.35 | 0 |  |
| 128 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2773 | 4VB-94  | PN1622140310 | 1 | BH300*360*12*24 | 4546.5  | 962.57  | 962.57  | 0 |  |
| 129 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2774 | 4VB-95  | PN1622140311 | 1 | BH300*400*12*24 | 11710.1 | 2126.63 | 2126.63 | 0 |  |
| 130 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2775 | 4VB-96  | PN1622140312 | 2 | BH300*360*10*20 | 6121.4  | 913.27  | 1826.54 | 0 |  |
| 131 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2776 | 4VB-97  | PN1622140313 | 1 | HW300*300*10*15 | 4719.7  | 468.74  | 468.74  | 0 |  |
| 132 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2777 | 4VB-98  | PN1622140314 | 1 | HW300*300*10*15 | 4739.7  | 470.6   | 470.6   | 0 |  |
| 133 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2778 | 4VB-99  | PN1622140315 | 1 | HW300*300*10*15 | 6003.8  | 602.6   | 602.6   | 0 |  |
| 134 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2779 | 4VB-100 | PN1622140316 | 1 | BH300*360*12*24 | 1943.5  | 368.64  | 368.64  | 0 |  |
| 135 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2780 | 4VB-101 | PN1622140317 | 1 | BH300*380*12*20 | 3843.6  | 824.71  | 824.71  | 0 |  |
|     | TB2-SDC.VP101-00UHA-A-M1A-DTE-2781 | 4VB-102 | PN1622140318 | 1 | BH300*380*12*20 | 1531.8  | 298.02  | 298.02  | 0 |  |



|     |                                    |         |              |   |                 |        |         |         |   |  |
|-----|------------------------------------|---------|--------------|---|-----------------|--------|---------|---------|---|--|
| 137 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2782 | 4VB-103 | PN1622140319 | 1 | BH300*500*14*30 | 3877.6 | 1089.28 | 1089.28 | 0 |  |
| 138 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2783 | 4VB-104 | PN1622140320 | 1 | BH300*500*14*30 | 3856.6 | 1158.31 | 1158.31 | 0 |  |
| 139 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2784 | 4VB-105 | PN1622140321 | 1 | BH300*480*14*30 | 3055   | 929.01  | 929.01  | 0 |  |
| 140 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2785 | 4VB-106 | PN1622140322 | 1 | BH300*400*12*24 | 3987.3 | 757.58  | 757.58  | 0 |  |
| 141 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2786 | 4VB-107 | PN1622140323 | 1 | BH300*400*12*24 | 3700   | 1759    | 1759    | 0 |  |
| 142 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2787 | 4VB-108 | PN1622140324 | 1 | HW300*300*10*15 | 5628   | 554.01  | 554.01  | 0 |  |
| 143 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2788 | 4VB-109 | PN1622140325 | 1 | HW300*300*10*15 | 5516.1 | 543.61  | 543.61  | 0 |  |
| 144 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2789 | 4VB-110 | PN1622140326 | 2 | BH300*340*10*20 | 5151.8 | 699.92  | 1399.83 | 0 |  |
| 145 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2790 | 4VB-111 | PN1622140327 | 2 | BH300*340*10*20 | 5181.8 | 703.73  | 1407.46 | 0 |  |
| 146 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2791 | 4VB-112 | PN1622140328 | 1 | BH300*340*10*20 | 5375.8 | 729.17  | 729.17  | 0 |  |
| 147 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2792 | 4VB-113 | PN1622140329 | 1 | BH300*340*10*20 | 5390.8 | 731.83  | 731.83  | 0 |  |
| 148 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2793 | 4VB-114 | PN1622140330 | 1 | HW300*300*10*15 | 5230.1 | 516.21  | 516.21  | 0 |  |
| 149 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2794 | 4VB-115 | PN1622140331 | 2 | HW100*100*6*8   | 3522   | 89.31   | 178.62  | 0 |  |
| 150 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2795 | 4VB-116 | PN1622140332 | 1 | BH300*340*10*20 | 5350.7 | 748.3   | 748.3   | 0 |  |
| 151 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2796 | 4VB-117 | PN1622140333 | 1 | BH300*360*10*20 | 5661.8 | 819.14  | 819.14  | 0 |  |
| 152 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2797 | 4VB-118 | PN1622140334 | 2 | BH300*340*10*20 | 5070.9 | 689.63  | 1379.26 | 0 |  |
| 153 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2798 | 4VB-119 | PN1622140335 | 1 | BH300*420*12*24 | 4974.9 | 1010.1  | 1010.1  | 0 |  |
| 154 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2799 | 4VB-120 | PN1622140336 | 1 | BH300*420*12*24 | 6569.8 | 1300.37 | 1300.37 | 0 |  |
| 155 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2800 | 4VB-121 | PN1622140337 | 1 | BH300*420*12*24 | 6476.8 | 1283.45 | 1283.45 | 0 |  |
| 156 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2801 | 4VB-122 | PN1622140338 | 1 | BH300*360*12*20 | 4920.1 | 769     | 769     | 0 |  |
| 157 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2802 | 4VB-123 | PN1622140339 | 1 | HW300*300*10*15 | 5943   | 596.96  | 596.96  | 0 |  |
| 158 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2803 | 4VB-124 | PN1622140340 | 1 | HW300*300*10*15 | 5400.1 | 546.47  | 546.47  | 0 |  |
| 159 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2804 | 4VB-125 | PN1622140341 | 1 | BH300*360*12*20 | 4945.1 | 772.44  | 772.44  | 0 |  |
| 160 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2805 | 4VB-126 | PN1622140342 | 1 | BH300*340*10*20 | 6075.2 | 842.42  | 842.42  | 0 |  |
| 161 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2806 | 4VB-127 | PN1622140343 | 1 | HW300*300*10*15 | 5253.6 | 527.54  | 527.54  | 0 |  |
| 162 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2807 | 4VB-128 | PN1622140344 | 1 | HW300*300*10*15 | 5933.8 | 596.09  | 596.09  | 0 |  |
| 163 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2808 | 4VB-129 | PN1622140345 | 1 | HW300*300*10*15 | 6003.8 | 602.6   | 602.6   | 0 |  |
| 164 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2809 | 4VB-130 | PN1622140346 | 1 | BH300*480*14*30 | 4321.7 | 1378.26 | 1378.26 | 0 |  |
| 165 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2810 | 4VB-131 | PN1622140347 | 1 | HW300*300*10*15 | 5230.1 | 516.21  | 516.21  | 0 |  |
| 166 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2811 | 4VB-132 | PN1622140348 | 1 | BH300*400*14*30 | 3700   | 2172.01 | 2172.01 | 0 |  |
| 167 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2812 | 4VB-133 | PN1622140349 | 1 | BH300*360*12*24 | 1962.5 | 371.66  | 371.66  | 0 |  |
| 168 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2813 | 4VB-134 | PN1622140350 | 1 | BH300*460*14*30 | 2046.6 | 571.84  | 571.84  | 0 |  |
| 169 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2814 | 4VB-135 | PN1622140351 | 1 | BH300*460*14*30 | 4452.5 | 1402.69 | 1402.69 | 0 |  |
| 170 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2815 | 4VB-136 | PN1622140352 | 1 | BH300*500*14*30 | 2903.9 | 834.3   | 834.3   | 0 |  |
| 171 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2816 | 4VB-137 | PN1622140353 | 1 | BH300*360*12*20 | 2124.7 | 364.63  | 364.63  | 0 |  |
| 172 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2817 | 4VB-138 | PN1622140354 | 4 | BH300*460*12*24 | 2078.1 | 512.92  | 2051.66 | 0 |  |
| 173 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2818 | 4VB-139 | PN1622140355 | 4 | BH300*460*12*24 | 4513.2 | 1205.89 | 4823.55 | 0 |  |
| 174 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2819 | 4VB-140 | PN1622140356 | 1 | HW250*250*9*14  | 4330.2 | 350.72  | 350.72  | 0 |  |
| 175 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2820 | 4VB-141 | PN1622140357 | 1 | HW250*250*9*14  | 4189.9 | 340.57  | 340.57  | 0 |  |
| 176 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2821 | 4VB-142 | PN1622140358 | 1 | HW250*250*9*14  | 4736.7 | 382.55  | 382.55  | 0 |  |
| 177 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2822 | 4VB-143 | PN1622140359 | 1 | HW250*250*9*14  | 4699.8 | 379.88  | 379.88  | 0 |  |
| 178 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2823 | 4VB-144 | PN1622140360 | 1 | BH300*360*12*20 | 1839.8 | 325.45  | 325.45  | 0 |  |
| 179 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2824 | 4VB-145 | PN1622140361 | 1 | BH300*400*12*24 | 3700   | 1727.71 | 1727.71 | 0 |  |
| 180 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2825 | 4VB-146 | PN1622140362 | 2 | BH300*480*14*30 | 1925.9 | 555.26  | 1110.52 | 0 |  |
| 181 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2826 | 4VB-147 | PN1622140363 | 1 | BH300*480*14*30 | 2180.1 | 591.14  | 591.14  | 0 |  |
| 182 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2827 | 4VB-148 | PN1622140364 | 8 | HW300*300*10*15 | 1935.1 | 227.29  | 1818.32 | 0 |  |
| 183 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2828 | 4VB-149 | PN1622140365 | 2 | HW300*300*10*15 | 2895.2 | 321.18  | 642.36  | 0 |  |
| 184 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2829 | 4VB-150 | PN1622140366 | 5 | HW300*300*10*15 | 2888.4 | 320.56  | 1602.78 | 0 |  |
| 185 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2830 | 4VB-151 | PN1622140367 | 2 | HW300*300*10*15 | 2994.7 | 330.44  | 660.87  | 0 |  |
| 186 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2831 | 4VB-152 | PN1622140368 | 1 | BH300*460*14*30 | 1905.9 | 537.7   | 537.7   | 0 |  |
| 187 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2832 | 4VB-153 | PN1622140369 | 2 | BH300*400*12*20 | 4566   | 909.86  | 1819.72 | 0 |  |
| 188 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2833 | 4VB-154 | PN1622140370 | 1 | BH300*400*12*20 | 1775.1 | 356.29  | 356.29  | 0 |  |
| 189 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2834 | 4VB-155 | PN1622140371 | 4 | BH300*400*12*20 | 4452.5 | 909.11  | 3636.44 | 0 |  |
| 190 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2835 | 4VB-156 | PN1622140372 | 4 | BH300*400*12*20 | 1905.9 | 392.22  | 1568.87 | 0 |  |
| 191 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2836 | 4VB-157 | PN1622140373 | 4 | BH300*460*12*24 | 1935.1 | 484.74  | 1938.96 | 0 |  |
| 192 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2837 | 4VB-158 | PN1622140374 | 1 | HW300*300*10*15 | 4719.7 | 468.74  | 468.74  | 0 |  |
| 193 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2838 | 4VB-159 | PN1622140375 | 1 | HW300*300*10*15 | 4739.7 | 470.6   | 470.6   | 0 |  |
| 194 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2839 | 4VB-160 | PN1622140376 | 1 | BH300*380*12*20 | 3843.6 | 824.71  | 824.71  | 0 |  |
| 195 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2840 | 4VB-161 | PN1622140377 | 1 | BH300*360*12*24 | 1928.7 | 366.28  | 366.28  | 0 |  |
| 196 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2841 | 4VB-162 | PN1622140378 | 1 | BH300*380*12*20 | 1531.8 | 298.02  | 298.02  | 0 |  |
| 197 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2842 | 4VB-163 | PN1622140379 | 1 | BH300*500*14*30 | 3877.6 | 1089.28 | 1089.28 | 0 |  |
| 198 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2843 | 4VB-164 | PN1622140380 | 1 | BH300*400*12*24 | 3700   | 1759    | 1759    | 0 |  |
| 199 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2844 | 4VB-165 | PN1622140381 | 2 | BH300*400*12*20 | 4566   | 909.86  | 1819.73 | 0 |  |
| 200 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2845 | 4VB-166 | PN1622140382 | 1 | BH300*360*10*20 | 5671.8 | 820.48  | 820.48  | 0 |  |
| 201 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2846 | 4VB-167 | PN1622140383 | 2 | HW300*300*10*15 | 2992.1 | 330.19  | 660.39  | 0 |  |
| 202 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2847 | 4VB-168 | PN1622140384 | 8 | HW300*300*10*15 | 2078.1 | 240.58  | 1924.66 | 0 |  |
| 203 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2848 | 4VB-169 | PN1622140385 | 8 | BH300*400*12*20 | 2046.6 | 413.33  | 3306.64 | 0 |  |
| 204 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2849 | 4VB-170 | PN1622140386 | 2 | BH300*400*12*20 | 1775.1 | 356.3   | 712.59  | 0 |  |
|     | TB2-SDC.VP101-00UHA-A-M1A-DTE-2850 | 4VB-171 | PN1622140387 | 1 | BH300*400*12*20 | 1775.1 | 356.29  | 356.29  | 0 |  |



|     |                                    |         |              |   |                 |         |         |         |   |  |
|-----|------------------------------------|---------|--------------|---|-----------------|---------|---------|---------|---|--|
| 206 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2851 | 4VB-172 | PN1622140388 | 1 | BH300*460*14*30 | 4452.5  | 1402.24 | 1402.24 | 0 |  |
| 207 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2852 | 4VB-173 | PN1622140389 | 1 | BH300*460*14*30 | 1905.9  | 537.7   | 537.7   | 0 |  |
| 208 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2853 | 4VB-174 | PN1622140390 | 1 | BH300*460*14*30 | 2046.6  | 571.84  | 571.84  | 0 |  |
| 209 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2854 | 37G-1   | PN1622240010 | 1 | HM582*300*12*17 | 9488    | 1380.64 | 1380.64 | 0 |  |
| 210 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2855 | 37G-2   | PN1622240011 | 1 | HM582*300*12*17 | 9489    | 1323.86 | 1323.86 | 0 |  |
| 211 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2856 | 37G-3   | PN1622240012 | 1 | BH700*250*12*16 | 8773    | 1138.5  | 1138.5  | 0 |  |
| 212 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2857 | 37G-4   | PN1622240013 | 1 | BH700*250*12*16 | 11983   | 1542.69 | 1542.69 | 0 |  |
| 213 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2858 | 37G-5   | PN1622240014 | 1 | HN596*199*10*15 | 2760    | 299.34  | 299.34  | 0 |  |
| 214 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2859 | 37G-6   | PN1622240015 | 1 | HN596*199*10*15 | 8488    | 840.82  | 840.82  | 0 |  |
| 215 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2860 | 37G-7   | PN1622240016 | 1 | BH500*300*10*14 | 10975   | 1496.87 | 1496.87 | 0 |  |
| 216 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2861 | 37G-8   | PN1622240017 | 2 | BH500*300*10*20 | 13260   | 1821.24 | 3642.48 | 0 |  |
| 217 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2862 | 37G-9   | PN1622240018 | 1 | BH600*250*10*14 | 11450   | 1768.48 | 1768.48 | 0 |  |
| 218 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2863 | 37G-10  | PN1622240019 | 1 | BH500*250*10*14 | 9980    | 1531.65 | 1531.65 | 0 |  |
| 219 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2864 | 37G-11  | PN1622240020 | 1 | HN496*199*9*14  | 1480.1  | 139.33  | 139.33  | 0 |  |
| 220 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2865 | 37G-12  | PN1622240021 | 1 | HN496*199*9*14  | 9486    | 779.48  | 779.48  | 0 |  |
| 221 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2866 | 37G-13  | PN1622240022 | 1 | HN446*199*8*12  | 8486    | 1046.63 | 1046.63 | 0 |  |
| 222 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2867 | 37G-14  | PN1622240023 | 1 | HN596*199*10*15 | 9083    | 1592.9  | 1592.9  | 0 |  |
| 223 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2868 | 37G-15  | PN1622240024 | 1 | BH800*300*12*20 | 11450   | 1967.69 | 1967.69 | 0 |  |
| 224 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2869 | 37G-16  | PN1622240025 | 1 | HN596*199*10*15 | 9488    | 971.05  | 971.05  | 0 |  |
| 225 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2870 | 37G-17  | PN1622240026 | 1 | BH500*300*10*14 | 11530   | 1669.28 | 1669.28 | 0 |  |
| 226 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2871 | 37G-18  | PN1622240027 | 1 | BH800*250*12*20 | 11450   | 1768.91 | 1768.91 | 0 |  |
| 227 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2872 | 37G-19  | PN1622240028 | 1 | BH600*250*10*14 | 9386    | 961.65  | 961.65  | 0 |  |
| 228 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2873 | 37G-20  | PN1622240029 | 1 | BH600*250*10*14 | 8470    | 1160.68 | 1160.68 | 0 |  |
| 229 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2874 | 37G-21  | PN1622240030 | 1 | BH800*300*12*20 | 9386    | 1599.92 | 1599.92 | 0 |  |
| 230 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2875 | 37G-22  | PN1622240031 | 1 | HN496*199*9*14  | 1540.9  | 142.28  | 142.28  | 0 |  |
| 231 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2876 | 37G-23  | PN1622240032 | 1 | BH600*350*12*20 | 4583    | 1040.98 | 1040.98 | 0 |  |
| 232 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2877 | 37G-24  | PN1622240033 | 1 | BH600*250*10*14 | 11450   | 1768.45 | 1768.45 | 0 |  |
| 233 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2878 | 37G-25  | PN1622240034 | 1 | BH900*400*20*30 | 9245    | 3991.72 | 3991.72 | 0 |  |
| 234 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2879 | 37G-26  | PN1622240035 | 1 | BH700*250*12*16 | 8773    | 1138.5  | 1138.5  | 0 |  |
| 235 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2880 | 37G-27  | PN1622240036 | 1 | HN596*199*10*15 | 2776    | 276.41  | 276.41  | 0 |  |
| 236 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2881 | 37G-28  | PN1622240037 | 2 | HM582*300*12*17 | 4577    | 704.04  | 1408.08 | 0 |  |
| 237 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2882 | 37G-29  | PN1622240038 | 1 | HN300*150*6.5*9 | 1383    | 63.25   | 63.25   | 0 |  |
| 238 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2883 | 37G-30  | PN1622240039 | 1 | HN596*199*10*15 | 3460    | 381.76  | 381.76  | 0 |  |
| 239 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2884 | 37G-31  | PN1622240040 | 1 | HN446*199*8*12  | 8486    | 1048.88 | 1048.88 | 0 |  |
| 240 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2885 | 37G-32  | PN1622240041 | 4 | HM582*300*12*17 | 9650    | 1446.68 | 5786.71 | 0 |  |
| 241 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2886 | 37G-33  | PN1622240042 | 2 | HN596*199*10*15 | 3180    | 353.28  | 706.56  | 0 |  |
| 242 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2887 | 37G-34  | PN1622240043 | 1 | BH800*300*12*20 | 11450   | 1971.22 | 1971.22 | 0 |  |
| 243 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2888 | 37G-35  | PN1622240044 | 1 | BH600*400*10*20 | 12347.7 | 2078.28 | 2078.28 | 0 |  |
| 244 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2889 | 37G-36  | PN1622240045 | 1 | HN596*199*10*15 | 8488    | 840.82  | 840.82  | 0 |  |
| 245 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2890 | 37G-37  | PN1622240046 | 1 | HN596*199*10*15 | 9083    | 1576.94 | 1576.94 | 0 |  |
| 246 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2891 | 37G-38  | PN1622240047 | 1 | HN446*199*8*12  | 9269    | 643.32  | 643.32  | 0 |  |
| 247 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2892 | 37G-39  | PN1622240048 | 1 | BH800*300*12*20 | 9386    | 1599.92 | 1599.92 | 0 |  |
| 248 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2893 | 37G-40  | PN1622240049 | 1 | BH800*300*12*20 | 11983   | 2030.48 | 2030.48 | 0 |  |
| 249 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2894 | 37G-41  | PN1622240050 | 1 | HN446*199*8*12  | 9269    | 643.32  | 643.32  | 0 |  |
| 250 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2895 | 37G-43  | PN1622240051 | 1 | HN596*199*10*15 | 9489    | 933.66  | 933.66  | 0 |  |
| 251 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2896 | 37G-45  | PN1622240052 | 1 | BH600*250*10*14 | 8470    | 1160.68 | 1160.68 | 0 |  |
| 252 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2897 | 37G-46  | PN1622240053 | 1 | HN496*199*9*14  | 9486    | 779.48  | 779.48  | 0 |  |
| 253 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2898 | 37G-47  | PN1622240054 | 1 | HN496*199*9*14  | 1540.9  | 142.28  | 142.28  | 0 |  |
| 254 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2899 | 37G-48  | PN1622240055 | 1 | HN496*199*9*14  | 1480.1  | 141.13  | 141.13  | 0 |  |
| 255 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2900 | 37G-49  | PN1622240056 | 1 | HN596*199*10*15 | 3180    | 342.38  | 342.38  | 0 |  |
| 256 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2901 | 37G-50  | PN1622240057 | 1 | BH600*250*10*14 | 9386    | 961.65  | 961.65  | 0 |  |
| 257 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2902 | 37G-51  | PN1622240058 | 1 | BH500*300*10*14 | 8491    | 929.34  | 929.34  | 0 |  |
| 258 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2903 | 37G-53  | PN1622240059 | 1 | BH500*300*10*14 | 11530   | 1669.28 | 1669.28 | 0 |  |
| 259 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2904 | 37G-54  | PN1622240060 | 1 | HN600*200*11*17 | 3466    | 647.28  | 647.28  | 0 |  |
| 260 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2905 | 37G-55  | PN1622240061 | 1 | BH800*250*12*20 | 11450   | 1769.54 | 1769.54 | 0 |  |
| 261 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2906 | 37G-56  | PN1622240062 | 1 | BH900*400*20*30 | 9245    | 3991.72 | 3991.72 | 0 |  |
| 262 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2907 | 37G-57  | PN1622240063 | 1 | BH900*350*20*30 | 9470    | 3243.14 | 3243.14 | 0 |  |
| 263 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2908 | 37G-58  | PN1622240064 | 1 | BH500*300*10*14 | 10975   | 1496.87 | 1496.87 | 0 |  |
| 264 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2909 | 37G-59  | PN1622240065 | 1 | BH500*250*10*14 | 9980    | 1531.65 | 1531.65 | 0 |  |
| 265 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2910 | 37G-60  | PN1622240066 | 1 | HN300*150*6.5*9 | 1385    | 63.46   | 63.46   | 0 |  |
| 266 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2911 | 37G-61  | PN1622240067 | 1 | BH500*300*10*14 | 8491    | 929.34  | 929.34  | 0 |  |
| 267 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2912 | 37G-62  | PN1622240068 | 1 | BH900*350*20*30 | 9470    | 3243.14 | 3243.14 | 0 |  |
| 268 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2913 | 41G-1   | PN1622240069 | 1 | HN496*199*9*14  | 10986   | 1402.09 | 1402.09 | 0 |  |
| 269 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2914 | 41G-2   | PN1622240070 | 1 | BH500*300*10*14 | 8470    | 1576.57 | 1576.57 | 0 |  |
| 270 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2915 | 41G-3   | PN1622240071 | 1 | HN396*199*7*11  | 9486    | 562.71  | 562.71  | 0 |  |
| 271 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2916 | 41G-4   | PN1622240072 | 1 | HN596*199*10*15 | 9980    | 1600.67 | 1600.67 | 0 |  |
| 272 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2918 | 41G-6   | PN1622240074 | 1 | BH450*150*8*8   | 3988    | 201.25  | 201.25  | 0 |  |
| 273 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2919 | 41G-7   | PN1622240075 | 1 | BH700*250*12*20 | 11450   | 1663.52 | 1663.52 | 0 |  |
|     | TB2-SDC.VP101-00UHA-A-M1A-DTE-2920 | 41G-8   | PN1622240076 | 1 | BH600*200*8*10  | 3185    | 232.83  | 232.83  | 0 |  |



|     |                                    |        |              |   |                  |        |         |         |   |  |
|-----|------------------------------------|--------|--------------|---|------------------|--------|---------|---------|---|--|
| 275 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2921 | 41G-9  | PN1622240077 | 1 | BH700*250*12*20  | 11450  | 1663.52 | 1663.52 | 0 |  |
| 276 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2922 | 41G-10 | PN1622240078 | 1 | HM582*300*12*17  | 18483  | 3531.14 | 3531.14 | 0 |  |
| 277 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2923 | 41G-11 | PN1622240079 | 1 | BH500*300*10*14  | 11773  | 1793.11 | 1793.11 | 0 |  |
| 278 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2924 | 41G-12 | PN1622240080 | 1 | HM582*300*12*17  | 9386   | 1602.39 | 1602.39 | 0 |  |
| 279 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2925 | 41G-13 | PN1622240081 | 1 | HM582*300*12*17  | 9083   | 1877.71 | 1877.71 | 0 |  |
| 280 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2926 | 41G-14 | PN1622240082 | 1 | BH700*250*12*16  | 11983  | 1571.77 | 1571.77 | 0 |  |
| 281 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2927 | 41G-15 | PN1622240083 | 1 | BH1400*350*16*30 | 18245  | 6223.47 | 6223.47 | 0 |  |
| 282 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2928 | 41G-16 | PN1622240084 | 1 | BH600*350*12*20  | 9083   | 2112.8  | 2112.8  | 0 |  |
| 283 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2929 | 41G-17 | PN1622240085 | 1 | HN596*199*10*15  | 9269   | 912.36  | 912.36  | 0 |  |
| 284 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2930 | 41G-18 | PN1622240086 | 1 | HN396*199*7*11   | 1192.1 | 81.35   | 81.35   | 0 |  |
| 285 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2931 | 41G-19 | PN1622240087 | 1 | HN596*199*10*15  | 10975  | 1435.3  | 1435.3  | 0 |  |
| 286 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2932 | 41G-20 | PN1622240088 | 1 | BH700*250*12*20  | 11450  | 1659.9  | 1659.9  | 0 |  |
| 287 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2933 | 41G-21 | PN1622240089 | 1 | HM582*300*12*17  | 13260  | 1886.69 | 1886.69 | 0 |  |
| 288 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2934 | 41G-22 | PN1622240090 | 1 | BH500*400*10*20  | 9390.5 | 1531.84 | 1531.84 | 0 |  |
| 289 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2935 | 41G-23 | PN1622240091 | 1 | BH500*250*10*14  | 9986   | 955.27  | 955.27  | 0 |  |
| 290 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2936 | 41G-24 | PN1622240092 | 1 | BH700*250*12*20  | 11988  | 1715.65 | 1715.65 | 0 |  |
| 291 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2937 | 41G-25 | PN1622240093 | 1 | BH600*200*8*10   | 8486   | 1017.56 | 1017.56 | 0 |  |
| 292 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2938 | 41G-26 | PN1622240094 | 1 | BH800*300*12*20  | 11983  | 2067.94 | 2067.94 | 0 |  |
| 293 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2939 | 41G-27 | PN1622240095 | 1 | HN496*199*9*14   | 3964   | 479.4   | 479.4   | 0 |  |
| 294 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2940 | 41G-28 | PN1622240096 | 1 | BH500*300*10*14  | 9089.5 | 951.5   | 951.5   | 0 |  |
| 295 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2941 | 41G-29 | PN1622240097 | 1 | BH500*300*10*14  | 8470   | 1576.56 | 1576.56 | 0 |  |
| 296 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2942 | 41G-30 | PN1622240098 | 1 | BH700*300*12*20  | 13010  | 2068.21 | 2068.21 | 0 |  |
| 297 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2943 | 41G-31 | PN1622240099 | 1 | BH900*350*20*30  | 9470   | 3851.45 | 3851.45 | 0 |  |
| 298 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2944 | 41G-32 | PN1622240100 | 1 | BH900*400*20*30  | 9245   | 4036.41 | 4036.41 | 0 |  |
| 299 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2945 | 41G-33 | PN1622240101 | 1 | HM440*300*11*18  | 13486  | 1643.25 | 1643.25 | 0 |  |
| 300 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2946 | 41G-34 | PN1622240102 | 1 | BH1400*300*16*24 | 18250  | 5313.45 | 5313.45 | 0 |  |
| 301 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2947 | 41G-35 | PN1622240103 | 1 | BH700*200*12*14  | 3951   | 552.78  | 552.78  | 0 |  |
| 302 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2948 | 41G-36 | PN1622240104 | 1 | BH450*150*8*8    | 3486   |         |         | 0 |  |
| 303 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2949 | 41G-37 | PN1622240105 | 1 | BH500*300*10*14  | 11536  | 1566.81 | 1566.81 | 0 |  |
| 304 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2950 | 41G-38 | PN1622240106 | 1 | HN596*199*10*15  | 3970   | 575.58  | 575.58  | 0 |  |
| 305 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2951 | 41G-39 | PN1622240107 | 1 | BH600*200*8*10   | 4583   | 331.43  | 331.43  | 0 |  |
| 306 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2952 | 41G-40 | PN1622240108 | 1 | BH600*200*8*10   | 3190   | 421.15  | 421.15  | 0 |  |
| 307 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2953 | 41G-41 | PN1622240109 | 1 | BH600*200*8*10   | 8486   | 1017.56 | 1017.56 | 0 |  |
| 308 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2954 | 41G-42 | PN1622240110 | 1 | HM582*300*12*17  | 9386   | 1630.08 | 1630.08 | 0 |  |
| 309 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2955 | 41G-43 | PN1622240111 | 1 | HM582*300*12*17  | 13260  | 1887.24 | 1887.24 | 0 |  |
| 310 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2956 | 41G-44 | PN1622240112 | 1 | BH600*200*8*10   | 3185   | 232.83  | 232.83  | 0 |  |
| 311 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2957 | 41G-45 | PN1622240113 | 1 | BH1400*350*16*30 | 18245  | 6223.47 | 6223.47 | 0 |  |
| 312 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2958 | 41G-47 | PN1622240114 | 1 | HN396*199*7*11   | 9486   | 562.71  | 562.71  | 0 |  |
| 313 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2959 | 41G-48 | PN1622240115 | 1 | HN596*199*10*15  | 9269   | 912.36  | 912.36  | 0 |  |
| 314 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2960 | 41G-49 | PN1622240116 | 1 | BH600*250*10*14  | 11450  | 1799.59 | 1799.59 | 0 |  |
| 315 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2961 | 41G-50 | PN1622240117 | 2 | BH600*200*8*10   | 4577   | 331.03  | 662.05  | 0 |  |
| 316 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2962 | 41G-51 | PN1622240118 | 1 | BH600*250*10*14  | 11450  | 1791.87 | 1791.87 | 0 |  |
| 317 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2963 | 41G-52 | PN1622240119 | 1 | BH600*250*10*14  | 11530  | 1847.81 | 1847.81 | 0 |  |
| 318 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2964 | 41G-53 | PN1622240120 | 1 | HN396*199*7*11   | 1192.1 | 81.35   | 81.35   | 0 |  |
| 319 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2965 | 41G-54 | PN1622240121 | 1 | HN396*199*7*11   | 1122.9 | 78.03   | 78.03   | 0 |  |
| 320 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2966 | 41G-55 | PN1622240122 | 1 | BH600*250*10*14  | 11530  | 1839.82 | 1839.82 | 0 |  |
| 321 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2967 | 41G-56 | PN1622240123 | 2 | HN396*199*7*11   | 1079.5 | 72.52   | 145.04  | 0 |  |
| 322 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2968 | 41G-57 | PN1622240124 | 1 | HN496*199*9*14   | 10986  | 1402.09 | 1402.09 | 0 |  |
| 323 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2969 | 41G-58 | PN1622240125 | 1 | BH500*250*10*14  | 9986   | 955.27  | 955.27  | 0 |  |
| 324 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2970 | 41G-59 | PN1622240126 | 1 | BH450*150*8*8    | 3486   |         |         | 0 |  |
| 325 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2971 | 41G-60 | PN1622240127 | 1 | BH500*300*10*14  | 11536  | 1566.81 | 1566.81 | 0 |  |
| 326 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2972 | 41G-61 | PN1622240128 | 1 | BH500*300*10*14  | 11773  | 1763.36 | 1763.36 | 0 |  |
| 327 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2973 | 41G-62 | PN1622240129 | 1 | HM582*300*12*17  | 18483  | 3509.63 | 3509.63 | 0 |  |
| 328 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2974 | 41G-63 | PN1622240130 | 1 | HN596*199*10*15  | 9440   | 923.36  | 923.36  | 0 |  |
| 329 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2975 | 41G-64 | PN1622240131 | 1 | HM440*300*11*18  | 13486  | 1643.25 | 1643.25 | 0 |  |
| 330 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2976 | 41G-65 | PN1622240132 | 1 | BH700*250*12*20  | 11450  | 1659.9  | 1659.9  | 0 |  |
| 331 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2977 | 41G-66 | PN1622240133 | 1 | BH1400*300*16*24 | 18250  | 5313.45 | 5313.45 | 0 |  |
| 332 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2978 | 41G-67 | PN1622240134 | 1 | HN596*199*10*15  | 10975  | 1430.25 | 1430.25 | 0 |  |
| 333 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2979 | 41G-68 | PN1622240135 | 1 | BH900*400*20*30  | 9245   | 4020.86 | 4020.86 | 0 |  |
| 334 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2980 | 41G-69 | PN1622240136 | 1 | BH700*200*12*14  | 3935   | 585.12  | 585.12  | 0 |  |
| 335 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2981 | 41G-70 | PN1622240137 | 1 | HN396*199*7*11   | 1122.9 | 78.03   | 78.03   | 0 |  |
| 336 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2982 | 41G-71 | PN1622240138 | 1 | BH900*350*20*30  | 9470   | 3901.66 | 3901.66 | 0 |  |
| 337 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2983 | 41G-72 | PN1622240139 | 1 | HN596*199*10*15  | 9980   | 1600.67 | 1600.67 | 0 |  |
| 338 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2984 | 44G-1  | PN1622240140 | 1 | BH400*300*10*14  | 3284.5 | 323.34  | 323.34  | 0 |  |
| 339 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2985 | 44G-2  | PN1622240141 | 1 | HN300*150*6.5*9  | 1685   | 76.46   | 76.46   | 0 |  |
| 340 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2986 | 44G-3  | PN1622240142 | 1 | HN396*199*7*11   | 1400   | 97.58   | 97.58   | 0 |  |
| 341 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2987 | 44G-4  | PN1622240143 | 1 | HN396*199*7*11   | 1500   | 102.63  | 102.63  | 0 |  |
| 342 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2988 | 44G-5  | PN1622240144 | 1 | HN396*199*7*11   | 1500   | 102.63  | 102.63  | 0 |  |
|     | TB2-SDC.VP101-00UHA-A-M1A-DTE-2989 | 44G-6  | PN1622240145 | 1 | HN396*199*7*11   | 1400   | 97.58   | 97.58   | 0 |  |



|     |                                    |        |              |   |                  |        |          |          |   |  |
|-----|------------------------------------|--------|--------------|---|------------------|--------|----------|----------|---|--|
| 344 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2990 | 44G-7  | PN1622240146 | 1 | HN396*199*7*11   | 1099   | 62.25    | 62.25    | 0 |  |
| 345 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2991 | 44G-8  | PN1622240147 | 1 | HN300*150*6.5*9  | 1685   | 76.46    | 76.46    | 0 |  |
| 346 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2992 | 44G-9  | PN1622240148 | 1 | BH400*300*10*14  | 5994.5 | 594.31   | 594.31   | 0 |  |
| 347 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2993 | 44G-10 | PN1622240149 | 2 | HN396*199*7*11   | 1099   | 62.25    | 124.51   | 0 |  |
| 348 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2994 | 44G-11 | PN1622240150 | 1 | BH400*300*10*14  | 5989   | 598.2    | 598.2    | 0 |  |
| 349 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2995 | 44G-12 | PN1622240151 | 1 | BH400*300*10*14  | 3284.5 | 323.34   | 323.34   | 0 |  |
| 350 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2996 | 44G-13 | PN1622240152 | 1 | BH400*300*10*14  | 5988.5 | 598.15   | 598.15   | 0 |  |
| 351 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2997 | 46G-1  | PN1622240153 | 1 | BH600*200*8*10   | 8486   | 1035.87  | 1035.87  | 0 |  |
| 352 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2998 | 46G-2  | PN1622240154 | 1 | BH600*300*12*20  | 5395   | 971.19   | 971.19   | 0 |  |
| 353 | TB2-SDC.VP101-00UHA-A-M1A-DTE-2999 | 46G-3  | PN1622240155 | 1 | BH500*250*10*14  | 5999   | 595.64   | 595.64   | 0 |  |
| 354 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3000 | 46G-4  | PN1622240156 | 1 | HN496*199*9*14   | 9486   | 779.48   | 779.48   | 0 |  |
| 355 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3001 | 46G-5  | PN1622240157 | 1 | BH500*250*10*14  | 10975  | 1367.73  | 1367.73  | 0 |  |
| 356 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3002 | 46G-6  | PN1622240158 | 1 | BH900*350*14*30  | 11450  | 2999.39  | 2999.39  | 0 |  |
| 357 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3003 | 46G-7  | PN1622240159 | 1 | HN496*199*9*14   | 1640   | 149.66   | 149.66   | 0 |  |
| 358 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3004 | 46G-8  | PN1622240160 | 1 | BH900*350*14*24  | 11450  | 2638.28  | 2638.28  | 0 |  |
| 359 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3005 | 46G-9  | PN1622240161 | 1 | BH600*250*10*14  | 11450  | 1805.37  | 1805.37  | 0 |  |
| 360 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3006 | 46G-10 | PN1622240162 | 1 | HN496*199*9*14   | 9486   | 779.48   | 779.48   | 0 |  |
| 361 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3007 | 46G-11 | PN1622240163 | 1 | HM582*300*12*17  | 13010  | 1804.01  | 1804.01  | 0 |  |
| 362 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3008 | 46G-12 | PN1622240164 | 1 | HN496*199*9*14   | 3939   | 327.9    | 327.9    | 0 |  |
| 363 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3009 | 46G-13 | PN1622240165 | 1 | BH1900*450*20*36 | 18250  | 10077.18 | 10077.18 | 0 |  |
| 364 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3010 | 46G-14 | PN1622240166 | 1 | HN496*199*9*14   | 10986  | 1357.79  | 1357.79  | 0 |  |
| 365 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3011 | 46G-15 | PN1622240167 | 1 | BH600*250*10*14  | 11450  | 1805.36  | 1805.36  | 0 |  |
| 366 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3012 | 46G-16 | PN1622240168 | 1 | BH500*250*10*14  | 11536  | 1582.49  | 1582.49  | 0 |  |
| 367 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3013 | 46G-17 | PN1622240169 | 1 | BH500*250*10*14  | 11536  | 1533.58  | 1533.58  | 0 |  |
| 368 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3014 | 46G-18 | PN1622240170 | 1 | HM582*300*12*17  | 8470   | 2010.36  | 2010.36  | 0 |  |
| 369 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3015 | 46G-19 | PN1622240171 | 2 | HN496*199*9*14   | 9986   | 1126.51  | 2253.02  | 0 |  |
| 370 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3016 | 46G-20 | PN1622240172 | 2 | HN496*199*9*14   | 13486  | 1105.24  | 2210.49  | 0 |  |
| 371 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3017 | 46G-21 | PN1622240173 | 1 | HN596*199*10*15  | 11530  | 1857.74  | 1857.74  | 0 |  |
| 372 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3018 | 46G-22 | PN1622240174 | 1 | BH800*250*12*20  | 9980   | 2202.3   | 2202.3   | 0 |  |
| 373 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3019 | 46G-23 | PN1622240175 | 1 | BH500*250*10*14  | 9083   | 1348.78  | 1348.78  | 0 |  |
| 374 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3020 | 46G-24 | PN1622240176 | 1 | HM582*300*12*17  | 8470   | 2010.36  | 2010.36  | 0 |  |
| 375 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3021 | 46G-25 | PN1622240177 | 1 | BH700*200*12*14  | 2895   | 358.09   | 358.09   | 0 |  |
| 376 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3022 | 46G-26 | PN1622240178 | 1 | BH800*300*12*20  | 9440   | 1661.95  | 1661.95  | 0 |  |
| 377 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3023 | 46G-27 | PN1622240179 | 1 | BH500*250*10*14  | 9083   | 1331.11  | 1331.11  | 0 |  |
| 378 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3024 | 46G-28 | PN1622240180 | 1 | BH500*300*10*14  | 9245   | 1683.56  | 1683.56  | 0 |  |
| 379 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3025 | 46G-29 | PN1622240181 | 1 | BH800*200*12*14  | 3951   | 605.12   | 605.12   | 0 |  |
| 380 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3026 | 46G-30 | PN1622240182 | 1 | BH800*200*12*14  | 3935   | 603.34   | 603.34   | 0 |  |
| 381 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3027 | 46G-31 | PN1622240183 | 1 | BH700*250*12*16  | 13260  | 1747.52  | 1747.52  | 0 |  |
| 382 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3028 | 46G-32 | PN1622240184 | 1 | BH700*350*12*20  | 9470   | 1742.38  | 1742.38  | 0 |  |
| 383 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3029 | 46G-33 | PN1622240185 | 1 | BH700*200*12*14  | 2885   | 337.2    | 337.2    | 0 |  |
| 384 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3030 | 46G-34 | PN1622240186 | 1 | BH1600*400*20*30 | 18483  | 8472.24  | 8472.24  | 0 |  |
| 385 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3031 | 46G-35 | PN1622240187 | 1 | HN596*199*10*15  | 11530  | 1808.11  | 1808.11  | 0 |  |
| 386 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3032 | 46G-36 | PN1622240188 | 1 | BH800*450*12*24  | 11983  | 2965.32  | 2965.32  | 0 |  |
| 387 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3033 | 46G-37 | PN1622240189 | 1 | HM582*300*12*17  | 9386   | 1588.24  | 1588.24  | 0 |  |
| 388 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3034 | 46G-38 | PN1622240190 | 1 | HM582*300*12*17  | 9386   | 1588.25  | 1588.25  | 0 |  |
| 389 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3035 | 46G-39 | PN1622240191 | 1 | BH700*200*12*14  | 2895   | 358.09   | 358.09   | 0 |  |
| 390 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3036 | 46G-40 | PN1622240192 | 1 | BH500*250*10*14  | 11773  | 1542.47  | 1542.47  | 0 |  |
| 391 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3037 | 46G-41 | PN1622240193 | 1 | BH500*250*10*14  | 11773  | 1542.47  | 1542.47  | 0 |  |
| 392 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3038 | 46G-42 | PN1622240194 | 1 | HN496*199*9*14   | 9269   | 762.22   | 762.22   | 0 |  |
| 393 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3039 | 46G-43 | PN1622240195 | 1 | BH800*350*12*24  | 11983  | 2552.45  | 2552.45  | 0 |  |
| 394 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3040 | 46G-44 | PN1622240196 | 1 | BH1600*400*20*30 | 18483  | 8472.25  | 8472.25  | 0 |  |
| 395 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3041 | 46G-45 | PN1622240197 | 1 | BH700*300*12*20  | 18245  | 2925.99  | 2925.99  | 0 |  |
| 396 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3042 | 46G-46 | PN1622240198 | 1 | HN496*199*9*14   | 3914   | 402.26   | 402.26   | 0 |  |
| 397 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3043 | 46G-47 | PN1622240199 | 1 | HN496*199*9*14   | 3945   | 328.38   | 328.38   | 0 |  |
| 398 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3044 | 46G-48 | PN1622240200 | 1 | HN496*199*9*14   | 1640   | 149.66   | 149.66   | 0 |  |
| 399 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3045 | 46G-49 | PN1622240201 | 1 | BH900*350*14*24  | 11450  | 2638.28  | 2638.28  | 0 |  |
| 400 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3046 | 46G-50 | PN1622240202 | 1 | HN496*199*9*14   | 10986  | 1357.79  | 1357.79  | 0 |  |
| 401 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3047 | 46G-51 | PN1622240203 | 1 | BH900*350*14*30  | 11450  | 3014.48  | 3014.48  | 0 |  |
| 402 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3048 | 46G-52 | PN1622240204 | 1 | BH600*200*8*10   | 8486   | 1035.87  | 1035.87  | 0 |  |
| 403 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3049 | 46G-53 | PN1622240205 | 1 | BH500*300*10*14  | 9245   | 1683.56  | 1683.56  | 0 |  |
| 404 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3050 | 46G-54 | PN1622240206 | 1 | BH700*250*12*16  | 13260  | 1747.52  | 1747.52  | 0 |  |
| 405 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3051 | 46G-55 | PN1622240207 | 1 | BH1900*450*20*36 | 18250  | 10077.18 | 10077.18 | 0 |  |
| 406 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3052 | 46G-56 | PN1622240208 | 1 | BH700*300*12*20  | 18245  | 2925.99  | 2925.99  | 0 |  |
| 407 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3053 | 46G-57 | PN1622240209 | 1 | BH500*250*10*14  | 5999   | 595.64   | 595.64   | 0 |  |
| 408 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3054 | 46G-58 | PN1622240210 | 1 | HN496*199*9*14   | 3885   | 422.08   | 422.08   | 0 |  |
| 409 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3055 | 46G-59 | PN1622240211 | 1 | BH500*250*10*14  | 10975  | 1367.73  | 1367.73  | 0 |  |
| 410 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3056 | 46G-60 | PN1622240212 | 1 | HN496*199*9*14   | 9269   | 765      | 765      | 0 |  |
| 411 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3057 | 46G-61 | PN1622240213 | 1 | BH700*350*12*20  | 9470   | 1804.42  | 1804.42  | 0 |  |
|     | TB2-SDC.VP101-00UHA-A-M1A-DTE-3058 | 46G-62 | PN1622240214 | 1 | BH800*250*12*20  | 9980   | 2202.3   | 2202.3   | 0 |  |



|     |                                    |         |              |   |                 |        |          |          |   |  |
|-----|------------------------------------|---------|--------------|---|-----------------|--------|----------|----------|---|--|
| 413 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3066 | 4VB-189 | PN1622140392 | 2 | HW250*250*9*14  | 4204.2 | 417.45   | 834.89   | 0 |  |
| 414 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3067 | 4VB-190 | PN1622140393 | 1 | HW250*250*9*14  | 4205.9 | 417.59   | 417.59   | 0 |  |
| 415 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3068 | 4VB-191 | PN1622140394 | 1 | HW300*300*10*15 | 4513.2 | 553.25   | 553.25   | 0 |  |
| 416 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3069 | 4VB-192 | PN1622140395 | 1 | HW250*250*9*14  | 4859.8 | 391.46   | 391.46   | 0 |  |
| 417 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3070 | 4VB-193 | PN1622140396 | 3 | HW250*250*9*14  | 1784.4 | 166.51   | 499.41   | 0 |  |
| 418 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3071 | 4VB-194 | PN1622140397 | 3 | HW250*250*9*14  | 1862.1 | 172.13   | 516.28   | 0 |  |
| 419 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3075 | 37G-42  | PN1622240225 | 1 | BH900*550*24*40 | 36980  | 23414.33 | 23414.33 | 0 |  |
| 420 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3076 | 37G-44  | PN1622240226 | 1 | BH900*400*20*30 | 36980  | 15602.09 | 15602.09 | 0 |  |
| 421 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3077 | 37G-52  | PN1622240227 | 1 | BH900*400*20*30 | 36980  | 15472.48 | 15472.48 | 0 |  |
| 422 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3078 | 41G-46  | PN1622240228 | 1 | BH900*650*24*40 | 37360  | 24232.35 | 24232.35 | 0 |  |
| 423 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3079 | 41G-73  | PN1622240229 | 1 | BH900*400*24*40 | 37310  | 16591.79 | 16591.79 | 0 |  |
| 424 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3080 | 41G-74  | PN1622240230 | 1 | BH900*500*24*40 | 37310  | 19566.6  | 19566.6  | 0 |  |
| 425 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3081 | 34PB-1  | PN1622240231 | 1 | C16A            | 2400   | 158.28   | 158.28   | 0 |  |
| 426 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3082 | 34PB-2  | PN1622240232 | 1 | C16A            | 2400   | 158.28   | 158.28   | 0 |  |
| 427 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3083 | 34PB-3  | PN1622240233 | 1 | C16A            | 3742   | 64.48    | 64.48    | 0 |  |
| 428 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3084 | 34PB-4  | PN1622240234 | 2 | I16             | 2254   | 47.61    | 95.22    | 0 |  |
| 429 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3085 | 34PB-5  | PN1622240235 | 2 | C16A            | 4000   | 77.67    | 155.35   | 0 |  |
| 430 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3086 | 34PB-6  | PN1622240236 | 1 | HN250*125*6*9   | 4893.5 | 156.92   | 156.92   | 0 |  |
| 431 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3087 | 34PB-7  | PN1622240237 | 1 | HN250*125*6*9   | 4893.5 | 156.92   | 156.92   | 0 |  |
| 432 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3088 | 34PB-8  | PN1622240238 | 6 | C16A            | 2592.5 | 44.67    | 268.02   | 0 |  |
| 433 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3089 | 34PB-9  | PN1622240239 | 1 | HN300*150*6.5*9 | 6480   | 271.99   | 271.99   | 0 |  |
| 434 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3090 | 34PB-10 | PN1622240240 | 1 | HN300*150*6.5*9 | 6480   | 269.16   | 269.16   | 0 |  |
| 435 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3091 | 34PB-11 | PN1622240241 | 1 | HN200*100*5.5*8 | 4730   | 102.37   | 102.37   | 0 |  |
| 436 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3092 | 34PB-12 | PN1622240242 | 1 | HN300*150*6.5*9 | 4893.5 | 199.49   | 199.49   | 0 |  |
| 437 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3093 | 37B-1   | PN1622240243 | 1 | C20A            | 4430   | 100.26   | 100.26   | 0 |  |
| 438 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3094 | 37B-2   | PN1622240244 | 1 | HN300*150*6.5*9 | 6991   | 291.61   | 291.61   | 0 |  |
| 439 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3095 | 37B-3   | PN1622240245 | 1 | C16A            | 1017.5 | 17.53    | 17.53    | 0 |  |
| 440 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3096 | 37B-4   | PN1622240246 | 1 | HN350*175*7*11  | 6991   | 376.65   | 376.65   | 0 |  |
| 441 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3097 | 37B-5   | PN1622240247 | 1 | C16A            | 4005   | 72.14    | 72.14    | 0 |  |
| 442 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3098 | 37B-6   | PN1622240248 | 1 | C20A            | 4005   | 91.46    | 91.46    | 0 |  |
| 443 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3099 | 37B-7   | PN1622240249 | 1 | C16A            | 2355   | 43.71    | 43.71    | 0 |  |
| 444 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3100 | 37B-8   | PN1622240250 | 1 | HN596*199*10*15 | 3684   | 400.95   | 400.95   | 0 |  |
| 445 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3101 | 37B-9   | PN1622240251 | 1 | C16A            | 3455   | 60.35    | 60.35    | 0 |  |
| 446 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3102 | 37B-10  | PN1622240252 | 1 | C16A            | 2980   | 51.35    | 51.35    | 0 |  |
| 447 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3103 | 37B-11  | PN1622240253 | 1 | HM582*300*12*17 | 4808   | 701.76   | 701.76   | 0 |  |
| 448 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3104 | 37B-12  | PN1622240254 | 1 | HN350*175*7*11  | 6989.5 | 385.82   | 385.82   | 0 |  |
| 449 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3105 | 37B-13  | PN1622240255 | 2 | I16             | 4025   | 88.66    | 177.32   | 0 |  |
| 450 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3106 | 37B-14  | PN1622240256 | 1 | HN446*199*8*12  | 5075   | 83.09    | 438.79   | 0 |  |
| 451 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3107 | 37B-15  | PN1622240257 | 1 | BH600*200*10*12 | 4985   | 88.66    | 463.92   | 0 |  |
| 452 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3108 | 37B-16  | PN1622240258 | 1 | BH550*200*8*10  | 4990   | 346.07   | 346.07   | 0 |  |
| 453 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3109 | 37B-17  | PN1622240259 | 2 | HM582*300*12*17 | 4807   | 696.95   | 1393.89  | 0 |  |
| 454 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3110 | 37B-18  | PN1622240260 | 1 | I16             | 3775   | 83.09    | 83.09    | 0 |  |
| 455 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3111 | 37B-19  | PN1622240261 | 1 | HN300*150*6.5*9 | 4693.5 | 83.09    | 188.81   | 0 |  |
| 456 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3112 | 37B-20  | PN1622240262 | 1 | HN300*150*6.5*9 | 4693.5 | 88.66    | 199.42   | 0 |  |
| 457 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3113 | 37B-21  | PN1622240263 | 1 | HN300*150*6.5*9 | 4543.5 | 180.04   | 180.04   | 0 |  |
| 458 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3114 | 37B-22  | PN1622240264 | 2 | C16A            | 3268.1 | 56.31    | 112.62   | 0 |  |
| 459 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3115 | 37B-23  | PN1622240265 | 2 | C16A            | 1304.2 | 22.47    | 44.94    | 0 |  |
| 460 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3116 | 37B-25  | PN1622240266 | 1 | HN596*199*10*15 | 3685   | 401.04   | 401.04   | 0 |  |
| 461 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3117 | 37B-26  | PN1622240267 | 1 | C20A            | 4580   | 103.65   | 103.65   | 0 |  |
| 462 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3118 | 37B-27  | PN1622240268 | 1 | HN300*150*6.5*9 | 4536.8 | 184.56   | 184.56   | 0 |  |
| 463 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3119 | 37B-28  | PN1622240269 | 1 | HN300*150*6.5*9 | 1395   | 63.91    | 63.91    | 0 |  |
| 464 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3120 | 37B-29  | PN1622240270 | 1 | HN300*150*6.5*9 | 4693.5 | 185.63   | 185.63   | 0 |  |
| 465 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3121 | 37B-30  | PN1622240271 | 1 | HN596*199*10*15 | 3684   | 400.95   | 400.95   | 0 |  |
| 466 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3122 | 37B-31  | PN1622240272 | 1 | HN596*199*10*15 | 3180   | 320.44   | 320.44   | 0 |  |
| 467 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3123 | 37B-32  | PN1622240273 | 1 | HN350*175*7*11  | 6991   | 360.96   | 360.96   | 0 |  |
| 468 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3124 | 37B-33  | PN1622240274 | 2 | C16A            | 3442.5 | 59.32    | 118.63   | 0 |  |
| 469 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3125 | 37B-34  | PN1622240275 | 1 | C16A            | 1017.5 | 17.53    | 17.53    | 0 |  |
| 470 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3126 | 37B-35  | PN1622240276 | 1 | I16             | 3442.5 | 90.26    | 90.26    | 0 |  |
| 471 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3127 | 37B-36  | PN1622240277 | 1 | I16             | 3442.5 | 90.26    | 90.26    | 0 |  |
| 472 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3128 | 37B-37  | PN1622240278 | 1 | C16A            | 4417.5 | 77.68    | 77.68    | 0 |  |
| 473 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3129 | 37B-38  | PN1622240279 | 4 | C20A            | 2858   | 67.22    | 268.87   | 0 |  |
| 474 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3130 | 37B-39  | PN1622240280 | 2 | C16A            | 1034   | 17.82    | 35.63    | 0 |  |
| 475 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3131 | 37B-40  | PN1622240281 | 1 | HN500*200*10*16 | 3180   | 321.04   | 321.04   | 0 |  |
| 476 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3132 | 37B-41  | PN1622240282 | 2 | C16A            | 1834.1 | 31.6     | 63.21    | 0 |  |
| 477 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3133 | 37B-42  | PN1622240283 | 1 | C16A            | 984    | 16.96    | 16.96    | 0 |  |
| 478 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3134 | 37B-43  | PN1622240284 | 1 | C16A            | 1104   | 19.02    | 19.02    | 0 |  |
| 479 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3135 | 37B-44  | PN1622240285 | 1 | I20A            | 1890.4 | 52.8     | 52.8     | 0 |  |
| 480 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3136 | 37B-45  | PN1622240286 | 1 | HN300*150*6.5*9 | 6990   | 291.58   | 291.58   | 0 |  |
|     | 2-SDC.VP101-00UHA-A-M1A-DTE-3137   | 37B-46  | PN1622240287 | 1 | HN350*175*7*11  | 6991   | 360.96   | 360.96   | 0 |  |



|     |                                    |         |              |    |                 |        |        |         |   |  |
|-----|------------------------------------|---------|--------------|----|-----------------|--------|--------|---------|---|--|
| 482 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3138 | 37B-47  | PN1622240288 | 1  | HN300*150*6.5*9 | 1383   | 63.25  | 63.25   | 0 |  |
| 483 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3139 | 37B-48  | PN1622240289 | 1  | C16A            | 1590   | 29.61  | 29.61   | 0 |  |
| 484 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3140 | 37B-49  | PN1622240290 | 1  | HN300*150*6.5*9 | 4693.5 | 199.42 | 199.42  | 0 |  |
| 485 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3141 | 37B-50  | PN1622240291 | 1  | HN350*175*7*11  | 6990.5 | 385.87 | 385.87  | 0 |  |
| 486 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3142 | 37B-51  | PN1622240292 | 1  | HN300*150*6.5*9 | 4693.5 | 188.81 | 188.81  | 0 |  |
| 487 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3143 | 37B-52  | PN1622240293 | 1  | I20A            | 1890.4 | 52.8   | 52.8    | 0 |  |
| 488 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3144 | 37B-53  | PN1622240294 | 1  | HN350*175*7*11  | 6990   | 376.6  | 376.6   | 0 |  |
| 489 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3145 | 37B-54  | PN1622240295 | 1  | HN300*150*6.5*9 | 4693.5 | 188.81 | 188.81  | 0 |  |
| 490 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3146 | 37B-55  | PN1622240296 | 1  | BH600*200*10*12 | 4984   | 475.32 | 475.32  | 0 |  |
| 491 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3147 | 37B-56  | PN1622240297 | 1  | BH600*200*10*12 | 4984   | 461.67 | 461.67  | 0 |  |
| 492 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3148 | 37B-57  | PN1622240298 | 1  | C16A            | 3805   | 91.24  | 91.24   | 0 |  |
| 493 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3149 | 37B-58  | PN1622240299 | 2  | BH500*150*8*10  | 1358   | 87.02  | 174.04  | 0 |  |
| 494 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3150 | 37B-59  | PN1622240300 | 1  | C16A            | 3805   | 91.24  | 91.24   | 0 |  |
| 495 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3151 | 37B-60  | PN1622240301 | 1  | C16A            | 3555   | 61.26  | 61.26   | 0 |  |
| 496 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3152 | 37B-61  | PN1622240302 | 1  | BH600*200*10*12 | 4985   | 463.23 | 463.23  | 0 |  |
| 497 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3153 | 37B-62  | PN1622240303 | 1  | C16A            | 4442.5 | 78.12  | 78.12   | 0 |  |
| 498 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3154 | 37B-63  | PN1622240304 | 1  | HM582*300*12*17 | 4808   | 701.76 | 701.76  | 0 |  |
| 499 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3155 | 37B-64  | PN1622240305 | 2  | C16A            | 1555   | 26.79  | 53.59   | 0 |  |
| 500 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3156 | 37B-66  | PN1622240306 | 1  | C16A            | 3180.5 | 54.8   | 54.8    | 0 |  |
| 501 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3157 | 37B-67  | PN1622240307 | 2  | C16A            | 3855   | 66.42  | 132.85  | 0 |  |
| 502 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3158 | 37B-68  | PN1622240308 | 1  | C16A            | 3455   | 60.35  | 60.35   | 0 |  |
| 503 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3159 | 37B-69  | PN1622240309 | 1  | C16A            | 2980   | 51.35  | 51.35   | 0 |  |
| 504 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3160 | 37B-70  | PN1622240310 | 1  | C16A            | 2330   | 40.15  | 40.15   | 0 |  |
| 505 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3161 | 37B-71  | PN1622240311 | 1  | C16A            | 3980   | 71.71  | 71.71   | 0 |  |
| 506 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3162 | 37B-72  | PN1622240312 | 1  | HN300*150*6.5*9 | 3174.7 | 128.26 | 128.26  | 0 |  |
| 507 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3163 | 37B-73  | PN1622240313 | 1  | HN500*200*10*16 | 3180   | 321.04 | 321.04  | 0 |  |
| 508 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3164 | 37B-74  | PN1622240314 | 1  | I16             | 4025   | 88.66  | 88.66   | 0 |  |
| 509 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3165 | 37B-75  | PN1622240315 | 1  | C20A            | 4405   | 83.09  | 99.69   | 0 |  |
| 510 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3166 | 37B-76  | PN1622240316 | 1  | C20A            | 3980   | 88.66  | 90.89   | 0 |  |
| 511 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3167 | 37B-77  | PN1622240317 | 1  | HN300*150*6.5*9 | 4543.5 | 183.21 | 183.21  | 0 |  |
| 512 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3168 | 37B-78  | PN1622240318 | 4  | I16             | 3467.5 | 90.77  | 363.08  | 0 |  |
| 513 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3169 | 37B-79  | PN1622240319 | 1  | BH550*200*8*10  | 4990   | 356.71 | 356.71  | 0 |  |
| 514 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3170 | 37B-80  | PN1622240320 | 1  | HN300*150*6.5*9 | 3174.7 | 128.18 | 128.18  | 0 |  |
| 515 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3171 | 37B-81  | PN1622240321 | 1  | HN300*150*6.5*9 | 4693.5 | 188.81 | 188.81  | 0 |  |
| 516 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3172 | 37B-82  | PN1622240322 | 1  | HN300*150*6.5*9 | 4536.8 | 182.26 | 182.26  | 0 |  |
| 517 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3173 | 37B-83  | PN1622240323 | 4  | BH500*150*8*10  | 1358   | 87.02  | 348.08  | 0 |  |
| 518 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3174 | 37B-84  | PN1622240324 | 1  | BH600*200*10*12 | 4985   | 585.57 | 585.57  | 0 |  |
| 519 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3175 | 37B-85  | PN1622240325 | 1  | HN596*199*10*15 | 3685   | 401.05 | 401.05  | 0 |  |
| 520 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3176 | 37B-86  | PN1622240326 | 1  | HN300*150*6.5*9 | 4693.5 | 185.63 | 185.63  | 0 |  |
| 521 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3177 | 37B-87  | PN1622240327 | 1  | HN300*150*6.5*9 | 4543.5 | 180.04 | 180.04  | 0 |  |
| 522 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3178 | 37B-88  | PN1622240328 | 26 | HN500*200*10*16 | 3180   | 321.04 | 8347.05 | 0 |  |
| 523 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3179 | 37B-89  | PN1622240329 | 1  | C16A            | 1084   | 18.68  | 18.68   | 0 |  |
| 524 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3180 | 37B-90  | PN1622240330 | 8  | C16A            | 1590   | 29.61  | 236.91  | 0 |  |
| 525 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3181 | 37B-91  | PN1622240331 | 1  | C16A            | 1004   | 17.3   | 17.3    | 0 |  |
| 526 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3182 | 37B-92  | PN1622240332 | 1  | C16A            | 1854   | 31.95  | 31.95   | 0 |  |
| 527 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3183 | 37B-93  | PN1622240333 | 1  | HN300*150*6.5*9 | 4543.5 | 183.21 | 183.21  | 0 |  |
| 528 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3184 | 37B-94  | PN1622240334 | 2  | C16A            | 1054   | 18.16  | 36.32   | 0 |  |
| 529 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3185 | 37B-95  | PN1622240335 | 4  | C20A            | 2858   | 67.22  | 268.87  | 0 |  |
| 530 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3186 | 37B-96  | PN1622240336 | 1  | C20A            | 2858   | 68.8   | 68.8    | 0 |  |
| 531 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3187 | 37B-97  | PN1622240337 | 1  | C20A            | 2858   | 68.8   | 68.8    | 0 |  |
| 532 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3188 | 37B-98  | PN1622240338 | 2  | HN596*199*10*15 | 3180   | 320.44 | 640.88  | 0 |  |
| 533 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3189 | 37B-99  | PN1622240339 | 1  | C16A            | 1590   | 29.61  | 29.61   | 0 |  |
| 534 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3190 | 37B-100 | PN1622240340 | 1  | BH600*200*10*12 | 4984   | 582.66 | 582.66  | 0 |  |
| 535 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3191 | 37B-101 | PN1622240341 | 1  | HN596*199*10*15 | 3180   | 320.44 | 320.44  | 0 |  |
| 536 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3192 | 37B-102 | PN1622240342 | 2  | HN300*150*6.5*9 | 1383   | 63.25  | 126.5   | 0 |  |
| 537 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3193 | 37B-103 | PN1622240343 | 2  | HN300*150*6.5*9 | 1395   | 63.91  | 127.82  | 0 |  |
| 538 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3194 | 37B-104 | PN1622240344 | 2  | C16A            | 1942.5 | 33.47  | 66.94   | 0 |  |
| 539 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3195 | 37B-105 | PN1622240345 | 3  | HN300*150*6.5*9 | 1383   | 63.25  | 189.76  | 0 |  |
| 540 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3196 | 37B-106 | PN1622240346 | 3  | HN300*150*6.5*9 | 1395   | 63.91  | 191.74  | 0 |  |
| 541 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3197 | 37B-114 | PN1622240347 | 1  | C16A            | 3555   | 61.26  | 61.26   | 0 |  |
| 542 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3198 | 39PB-1  | PN1622240348 | 2  | C16A            | 1828   | 113.74 | 227.47  | 0 |  |
| 543 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3199 | 39PB-2  | PN1622240349 | 1  | C20A            | 985    | 28.17  | 28.17   | 0 |  |
| 544 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3200 | 39PB-3  | PN1622240350 | 1  | C20A            | 985    | 28.17  | 28.17   | 0 |  |
| 545 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3201 | 39PB-4  | PN1622240351 | 2  | C20A            | 881    | 22.97  | 45.95   | 0 |  |
| 546 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3202 | 39PB-5  | PN1622240352 | 2  | C20A            | 881    | 22.97  | 45.95   | 0 |  |
| 547 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3203 | 39PB-6  | PN1622240353 | 2  | C20A            | 4520   | 102.29 | 204.59  | 0 |  |
| 548 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3204 | 39PB-7  | PN1622240354 | 2  | C20A            | 4377   | 99.06  | 198.12  | 0 |  |
| 549 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3205 | 39PB-8  | PN1622240355 | 1  | C20A            | 4534   | 102.61 | 102.61  | 0 |  |
|     | TB2-SDC.VP101-00UHA-A-M1A-DTE-3206 | 39PB-9  | PN1622240356 | 2  | C20A            | 4607   | 104.26 | 208.53  | 0 |  |



|     |                                    |         |              |    |                 |         |        |        |   |  |
|-----|------------------------------------|---------|--------------|----|-----------------|---------|--------|--------|---|--|
| 551 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3207 | 39PB-10 | PN1622240357 | 2  | C20A            | 4457    | 100.87 | 201.74 | 0 |  |
| 552 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3208 | 39PB-11 | PN1622240358 | 1  | C20A            | 4607    | 104.26 | 104.26 | 0 |  |
| 553 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3209 | 39PB-12 | PN1622240359 | 1  | C20A            | 965     | 27.91  | 27.91  | 0 |  |
| 554 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3210 | 40PB-1  | PN1622240360 | 1  | C16A            | 2255    | 157.51 | 157.51 | 0 |  |
| 555 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3211 | 40PB-2  | PN1622240361 | 1  | C16A            | 2255    | 157.51 | 157.51 | 0 |  |
| 556 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3212 | 41B-1   | PN1622240362 | 1  | HN200*100*5.5*8 | 5180.5  | 122.54 | 122.54 | 0 |  |
| 557 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3213 | 41B-2   | PN1622240363 | 5  | C16A            | 1134    | 19.54  | 97.7   | 0 |  |
| 558 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3214 | 41B-3   | PN1622240364 | 1  | HN396*199*7*11  | 9085.5  | 540.02 | 540.02 | 0 |  |
| 559 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3215 | 41B-4   | PN1622240365 | 1  | C20A            | 4430    | 102.13 | 102.13 | 0 |  |
| 560 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3216 | 41B-7   | PN1622240366 | 1  | BH600*200*8*10  | 5484    | 418.4  | 418.4  | 0 |  |
| 561 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3217 | 41B-9   | PN1622240367 | 2  | C16A            | 1184    | 20.4   | 40.8   | 0 |  |
| 562 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3218 | 41B-10  | PN1622240368 | 1  | C16A            | 2322.8  | 40.02  | 40.02  | 0 |  |
| 563 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3219 | 41B-11  | PN1622240369 | 1  | C16A            | 1629.4  | 28.08  | 28.08  | 0 |  |
| 564 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3220 | 41B-12  | PN1622240370 | 1  | HN350*175*7*11  | 8488    | 446.86 | 446.86 | 0 |  |
| 565 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3221 | 41B-14  | PN1622240371 | 1  | HN350*175*7*11  | 8488    | 446.86 | 446.86 | 0 |  |
| 566 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3222 | 41B-15  | PN1622240372 | 1  | C20A            | 4430    | 102.13 | 102.13 | 0 |  |
| 567 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3223 | 41B-16  | PN1622240373 | 1  | C16A            | 2730    | 47.86  | 47.86  | 0 |  |
| 568 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3224 | 41B-17  | PN1622240374 | 1  | BH600*200*8*10  | 6490    | 465.9  | 465.9  | 0 |  |
| 569 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3225 | 41B-18  | PN1622240375 | 1  | BH600*200*8*10  | 6491    | 466.39 | 466.39 | 0 |  |
| 570 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3226 | 41B-19  | PN1622240376 | 2  | C20A            | 4430    | 100.26 | 200.52 | 0 |  |
| 571 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3227 | 41B-20  | PN1622240377 | 4  | C20A            | 2858    | 67.76  | 271.06 | 0 |  |
| 572 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3228 | 41B-21  | PN1622240378 | 2  | C20A            | 1740.1  | 42.46  | 84.93  | 0 |  |
| 573 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3229 | 41B-22  | PN1622240379 | 1  | C20A            | 3687.1  | 86.97  | 86.97  | 0 |  |
| 574 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3230 | 41B-23  | PN1622240380 | 1  | HN300*150*6.5*9 | 1284.5  | 55.76  | 55.76  | 0 |  |
| 575 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3231 | 41B-24  | PN1622240381 | 1  | BH600*200*8*10  | 6490    | 465.9  | 465.9  | 0 |  |
| 576 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3232 | 41B-25  | PN1622240382 | 1  | BH600*200*8*10  | 5485    | 423.21 | 423.21 | 0 |  |
| 577 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3233 | 41B-26  | PN1622240383 | 1  | BH600*200*8*10  | 4807    | 346.17 | 346.17 | 0 |  |
| 578 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3234 | 41B-27  | PN1622240384 | 2  | HN200*100*5.5*8 | 5180.5  | 112.12 | 224.24 | 0 |  |
| 579 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3235 | 41B-28  | PN1622240385 | 1  | HN496*199*9*14  | 3989    | 330.51 | 330.51 | 0 |  |
| 580 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3236 | 41B-29  | PN1622240386 | 1  | BH500*450*12*20 | 3989    | 747.28 | 747.28 | 0 |  |
| 581 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3237 | 41B-30  | PN1622240387 | 1  | HN396*199*7*11  | 10988.5 | 661.59 | 661.59 | 0 |  |
| 582 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3238 | 41B-31  | PN1622240388 | 1  | HN496*199*9*14  | 3988    | 329.9  | 329.9  | 0 |  |
| 583 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3239 | 41B-32  | PN1622240389 | 1  | HN396*199*7*11  | 10988.5 | 659.74 | 659.74 | 0 |  |
| 584 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3240 | 41B-33  | PN1622240390 | 4  | C20A            | 1588    | 45.91  | 183.66 | 0 |  |
| 585 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3241 | 41B-34  | PN1622240391 | 1  | BH600*200*8*10  | 5485    | 423.21 | 423.21 | 0 |  |
| 586 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3242 | 41B-35  | PN1622240392 | 1  | HN396*199*7*11  | 9391    | 564.96 | 564.96 | 0 |  |
| 587 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3243 | 41B-37  | PN1622240393 | 1  | C16A            | 2069.8  | 35.66  | 35.66  | 0 |  |
| 588 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3244 | 41B-38  | PN1622240394 | 1  | C16A            | 2817.3  | 50.24  | 50.24  | 0 |  |
| 589 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3245 | 41B-39  | PN1622240395 | 1  | C16A            | 3230    | 55.66  | 55.66  | 0 |  |
| 590 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3246 | 41B-40  | PN1622240396 | 3  | HN496*199*9*14  | 1387.5  | 122.26 | 366.77 | 0 |  |
| 591 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3247 | 41B-41  | PN1622240397 | 1  | PL20*360        | 2184    | 575.69 | 575.69 | 0 |  |
| 592 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3248 | 41B-42  | PN1622240398 | 1  | HW200*200*8*12  | 5281    | 280.81 | 280.81 | 0 |  |
| 593 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3249 | 41B-43  | PN1622240399 | 1  | HW200*200*8*12  | 4455    | 230.48 | 230.48 | 0 |  |
| 594 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3250 | 41B-44  | PN1622240400 | 1  | BH600*200*8*10  | 4807    | 349.05 | 349.05 | 0 |  |
| 595 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3251 | 41B-46  | PN1622240401 | 1  | BH600*200*8*10  | 6491    | 466.39 | 466.39 | 0 |  |
| 596 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3252 | 41B-47  | PN1622240402 | 1  | C20A            | 2858    | 67.76  | 67.76  | 0 |  |
| 597 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3253 | 41B-48  | PN1622240403 | 1  | BH600*200*8*10  | 4807    | 350.37 | 350.37 | 0 |  |
| 598 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3254 | 41B-49  | PN1622240404 | 2  | C16A            | 2305    | 39.72  | 79.43  | 0 |  |
| 599 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3255 | 41B-50  | PN1622240405 | 1  | C16A            | 2880    | 49.62  | 49.62  | 0 |  |
| 600 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3256 | 41B-51  | PN1622240406 | 2  | HN200*100*5.5*8 | 4330    | 93.71  | 187.42 | 0 |  |
| 601 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3257 | 41B-52  | PN1622240407 | 4  | HN200*100*5.5*8 | 4480    | 96.96  | 387.83 | 0 |  |
| 602 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3258 | 41B-53  | PN1622240408 | 2  | BH600*200*8*10  | 3190    | 421.13 | 842.29 | 0 |  |
| 603 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3259 | 41B-54  | PN1622240409 | 2  | C20A            | 1740.1  | 42.46  | 84.93  | 0 |  |
| 604 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3260 | 41B-55  | PN1622240410 | 1  | C20A            | 2730    | 62.6   | 62.6   | 0 |  |
| 605 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3261 | 41B-57  | PN1622240411 | 1  | HW200*200*8*12  | 5155    | 271.11 | 271.11 | 0 |  |
| 606 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3262 | 41B-58  | PN1622240412 | 4  | C20A            | 1588    | 45.91  | 183.66 | 0 |  |
| 607 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3263 | 41B-61  | PN1622240413 | 1  | HN396*199*7*11  | 9391    | 553.69 | 553.69 | 0 |  |
| 608 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3264 | 41B-62  | PN1622240414 | 1  | HW200*200*8*12  | 5155    | 271.89 | 271.89 | 0 |  |
| 609 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3265 | 41B-65  | PN1622240415 | 1  | HN250*125*6*9   | 6891.5  | 221.18 | 221.18 | 0 |  |
| 610 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3266 | 41B-66  | PN1622240416 | 1  | HN250*125*6*9   | 6891.5  | 221.1  | 221.1  | 0 |  |
| 611 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3267 | 41B-67  | PN1622240417 | 1  | HN396*199*7*11  | 8488    | 508.96 | 508.96 | 0 |  |
| 612 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3268 | 41B-71  | PN1622240418 | 2  | HN200*100*5.5*8 | 5155    | 111.57 | 223.13 | 0 |  |
| 613 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3269 | 41B-72  | PN1622240419 | 1  | HN396*199*7*11  | 9085.5  | 540.02 | 540.02 | 0 |  |
| 614 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3270 | 41B-73  | PN1622240420 | 1  | HN350*175*7*11  | 8493    | 441.66 | 441.66 | 0 |  |
| 615 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3271 | 41B-74  | PN1622240421 | 10 | C16A            | 1793    | 30.89  | 308.95 | 0 |  |
| 616 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3272 | 41B-75  | PN1622240422 | 1  | BH500*200*8*10  | 5490    | 351.08 | 351.08 | 0 |  |
| 617 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3273 | 41B-78  | PN1622240423 | 1  | HN350*175*7*11  | 6490.5  | 337.49 | 337.49 | 0 |  |
| 618 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3274 | 41B-79  | PN1622240424 | 1  | C16A            | 4255    | 73.32  | 73.32  | 0 |  |
|     | TB2-SDC.VP101-00UHA-A-M1A-DTE-3275 | 41B-80  | PN1622240425 | 1  | C16A            | 3755    | 64.7   | 64.7   | 0 |  |



|     |                                    |         |              |   |                 |        |         |         |   |  |
|-----|------------------------------------|---------|--------------|---|-----------------|--------|---------|---------|---|--|
| 620 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3276 | 41B-81  | PN1622240426 | 1 | C16A            | 2367.5 | 40.79   | 40.79   | 0 |  |
| 621 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3277 | 41B-82  | PN1622240427 | 1 | BH550*200*8*10  | 5490   | 393.41  | 393.41  | 0 |  |
| 622 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3278 | 41B-84  | PN1622240428 | 2 | C16A            | 2255   | 38.86   | 77.71   | 0 |  |
| 623 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3279 | 41B-95  | PN1622240429 | 1 | HM582*300*12*17 | 9489   | 1335.14 | 1335.14 | 0 |  |
| 624 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3280 | 41B-96  | PN1622240430 | 1 | HN596*199*10*15 | 10990  | 1072.5  | 1072.5  | 0 |  |
| 625 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3281 | 41B-97  | PN1622240431 | 1 | HN596*199*10*15 | 8488   | 880.74  | 880.74  | 0 |  |
| 626 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3282 | 41B-98  | PN1622240432 | 1 | HN596*199*10*15 | 9488   | 929.71  | 929.71  | 0 |  |
| 627 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3283 | 41B-99  | PN1622240433 | 3 | C16A            | 980    | 16.89   | 50.66   | 0 |  |
| 628 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3284 | 41B-100 | PN1622240434 | 1 | HN350*175*7*11  | 6490.5 | 338.38  | 338.38  | 0 |  |
| 629 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3285 | 41B-101 | PN1622240435 | 1 | HN350*175*7*11  | 6490.5 | 339.22  | 339.22  | 0 |  |
| 630 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3286 | 41B-102 | PN1622240436 | 1 | HN350*175*7*11  | 6490.5 | 334.96  | 334.96  | 0 |  |
| 631 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3287 | 41B-103 | PN1622240437 | 1 | HN350*175*7*11  | 6490.5 | 337.57  | 337.57  | 0 |  |
| 632 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3288 | 41B-104 | PN1622240438 | 2 | C16A            | 3467.5 | 59.75   | 119.5   | 0 |  |
| 633 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3289 | 41B-105 | PN1622240439 | 1 | C16A            | 3505   | 60.39   | 60.39   | 0 |  |
| 634 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3290 | 41B-106 | PN1622240440 | 1 | C16A            | 1081   | 18.63   | 18.63   | 0 |  |
| 635 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3291 | 41B-107 | PN1622240441 | 1 | C16A            | 1081   | 18.63   | 18.63   | 0 |  |
| 636 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3292 | 41B-108 | PN1622240442 | 3 | HN300*150*6.5*9 | 1284.5 | 55.76   | 167.28  | 0 |  |
| 637 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3293 | 41B-109 | PN1622240443 | 1 | HN200*100*5.5*8 | 5281   | 114.29  | 114.29  | 0 |  |
| 638 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3294 | 41B-110 | PN1622240444 | 1 | C16A            | 2730   | 47.86   | 47.86   | 0 |  |
| 639 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3295 | 41B-111 | PN1622240445 | 2 | C16A            | 1793   | 32.46   | 64.92   | 0 |  |
| 640 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3296 | 41B-113 | PN1622240446 | 1 | BH600*200*8*10  | 3176   | 243.95  | 243.95  | 0 |  |
| 641 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3297 | 41B-114 | PN1622240447 | 1 | BH600*200*8*10  | 3176   | 241.07  | 241.07  | 0 |  |
| 642 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3298 | 41B-115 | PN1622240448 | 2 | BH600*200*8*10  | 3176   | 243.08  | 486.16  | 0 |  |
| 643 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3299 | 41B-116 | PN1622240449 | 1 | C16A            | 855.5  | 14.74   | 14.74   | 0 |  |
| 644 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3300 | 41B-117 | PN1622240450 | 1 | C16A            | 2069.8 | 35.66   | 35.66   | 0 |  |
| 645 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3301 | 41B-118 | PN1622240451 | 1 | C16A            | 855.5  | 14.74   | 14.74   | 0 |  |
| 646 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3302 | 41B-119 | PN1622240452 | 1 | C16A            | 2322.8 | 40.02   | 40.02   | 0 |  |
| 647 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3303 | 41B-120 | PN1622240453 | 1 | C16A            | 1629.4 | 28.08   | 28.08   | 0 |  |
| 648 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3304 | 41B-121 | PN1622240454 | 1 | C16A            | 4230   | 72.89   | 72.89   | 0 |  |
| 649 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3305 | 41B-122 | PN1622240455 | 1 | C16A            | 2817.3 | 50.24   | 50.24   | 0 |  |
| 650 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3306 | 41B-123 | PN1622240456 | 1 | BH550*200*8*10  | 5490   | 371.71  | 371.71  | 0 |  |
| 651 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3307 | 41B-124 | PN1622240457 | 1 | HM582*300*12*17 | 9489   | 1335.14 | 1335.14 | 0 |  |
| 652 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3308 | 41B-125 | PN1622240458 | 1 | C16A            | 980    | 16.89   | 16.89   | 0 |  |
| 653 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3309 | 41B-126 | PN1622240459 | 1 | C16A            | 942.5  | 16.24   | 16.24   | 0 |  |
| 654 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3310 | 41B-127 | PN1622240460 | 1 | HN350*175*7*11  | 8493   | 441.66  | 441.66  | 0 |  |
| 655 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3311 | 41B-128 | PN1622240461 | 1 | HN350*175*7*11  | 6490.5 | 337.49  | 337.49  | 0 |  |
| 656 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3312 | 41B-129 | PN1622240462 | 1 | HN596*199*10*15 | 10990  | 1069.23 | 1069.23 | 0 |  |
| 657 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3313 | 41B-130 | PN1622240463 | 1 | HN596*199*10*15 | 9488   | 929.6   | 929.6   | 0 |  |
| 658 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3314 | 41B-131 | PN1622240464 | 1 | C20A            | 3687.1 | 86.97   | 86.97   | 0 |  |
| 659 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3315 | 41B-132 | PN1622240465 | 1 | BH600*200*8*10  | 5484   | 418.4   | 418.4   | 0 |  |
| 660 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3316 | 41B-133 | PN1622240466 | 1 | HN200*100*5.5*8 | 5281   | 114.29  | 114.29  | 0 |  |
| 661 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3317 | 41B-136 | PN1622240467 | 1 | HN596*199*10*15 | 8488   | 880.7   | 880.7   | 0 |  |
| 662 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3318 | 41B-138 | PN1622240468 | 2 | C16A            | 1492   | 25.71   | 51.42   | 0 |  |
| 663 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3319 | 41B-139 | PN1622240469 | 1 | C16A            | 4255   | 73.32   | 73.32   | 0 |  |
| 664 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3320 | 41B-141 | PN1622240470 | 4 | C20A            | 2858   | 67.76   | 271.06  | 0 |  |
| 665 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3321 | 41B-142 | PN1622240471 | 2 | C20A            | 1144.5 | 25.9    | 51.8    | 0 |  |
| 666 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3322 | 41B-143 | PN1622240472 | 1 | BH600*200*8*10  | 4807   | 347.84  | 347.84  | 0 |  |
| 667 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3323 | 41B-145 | PN1622240473 | 1 | BH500*200*8*10  | 5490   | 351.08  | 351.08  | 0 |  |
| 668 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3324 | 41B-147 | PN1622240474 | 1 | HN200*100*5.5*8 | 4330   | 93.71   | 93.71   | 0 |  |
| 669 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3325 | 41B-148 | PN1622240475 | 1 | HN200*100*5.5*8 | 4330   | 93.71   | 93.71   | 0 |  |
| 670 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3326 | 41B-149 | PN1622240476 | 1 | HN200*100*5.5*8 | 4480   | 96.96   | 96.96   | 0 |  |
| 671 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3327 | 41B-150 | PN1622240477 | 1 | HN200*100*5.5*8 | 4480   | 96.96   | 96.96   | 0 |  |
| 672 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3328 | 41B-151 | PN1622240478 | 1 | HN200*100*5.5*8 | 4480   | 96.96   | 96.96   | 0 |  |
| 673 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3329 | 41B-152 | PN1622240479 | 1 | HN200*100*5.5*8 | 4480   | 96.96   | 96.96   | 0 |  |
| 674 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3330 | 41B-153 | PN1622240480 | 1 | C20A            | 1588   | 45.91   | 45.91   | 0 |  |
| 675 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3331 | 41B-155 | PN1622240481 | 1 | HN396*199*7*11  | 8488   | 504.85  | 504.85  | 0 |  |
| 676 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3332 | 41B-156 | PN1622240482 | 5 | C16A            | 1134   | 19.54   | 97.7    | 0 |  |
| 677 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3333 | 41B-157 | PN1622240483 | 1 | C20A            | 1588   | 45.91   | 45.91   | 0 |  |
| 678 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3334 | 41B-158 | PN1622240484 | 1 | C16A            | 4230   | 72.89   | 72.89   | 0 |  |
| 679 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3335 | 41B-159 | PN1622240485 | 5 | C20A            | 1185.3 | 39.26   | 196.29  | 0 |  |
| 680 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3336 | 41B-161 | PN1622240486 | 1 | C16A            | 3755   | 64.7    | 64.7    | 0 |  |
| 681 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3337 | 41B-162 | PN1622240487 | 1 | C16A            | 2367.5 | 40.79   | 40.79   | 0 |  |
| 682 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3338 | 41B-163 | PN1622240488 | 2 | C20A            | 1144.5 | 25.9    | 51.8    | 0 |  |
| 683 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3339 | 41B-164 | PN1622240489 | 4 | C20A            | 1185.3 | 39.26   | 157.03  | 0 |  |
| 684 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3340 | 41B-167 | PN1622240490 | 1 | PL20*360        | 2184   | 575.69  | 575.69  | 0 |  |
| 685 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3341 | 41B-168 | PN1622240491 | 1 | C16A            | 942.5  | 16.24   | 16.24   | 0 |  |
| 686 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3342 | 41B-169 | PN1622240492 | 1 | HN200*100*5.5*8 | 5180.5 | 122.54  | 122.54  | 0 |  |
| 687 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3343 | 41B-170 | PN1622240493 | 1 | C20A            | 2858   | 67.76   | 67.76   | 0 |  |
|     | TB2-SDC.VP101-00UHA-A-M1A-DTE-3344 | 41PB-1  | PN1622240494 | 2 | C20A            | 1499   | 115.61  | 231.23  | 0 |  |



|     |                                    |        |              |   |                 |        |        |        |   |  |
|-----|------------------------------------|--------|--------------|---|-----------------|--------|--------|--------|---|--|
| 689 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3345 | 41PB-2 | PN1622240495 | 1 | C20A            | 1378.5 | 94.25  | 94.25  | 0 |  |
| 690 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3346 | 41PB-3 | PN1622240496 | 1 | C20A            | 1378.5 | 94.25  | 94.25  | 0 |  |
| 691 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3347 | 42PB-1 | PN1622240497 | 1 | C16A            | 1415   | 75.29  | 75.29  | 0 |  |
| 692 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3348 | 43PB-1 | PN1622240498 | 1 | C16A            | 1740   | 391.46 | 391.46 | 0 |  |
| 693 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3349 | 43PB-2 | PN1622240499 | 1 | C16A            | 1740   | 139.92 | 139.92 | 0 |  |
| 694 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3350 | 44B-1  | PN1622240500 | 6 | C16A            | 805    | 13.87  | 83.22  | 0 |  |
| 695 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3351 | 44B-2  | PN1622240501 | 1 | HN350*175*7*11  | 8493   | 446.45 | 446.45 | 0 |  |
| 696 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3352 | 44B-3  | PN1622240502 | 1 | HN350*175*7*11  | 8493   | 446.45 | 446.45 | 0 |  |
| 697 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3353 | 44B-4  | PN1622240503 | 1 | C20A            | 1187   | 29.02  | 29.02  | 0 |  |
| 698 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3354 | 44B-5  | PN1622240504 | 1 | HN350*175*7*11  | 7900   | 402.61 | 402.61 | 0 |  |
| 699 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3355 | 44B-6  | PN1622240505 | 1 | C16A            | 1659.7 | 28.6   | 28.6   | 0 |  |
| 700 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3356 | 44B-7  | PN1622240506 | 2 | C16A            | 1207.8 | 20.81  | 41.62  | 0 |  |
| 701 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3357 | 44B-8  | PN1622240507 | 1 | C16A            | 2781.7 | 50.06  | 50.06  | 0 |  |
| 702 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3358 | 44B-9  | PN1622240508 | 2 | C20A            | 787    | 19.97  | 39.94  | 0 |  |
| 703 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3359 | 44B-10 | PN1622240509 | 2 | C16A            | 681    | 11.73  | 23.47  | 0 |  |
| 704 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3360 | 44B-11 | PN1622240510 | 3 | C20A            | 1187   | 29.02  | 87.07  | 0 |  |
| 705 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3361 | 44B-12 | PN1622240511 | 1 | HN350*175*7*11  | 7900   | 402.61 | 402.61 | 0 |  |
| 706 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3362 | 44B-13 | PN1622240512 | 2 | HW150*150*7*10  | 4988.6 | 158.8  | 317.59 | 0 |  |
| 707 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3363 | 44B-14 | PN1622240513 | 1 | HN396*199*7*11  | 9091.5 | 547.71 | 547.71 | 0 |  |
| 708 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3364 | 44B-15 | PN1622240514 | 1 | HN350*175*7*11  | 4750.9 | 249.75 | 249.75 | 0 |  |
| 709 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3365 | 44B-16 | PN1622240515 | 1 | HN396*199*7*11  | 9393   | 555.68 | 555.68 | 0 |  |
| 710 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3366 | 44B-17 | PN1622240516 | 1 | HN396*199*7*11  | 9393   | 549.1  | 549.1  | 0 |  |
| 711 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3367 | 44B-18 | PN1622240517 | 2 | C20A            | 787    | 19.97  | 39.94  | 0 |  |
| 712 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3368 | 44B-19 | PN1622240518 | 1 | HN350*175*7*11  | 4750.9 | 249.75 | 249.75 | 0 |  |
| 713 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3369 | 44B-20 | PN1622240519 | 2 | C16A            | 2209   | 39.62  | 79.23  | 0 |  |
| 714 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3370 | 44B-21 | PN1622240520 | 1 | HN396*199*7*11  | 6795   | 416.41 | 416.41 | 0 |  |
| 715 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3371 | 44B-22 | PN1622240521 | 1 | HN396*199*7*11  | 6795   | 422.99 | 422.99 | 0 |  |
| 716 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3372 | 44B-23 | PN1622240522 | 1 | HN396*199*7*11  | 9390   | 555.51 | 555.51 | 0 |  |
| 717 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3373 | 44B-24 | PN1622240523 | 1 | HN396*199*7*11  | 9390   | 548.93 | 548.93 | 0 |  |
| 718 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3374 | 44B-25 | PN1622240524 | 1 | HN396*199*7*11  | 9393   | 558.14 | 558.14 | 0 |  |
| 719 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3375 | 44B-26 | PN1622240525 | 1 | HN396*199*7*11  | 9390   | 557.97 | 557.97 | 0 |  |
| 720 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3376 | 44B-27 | PN1622240526 | 1 | C16A            | 1659.7 | 28.6   | 28.6   | 0 |  |
| 721 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3377 | 44B-28 | PN1622240527 | 2 | C20A            | 787    | 19.97  | 39.94  | 0 |  |
| 722 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3378 | 44B-29 | PN1622240528 | 1 | C16A            | 2166.5 | 38.94  | 38.94  | 0 |  |
| 723 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3379 | 44B-30 | PN1622240529 | 2 | C16A            | 2067   | 35.62  | 71.23  | 0 |  |
| 724 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3380 | 44B-31 | PN1622240530 | 2 | C20A            | 1187   | 29.02  | 58.05  | 0 |  |
| 725 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3381 | 44B-32 | PN1622240531 | 1 | HN396*199*7*11  | 9091.5 | 542.69 | 542.69 | 0 |  |
| 726 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3382 | 44B-33 | PN1622240532 | 2 | C16A            | 2017.4 | 34.76  | 69.52  | 0 |  |
| 727 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3383 | 44B-34 | PN1622240533 | 1 | HN396*199*7*11  | 9091.5 | 538.98 | 538.98 | 0 |  |
| 728 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3384 | 44B-35 | PN1622240534 | 1 | C16A            | 2781.7 | 50.06  | 50.06  | 0 |  |
| 729 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3385 | 44B-36 | PN1622240535 | 1 | C16A            | 787    | 15.77  | 15.77  | 0 |  |
| 730 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3386 | 44B-37 | PN1622240536 | 3 | C20A            | 1187   | 29.02  | 87.07  | 0 |  |
| 731 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3387 | 44B-38 | PN1622240537 | 2 | C20A            | 787    | 19.97  | 39.94  | 0 |  |
| 732 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3388 | 44B-39 | PN1622240538 | 1 | C20A            | 787    | 19.97  | 19.97  | 0 |  |
| 733 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3389 | 44B-40 | PN1622240539 | 1 | C20A            | 1187   | 29.02  | 29.02  | 0 |  |
| 734 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3390 | 44B-41 | PN1622240540 | 1 | C20A            | 893    | 24.53  | 24.53  | 0 |  |
| 735 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3391 | 44B-42 | PN1622240541 | 1 | HN396*199*7*11  | 9390   | 550.16 | 550.16 | 0 |  |
| 736 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3392 | 44B-43 | PN1622240542 | 1 | HN396*199*7*11  | 6944.2 | 410.22 | 410.22 | 0 |  |
| 737 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3393 | 44B-44 | PN1622240543 | 1 | HN396*199*7*11  | 9393   | 550.33 | 550.33 | 0 |  |
| 738 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3394 | 44B-45 | PN1622240544 | 1 | HN396*199*7*11  | 9091.5 | 544.42 | 544.42 | 0 |  |
| 739 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3395 | 44B-46 | PN1622240545 | 1 | HN396*199*7*11  | 6944.2 | 418.03 | 418.03 | 0 |  |
| 740 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3396 | 44B-47 | PN1622240546 | 2 | C20A            | 787    | 19.97  | 39.94  | 0 |  |
| 741 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3397 | 44B-48 | PN1622240547 | 2 | C20A            | 1187   | 29.02  | 58.05  | 0 |  |
| 742 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3398 | 44B-49 | PN1622240548 | 1 | C16A            | 2166.5 | 38.94  | 38.94  | 0 |  |
| 743 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3399 | 46B-1  | PN1622240549 | 1 | C16A            | 2130   | 36.7   | 36.7   | 0 |  |
| 744 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3400 | 46B-2  | PN1622240550 | 1 | HN446*199*8*12  | 6489.5 | 468.84 | 468.84 | 0 |  |
| 745 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3401 | 46B-3  | PN1622240551 | 1 | C20A            | 4880   | 114.69 | 114.69 | 0 |  |
| 746 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3402 | 46B-4  | PN1622240552 | 1 | BH600*150*10*10 | 3988   | 310.65 | 310.65 | 0 |  |
| 747 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3403 | 46B-5  | PN1622240553 | 1 | BH600*150*10*10 | 3988   | 310.65 | 310.65 | 0 |  |
| 748 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3404 | 46B-6  | PN1622240554 | 1 | BH500*200*8*10  | 4815.5 | 314.52 | 314.52 | 0 |  |
| 749 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3405 | 46B-7  | PN1622240555 | 1 | BH500*200*8*10  | 4814   | 314.43 | 314.43 | 0 |  |
| 750 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3406 | 46B-8  | PN1622240556 | 1 | HN300*150*6.5*9 | 2990.5 | 124    | 124    | 0 |  |
| 751 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3407 | 46B-9  | PN1622240557 | 1 | HN300*150*6.5*9 | 2990.5 | 127.24 | 127.24 | 0 |  |
| 752 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3408 | 46B-10 | PN1622240558 | 1 | HM582*300*12*17 | 5489   | 767.8  | 767.8  | 0 |  |
| 753 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3409 | 46B-11 | PN1622240559 | 1 | HM390*300*10*16 | 5500   | 624.07 | 624.07 | 0 |  |
| 754 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3410 | 46B-12 | PN1622240560 | 1 | HN596*199*10*15 | 8486   | 823.89 | 823.89 | 0 |  |
| 755 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3411 | 46B-13 | PN1622240561 | 1 | HM582*300*12*17 | 5489   | 787.5  | 787.5  | 0 |  |
| 756 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3412 | 46B-15 | PN1622240562 | 2 | HN396*199*7*11  | 3990   | 236.47 | 472.94 | 0 |  |
|     | 2-SDC.VP101-00UHA-A-M1A-DTE-3413   | 46B-16 | PN1622240563 | 1 | HN300*150*6.5*9 | 2990.5 | 124    | 124    | 0 |  |



|     |                                    |         |              |   |                 |         |         |         |   |  |
|-----|------------------------------------|---------|--------------|---|-----------------|---------|---------|---------|---|--|
| 758 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3414 | 46B-17  | PN1622240564 | 1 | HN250*125*6*9   | 4664    | 145.25  | 145.25  | 0 |  |
| 759 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3415 | 46B-18  | PN1622240565 | 1 | HN250*125*6*9   | 4664    | 151.32  | 151.32  | 0 |  |
| 760 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3416 | 46B-19  | PN1622240566 | 1 | HN300*150*6.5*9 | 6489.5  | 279.53  | 279.53  | 0 |  |
| 761 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3417 | 46B-20  | PN1622240567 | 1 | HN300*150*6.5*9 | 1304    | 65      | 65      | 0 |  |
| 762 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3418 | 46B-21  | PN1622240568 | 1 | BH700*300*12*20 | 9487    | 1513.11 | 1513.11 | 0 |  |
| 763 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3419 | 46B-22  | PN1622240569 | 1 | HN200*100*5.5*8 | 4880    | 109.37  | 109.37  | 0 |  |
| 764 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3420 | 46B-23  | PN1622240570 | 1 | HN200*100*5.5*8 | 4380.5  | 94.8    | 94.8    | 0 |  |
| 765 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3421 | 46B-24  | PN1622240571 | 1 | HN200*100*5.5*8 | 3955.5  | 85.61   | 85.61   | 0 |  |
| 766 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3422 | 46B-25  | PN1622240572 | 1 | HN200*100*5.5*8 | 3955.5  | 85.61   | 85.61   | 0 |  |
| 767 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3423 | 46B-26  | PN1622240573 | 1 | HN200*100*5.5*8 | 4380.5  | 99.95   | 99.95   | 0 |  |
| 768 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3424 | 46B-27  | PN1622240574 | 1 | HN250*125*6*9   | 4664    | 93.71   | 93.71   | 0 |  |
| 769 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3425 | 46B-28  | PN1622240575 | 1 | HN200*100*5.5*8 | 4330    | 93.71   | 93.71   | 0 |  |
| 770 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3426 | 46B-29  | PN1622240576 | 1 | HN396*199*7*11  | 10989.5 | 648.52  | 648.52  | 0 |  |
| 771 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3427 | 46B-30  | PN1622240577 | 1 | HN596*199*10*15 | 6491    | 641.47  | 641.47  | 0 |  |
| 772 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3428 | 46B-31  | PN1622240578 | 1 | BH500*250*10*14 | 6489.5  | 619.24  | 619.24  | 0 |  |
| 773 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3429 | 46B-32  | PN1622240579 | 1 | BH600*250*10*14 | 5488    | 579.67  | 579.67  | 0 |  |
| 774 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3430 | 46B-33  | PN1622240580 | 1 | BH500*250*10*14 | 6489.5  | 618.87  | 618.87  | 0 |  |
| 775 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3431 | 46B-34  | PN1622240581 | 1 | HN446*199*8*12  | 6489.5  | 454.95  | 454.95  | 0 |  |
| 776 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3432 | 46B-35  | PN1622240582 | 1 | HN596*199*10*15 | 5489    | 575.56  | 575.56  | 0 |  |
| 777 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3433 | 46B-36  | PN1622240583 | 1 | HM582*300*12*17 | 5000    | 774.03  | 774.03  | 0 |  |
| 778 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3434 | 46B-37  | PN1622240584 | 1 | HM582*300*12*17 | 5489    | 841.63  | 841.63  | 0 |  |
| 779 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3435 | 46B-38  | PN1622240585 | 1 | HM390*300*10*16 | 5500    | 619.7   | 619.7   | 0 |  |
| 780 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3436 | 46B-39  | PN1622240586 | 1 | HM482*300*11*15 | 5500    | 704.47  | 704.47  | 0 |  |
| 781 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3437 | 46B-40  | PN1622240587 | 1 | HN300*150*6.5*9 | 2990.5  | 126.24  | 126.24  | 0 |  |
| 782 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3438 | 46B-41  | PN1622240588 | 1 | HM582*300*12*17 | 9391    | 1301.35 | 1301.35 | 0 |  |
| 783 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3439 | 46B-42  | PN1622240589 | 1 | HN396*199*7*11  | 3988    | 236.36  | 236.36  | 0 |  |
| 784 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3440 | 46B-43  | PN1622240590 | 1 | HN350*175*7*11  | 3990.5  | 208.04  | 208.04  | 0 |  |
| 785 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3441 | 46B-44  | PN1622240591 | 1 | HN496*199*9*14  | 9089.5  | 739.86  | 739.86  | 0 |  |
| 786 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3442 | 46B-45  | PN1622240592 | 1 | C20A            | 1304    | 40.07   | 40.07   | 0 |  |
| 787 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3443 | 46B-46  | PN1622240593 | 2 | C16A            | 3430.5  | 59.11   | 118.22  | 0 |  |
| 788 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3444 | 46B-47  | PN1622240594 | 1 | BH800*350*12*24 | 11988   | 2463.1  | 2463.1  | 0 |  |
| 789 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3445 | 46B-48  | PN1622240595 | 1 | BH800*300*12*24 | 10990   | 2048.75 | 2048.75 | 0 |  |
| 790 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3446 | 46B-49  | PN1622240596 | 2 | HW200*200*8*12  | 1650    | 88.56   | 177.13  | 0 |  |
| 791 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3447 | 46B-51  | PN1622240597 | 1 | HN396*199*7*11  | 3290    | 214.37  | 214.37  | 0 |  |
| 792 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3448 | 46B-54  | PN1622240598 | 1 | HN446*199*8*12  | 4290    | 313.32  | 313.32  | 0 |  |
| 793 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3449 | 46B-60  | PN1622240599 | 2 | HM582*300*12*17 | 5000    | 773.95  | 1547.9  | 0 |  |
| 794 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3450 | 46B-62  | PN1622240600 | 2 | HN396*199*7*11  | 3990.5  | 236.5   | 473     | 0 |  |
| 795 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3451 | 46B-63  | PN1622240601 | 1 | HN350*175*7*11  | 3988    | 213.31  | 213.31  | 0 |  |
| 796 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3452 | 46B-64  | PN1622240602 | 1 | HN350*175*7*11  | 3987    | 207.35  | 207.35  | 0 |  |
| 797 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3453 | 46B-66  | PN1622240603 | 4 | C16A            | 857     | 14.77   | 59.07   | 0 |  |
| 798 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3454 | 46B-67  | PN1622240604 | 2 | HN496*199*9*14  | 8486    | 687.58  | 1375.16 | 0 |  |
| 799 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3455 | 46B-70  | PN1622240605 | 1 | HN446*199*8*12  | 3988    | 276.69  | 276.69  | 0 |  |
| 800 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3456 | 46B-71  | PN1622240606 | 1 | HN446*199*8*12  | 5000    | 378.88  | 378.88  | 0 |  |
| 801 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3457 | 46B-72  | PN1622240607 | 1 | C20A            | 1304    | 40.07   | 40.07   | 0 |  |
| 802 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3458 | 46B-73  | PN1622240608 | 2 | C20A            | 4430    | 100.26  | 200.52  | 0 |  |
| 803 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3459 | 46B-74  | PN1622240609 | 2 | C20A            | 4280    | 96.86   | 193.73  | 0 |  |
| 804 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3460 | 46B-75  | PN1622240610 | 1 | C20A            | 4455    | 105.07  | 105.07  | 0 |  |
| 805 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3461 | 46B-76  | PN1622240611 | 2 | C20A            | 4305    | 97.43   | 194.86  | 0 |  |
| 806 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3462 | 46B-77  | PN1622240612 | 3 | C16A            | 3955.5  | 68.16   | 204.47  | 0 |  |
| 807 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3463 | 46B-78  | PN1622240613 | 2 | C16A            | 1007.5  | 17.36   | 34.72   | 0 |  |
| 808 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3464 | 46B-79  | PN1622240614 | 1 | C20A            | 656.5   | 55.42   | 55.42   | 0 |  |
| 809 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3465 | 46B-80  | PN1622240615 | 2 | C16A            | 4105.5  | 70.74   | 141.48  | 0 |  |
| 810 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3466 | 46B-81  | PN1622240616 | 2 | C16A            | 842     | 14.51   | 29.02   | 0 |  |
| 811 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3467 | 46B-85  | PN1622240617 | 3 | HN300*150*6.5*9 | 1992.5  | 81.68   | 245.04  | 0 |  |
| 812 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3468 | 46B-86  | PN1622240618 | 1 | HN396*199*7*11  | 4139.5  | 261.54  | 261.54  | 0 |  |
| 813 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3469 | 46B-90  | PN1622240619 | 3 | C16A            | 1055.5  | 18.18   | 54.55   | 0 |  |
| 814 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3470 | 46B-91  | PN1622240620 | 1 | C16A            | 967.5   | 16.67   | 16.67   | 0 |  |
| 815 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3471 | 46B-92  | PN1622240621 | 3 | C16A            | 630     | 15.16   | 45.49   | 0 |  |
| 816 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3472 | 46B-93  | PN1622240622 | 1 | C16A            | 2430    | 41.87   | 41.87   | 0 |  |
| 817 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3473 | 46B-94  | PN1622240623 | 2 | C16A            | 782     | 13.47   | 26.95   | 0 |  |
| 818 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3475 | 46B-96  | PN1622240625 | 1 | HN200*100*5.5*8 | 4392.5  | 102.23  | 102.23  | 0 |  |
| 819 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3476 | 46B-97  | PN1622240626 | 1 | HN200*100*5.5*8 | 4880    | 109.37  | 109.37  | 0 |  |
| 820 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3477 | 46B-98  | PN1622240627 | 2 | C16A            | 2830.5  | 48.77   | 97.54   | 0 |  |
| 821 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3478 | 46B-99  | PN1622240628 | 1 | HN596*199*10*15 | 8486    | 826.91  | 826.91  | 0 |  |
| 822 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3479 | 46B-100 | PN1622240629 | 2 | HN200*100*5.5*8 | 5180    | 112.11  | 224.22  | 0 |  |
| 823 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3480 | 46B-101 | PN1622240630 | 3 | C16A            | 3605.5  | 62.13   | 186.38  | 0 |  |
| 824 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3481 | 46B-102 | PN1622240631 | 3 | C16A            | 630     | 16.02   | 48.07   | 0 |  |
| 825 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3482 | 46B-103 | PN1622240632 | 1 | C16A            | 3442.5  | 59.32   | 59.32   | 0 |  |
|     | 2-SDC.VP101-00UHA-A-M1A-DTE-3484   | 46B-106 | PN1622240634 | 1 | HN200*100*5.5*8 | 3955.5  | 85.61   | 85.61   | 0 |  |



|     |                                    |         |              |    |                 |         |         |         |   |  |
|-----|------------------------------------|---------|--------------|----|-----------------|---------|---------|---------|---|--|
| 827 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3485 | 46B-107 | PN1622240635 | 2  | HN200*100*5.5*8 | 3955.5  | 85.61   | 171.21  | 0 |  |
| 828 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3486 | 46B-108 | PN1622240636 | 10 | I16             | 4030    | 82.67   | 826.67  | 0 |  |
| 829 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3487 | 46B-109 | PN1622240637 | 8  | I16             | 3555    | 72.92   | 583.38  | 0 |  |
| 830 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3488 | 46B-110 | PN1622240638 | 8  | I16             | 3580.5  | 73.45   | 587.57  | 0 |  |
| 831 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3489 | 46B-111 | PN1622240639 | 5  | I16             | 3605.5  | 73.96   | 369.8   | 0 |  |
| 832 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3490 | 46B-112 | PN1622240640 | 2  | HN200*100*5.5*8 | 5205    | 112.65  | 225.3   | 0 |  |
| 833 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3491 | 46B-117 | PN1622240641 | 2  | BH700*250*12*20 | 9488    | 1356.71 | 2713.42 | 0 |  |
| 834 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3492 | 46B-121 | PN1622240642 | 1  | I16             | 4130    | 88.68   | 88.68   | 0 |  |
| 835 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3493 | 46B-129 | PN1622240643 | 1  | I16             | 3605.5  | 73.96   | 73.96   | 0 |  |
| 836 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3494 | 46B-130 | PN1622240644 | 1  | HN496*199*9*14  | 3988    | 329.9   | 329.9   | 0 |  |
| 837 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3495 | 46B-131 | PN1622240645 | 1  | HN446*199*8*12  | 4290    | 313.32  | 313.32  | 0 |  |
| 838 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3496 | 46B-135 | PN1622240646 | 1  | HN496*199*9*14  | 9090    | 748.14  | 748.14  | 0 |  |
| 839 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3497 | 46B-136 | PN1622240647 | 1  | C20A            | 656.5   | 55.42   | 55.42   | 0 |  |
| 840 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3498 | 46B-143 | PN1622240648 | 1  | HN396*199*7*11  | 10989.5 | 648.52  | 648.52  | 0 |  |
| 841 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3499 | 46B-144 | PN1622240649 | 1  | BH600*250*10*14 | 5488    | 579.67  | 579.67  | 0 |  |
| 842 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3500 | 46B-145 | PN1622240650 | 1  | HN350*175*7*11  | 3990    | 208.02  | 208.02  | 0 |  |
| 843 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3501 | 46B-146 | PN1622240651 | 1  | HN300*150*6.5*9 | 6489.5  | 279.53  | 279.53  | 0 |  |
| 844 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3502 | 46B-148 | PN1622240652 | 1  | HN446*199*8*12  | 5000    | 378.88  | 378.88  | 0 |  |
| 845 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3503 | 46B-149 | PN1622240653 | 1  | HN446*199*8*12  | 6489.5  | 454.95  | 454.95  | 0 |  |
| 846 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3504 | 46B-150 | PN1622240654 | 1  | HN396*199*7*11  | 3290    | 214.37  | 214.37  | 0 |  |
| 847 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3505 | 46B-151 | PN1622240655 | 1  | HM482*300*11*15 | 5500    | 704.47  | 704.47  | 0 |  |
| 848 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3506 | 46B-152 | PN1622240656 | 1  | HN596*199*10*15 | 6491    | 656.05  | 656.05  | 0 |  |
| 849 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3507 | 46B-153 | PN1622240657 | 1  | BH500*250*10*14 | 6489.5  | 619.24  | 619.24  | 0 |  |
| 850 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3508 | 46B-155 | PN1622240658 | 1  | BH500*200*8*10  | 4815.5  | 314.52  | 314.52  | 0 |  |
| 851 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3509 | 46B-157 | PN1622240659 | 1  | BH500*250*10*14 | 6489.5  | 618.87  | 618.87  | 0 |  |
| 852 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3510 | 46B-159 | PN1622240660 | 1  | HM390*300*10*16 | 5500    | 619.7   | 619.7   | 0 |  |
| 853 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3511 | 46B-160 | PN1622240661 | 1  | C20A            | 656.5   | 19.07   | 19.07   | 0 |  |
| 854 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3512 | 46B-161 | PN1622240662 | 1  | C20A            | 4455    | 105.07  | 105.07  | 0 |  |
| 855 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3513 | 46B-162 | PN1622240663 | 1  | HM582*300*12*17 | 9391    | 1303.02 | 1303.02 | 0 |  |
| 856 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3514 | 46B-165 | PN1622240664 | 1  | BH500*200*8*10  | 4814    | 314.99  | 314.99  | 0 |  |
| 857 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3515 | 46B-167 | PN1622240665 | 1  | HM482*300*11*15 | 5500    | 704.47  | 704.47  | 0 |  |
| 858 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3516 | 46B-170 | PN1622240666 | 1  | C20A            | 4880    | 114.69  | 114.69  | 0 |  |
| 859 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3517 | 46B-174 | PN1622240667 | 1  | BH800*300*12*20 | 9487    | 1615.88 | 1615.88 | 0 |  |
| 860 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3518 | 46B-175 | PN1622240668 | 1  | HM482*300*11*15 | 5500    | 704.47  | 704.47  | 0 |  |
| 861 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3519 | 46B-176 | PN1622240669 | 1  | HN350*175*7*11  | 4139.5  | 234.55  | 234.55  | 0 |  |
| 862 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3520 | 46B-177 | PN1622240670 | 1  | HN350*175*7*11  | 6489.5  | 352.71  | 352.71  | 0 |  |
| 863 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3521 | 46B-178 | PN1622240671 | 1  | HN496*199*9*14  | 9090    | 748.14  | 748.14  | 0 |  |
| 864 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3522 | 46B-179 | PN1622240672 | 1  | C20A            | 1112    | 27.33   | 27.33   | 0 |  |
| 865 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3523 | 46B-183 | PN1622240673 | 1  | HN396*199*7*11  | 3988    | 238.53  | 238.53  | 0 |  |
| 866 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3524 | 46B-185 | PN1622240674 | 1  | C16A            | 1030.5  | 17.76   | 17.76   | 0 |  |
| 867 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3525 | 46B-186 | PN1622240675 | 1  | C16A            | 3605.5  | 62.13   | 62.13   | 0 |  |
| 868 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3526 | 46B-187 | PN1622240676 | 1  | C20A            | 1405    | 40.99   | 40.99   | 0 |  |
| 869 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3527 | 46B-188 | PN1622240677 | 2  | C20A            | 1405    | 40.99   | 81.99   | 0 |  |
| 870 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3528 | 46B-189 | PN1622240678 | 3  | C20A            | 1405    | 40.99   | 122.98  | 0 |  |
| 871 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3529 | 46B-190 | PN1622240679 | 1  | HM582*300*12*17 | 5489    | 829.18  | 829.18  | 0 |  |
| 872 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3530 | 46B-191 | PN1622240680 | 1  | HN596*199*10*15 | 5489    | 548.69  | 548.69  | 0 |  |
| 873 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3532 | 46B-193 | PN1622240682 | 1  | C20A            | 4392.5  | 100.16  | 100.16  | 0 |  |
| 874 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3533 | 46B-194 | PN1622240683 | 1  | C20A            | 1112    | 27.33   | 27.33   | 0 |  |
| 875 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3534 | 46B-195 | PN1622240684 | 1  | C20A            | 656.5   | 19.07   | 19.07   | 0 |  |
| 876 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3535 | 46B-196 | PN1622240685 | 2  | C20A            | 1112    | 27.33   | 54.65   | 0 |  |
| 877 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3536 | 46B-197 | PN1622240686 | 3  | C20A            | 1161.5  | 28.45   | 85.34   | 0 |  |
| 878 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3537 | 46B-198 | PN1622240687 | 3  | C20A            | 1161.5  | 28.45   | 85.34   | 0 |  |
| 879 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3538 | 46B-199 | PN1622240688 | 2  | I16             | 4030    | 82.67   | 165.33  | 0 |  |
| 880 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3539 | 46B-200 | PN1622240689 | 2  | I16             | 3605.5  | 73.96   | 147.92  | 0 |  |
| 881 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3540 | 46B-202 | PN1622240690 | 1  | BH500*250*10*14 | 9091    | 852.01  | 852.01  | 0 |  |
| 882 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3541 | 46B-203 | PN1622240691 | 1  | BH800*300*12*24 | 10990   | 2048.75 | 2048.75 | 0 |  |
| 883 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3542 | 46B-204 | PN1622240692 | 2  | C16A            | 834     | 14.37   | 28.74   | 0 |  |
| 884 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3543 | 46B-205 | PN1622240693 | 1  | HN596*199*10*15 | 9389    | 917.4   | 917.4   | 0 |  |
| 885 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3544 | 46B-206 | PN1622240694 | 1  | HN596*199*10*15 | 9389    | 917.4   | 917.4   | 0 |  |
| 886 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3545 | 46B-207 | PN1622240695 | 1  | HM582*300*12*17 | 5000    | 774.12  | 774.12  | 0 |  |
| 887 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3546 | 46B-211 | PN1622240696 | 1  | C16A            | 3442.3  | 59.31   | 59.31   | 0 |  |
| 888 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3547 | 46B-213 | PN1622240697 | 1  | HN300*150*6.5*9 | 1304    | 65      | 65      | 0 |  |
| 889 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3548 | 34P-1   | PN1622240698 | 2  | I16             | 1300    | 44.62   | 89.25   | 0 |  |
| 890 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3549 | 34P-2   | PN1622240699 | 1  | I16             | 2200    | 320.09  | 320.09  | 0 |  |
| 891 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3550 | 34P-3   | PN1622240700 | 1  | I16             | 2200    | 320.09  | 320.09  | 0 |  |
| 892 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3551 | 34P-4   | PN1622240701 | 1  | I16             | 1300    | 44.62   | 44.62   | 0 |  |
| 893 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3552 | 34P-5   | PN1622240702 | 1  | I16             | 2040    | 55.74   | 55.74   | 0 |  |
| 894 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3553 | 34P-6   | PN1622240703 | 1  | I16             | 2040    | 55.74   | 55.74   | 0 |  |
|     | TB2-SDC.VP101-00UHA-A-M1A-DTE-3554 | 34P-7   | PN1622240704 | 1  | I16             | 2040    | 55.74   | 55.74   | 0 |  |



|     |                                    |        |              |   |                 |        |        |        |   |  |
|-----|------------------------------------|--------|--------------|---|-----------------|--------|--------|--------|---|--|
| 896 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3555 | 34P-8  | PN1622240705 | 1 | I16             | 2040   | 55.74  | 55.74  | 0 |  |
| 897 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3556 | 34P-9  | PN1622240706 | 1 | I16             | 2040   | 58.99  | 58.99  | 0 |  |
| 898 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3557 | 34P-10 | PN1622240707 | 1 | I16             | 2040   | 58.99  | 58.99  | 0 |  |
| 899 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3558 | 34P-11 | PN1622240708 | 1 | I16             | 1300   | 44.62  | 44.62  | 0 |  |
| 900 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3559 | 34P-12 | PN1622240709 | 1 | I16             | 2040   | 59.79  | 59.79  | 0 |  |
| 901 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3560 | 34P-13 | PN1622240710 | 1 | I16             | 2040   | 59.79  | 59.79  | 0 |  |
| 902 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3561 | 34P-14 | PN1622240711 | 3 | I16             | 1440   | 39.38  | 118.15 | 0 |  |
| 903 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3562 | 34P-15 | PN1622240712 | 1 | I16             | 1440   | 39.38  | 39.38  | 0 |  |
| 904 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3563 | 37P-1  | PN1622240713 | 2 | HW150*150*7*10  | 4204   | 159.04 | 318.08 | 0 |  |
| 905 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3564 | 37P-2  | PN1622240714 | 2 | HW150*150*7*10  | 4218   | 159.49 | 318.97 | 0 |  |
| 906 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3565 | 37P-3  | PN1622240715 | 1 | HW150*150*7*10  | 4200   | 152.05 | 152.05 | 0 |  |
| 907 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3566 | 37P-4  | PN1622240716 | 1 | HW150*150*7*10  | 4204   | 152.17 | 152.17 | 0 |  |
| 908 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3568 | 37P-6  | PN1622240718 | 1 | BH500*300*12*20 | 4300   | 723.64 | 723.64 | 0 |  |
| 909 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3569 | 37P-7  | PN1622240719 | 1 | BH500*300*12*20 | 4300   | 723.64 | 723.64 | 0 |  |
| 910 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3570 | 39P-1  | PN1622240720 | 1 | I16             | 1640   | 49.96  | 49.96  | 0 |  |
| 911 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3571 | 39P-2  | PN1622240721 | 1 | I16             | 1640   | 49.98  | 49.98  | 0 |  |
| 912 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3572 | 39P-3  | PN1622240722 | 1 | I16             | 1620   | 53.21  | 53.21  | 0 |  |
| 913 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3573 | 39P-4  | PN1622240723 | 1 | I16             | 1640   | 49.84  | 49.84  | 0 |  |
| 914 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3574 | 39P-5  | PN1622240724 | 1 | I16             | 1640   | 49.96  | 49.96  | 0 |  |
| 915 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3575 | 39P-6  | PN1622240725 | 1 | I16             | 1640   | 49.98  | 49.98  | 0 |  |
| 916 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3576 | 39P-7  | PN1622240726 | 1 | I16             | 1620   | 53.21  | 53.21  | 0 |  |
| 917 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3577 | 39P-8  | PN1622240727 | 1 | I16             | 1640   | 49.84  | 49.84  | 0 |  |
| 918 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3578 | 39P-9  | PN1622240728 | 1 | I16             | 2200   | 59.02  | 59.02  | 0 |  |
| 919 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3579 | 39P-10 | PN1622240729 | 1 | I16             | 2000   | 53.83  | 53.83  | 0 |  |
| 920 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3580 | 39P-11 | PN1622240730 | 1 | I16             | 2200   | 59.02  | 59.02  | 0 |  |
| 921 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3581 | 39P-12 | PN1622240731 | 1 | I16             | 2000   | 53.83  | 53.83  | 0 |  |
| 922 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3582 | 39P-13 | PN1622240732 | 1 | I16             | 2200   | 59.02  | 59.02  | 0 |  |
| 923 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3583 | 39P-14 | PN1622240733 | 1 | I16             | 2200   | 59.02  | 59.02  | 0 |  |
| 924 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3584 | 40P-1  | PN1622240734 | 1 | I16             | 2620   | 74.49  | 74.49  | 0 |  |
| 925 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3585 | 40P-2  | PN1622240735 | 1 | I16             | 2620   | 74.49  | 74.49  | 0 |  |
| 926 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3586 | 40P-3  | PN1622240736 | 1 | I16             | 2620   | 77.58  | 77.58  | 0 |  |
| 927 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3587 | 40P-4  | PN1622240737 | 1 | I16             | 2620   | 77.58  | 77.58  | 0 |  |
| 928 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3588 | 40P-5  | PN1622240738 | 1 | I16             | 2640   | 68.64  | 68.64  | 0 |  |
| 929 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3589 | 40P-6  | PN1622240739 | 1 | I16             | 2640   | 68.64  | 68.64  | 0 |  |
| 930 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3590 | 40P-7  | PN1622240740 | 1 | I16             | 2640   | 70.78  | 70.78  | 0 |  |
| 931 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3591 | 40P-8  | PN1622240741 | 1 | I16             | 2640   | 70.78  | 70.78  | 0 |  |
| 932 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3592 | 41P-1  | PN1622240742 | 3 | HW100*100*6*8   | 2004   | 47.23  | 141.68 | 0 |  |
| 933 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3593 | 41P-2  | PN1622240743 | 1 | HW200*200*8*12  | 2000   | 136.3  | 136.3  | 0 |  |
| 934 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3594 | 41P-3  | PN1622240744 | 2 | HW250*250*9*14  | 2000   | 191    | 382    | 0 |  |
| 935 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3595 | 41P-4  | PN1622240745 | 1 | HW100*100*6*8   | 2000   | 46.22  | 46.22  | 0 |  |
| 936 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3596 | 41P-5  | PN1622240746 | 1 | HW100*100*6*8   | 2000   | 46.22  | 46.22  | 0 |  |
| 937 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3597 | 41P-6  | PN1622240747 | 3 | HW100*100*6*8   | 2004   | 45.91  | 137.73 | 0 |  |
| 938 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3598 | 42P-1  | PN1622240748 | 1 | L75*6           | 640    | 14.09  | 14.09  | 0 |  |
| 939 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3599 | 42P-2  | PN1622240749 | 1 | L75*6           | 640    | 14.09  | 14.09  | 0 |  |
| 940 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3600 | 42P-3  | PN1622240750 | 1 | HW100*100*6*8   | 4304   | 251.22 | 251.22 | 0 |  |
| 941 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3601 | 42P-4  | PN1622240751 | 1 | HW100*100*6*8   | 4304   | 251.22 | 251.22 | 0 |  |
| 942 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3602 | 42P-5  | PN1622240752 | 1 | HW100*100*6*8   | 4000   | 139.45 | 139.45 | 0 |  |
| 943 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3603 | 42P-6  | PN1622240753 | 1 | HW100*100*6*8   | 4000   | 139.45 | 139.45 | 0 |  |
| 944 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3604 | 42P-7  | PN1622240754 | 2 | L75*6           | 640    | 14.09  | 28.18  | 0 |  |
| 945 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3605 | 42P-8  | PN1622240755 | 1 | L75*6           | 640    | 14.09  | 14.09  | 0 |  |
| 946 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3606 | 43H-1  | PN1622240756 | 1 | L100*10         | 2590   | 126.26 | 126.26 | 0 |  |
| 947 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3607 | 43H-2  | PN1622240757 | 1 | L100*10         | 2540   | 125.22 | 125.22 | 0 |  |
| 948 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3608 | 43H-3  | PN1622240758 | 1 | L100*10         | 2630   | 128.43 | 128.43 | 0 |  |
| 949 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3609 | 43H-4  | PN1622240759 | 1 | L100*10         | 2590   | 127.71 | 127.71 | 0 |  |
| 950 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3610 | 44H-1  | PN1622240760 | 4 | C20A            | 1296.5 | 85.74  | 342.98 | 0 |  |
| 951 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3611 | 44H-2  | PN1622240761 | 2 | C20A            | 1274.5 | 79.58  | 159.16 | 0 |  |
| 952 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3612 | 44H-3  | PN1622240762 | 4 | C20A            | 1596.5 | 99.32  | 397.3  | 0 |  |
| 953 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3613 | 44H-4  | PN1622240763 | 1 | C20A            | 1606.6 | 97.65  | 97.65  | 0 |  |
| 954 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3614 | 44H-5  | PN1622240764 | 1 | C20A            | 1606.3 | 97.62  | 97.62  | 0 |  |
| 955 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3615 | 44H-6  | PN1622240765 | 1 | C20A            | 1296.5 | 85.57  | 85.57  | 0 |  |
| 956 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3616 | 44H-7  | PN1622240766 | 1 | C16A            | 890.5  | 22.06  | 22.06  | 0 |  |
| 957 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3617 | 44H-8  | PN1622240767 | 1 | C16A            | 1690.5 | 37.57  | 37.57  | 0 |  |
| 958 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3618 | 44H-9  | PN1622240768 | 1 | C16A            | 890.5  | 22.06  | 22.06  | 0 |  |
| 959 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3619 | 44H-10 | PN1622240769 | 1 | C16A            | 1690.5 | 37.57  | 37.57  | 0 |  |
| 960 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3620 | 44P-1  | PN1622240770 | 1 | HW250*250*9*14  | 1900   | 183.76 | 183.76 | 0 |  |
| 961 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3621 | 44P-2  | PN1622240771 | 1 | HW250*250*9*14  | 1900   | 183.76 | 183.76 | 0 |  |
| 962 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3622 | 44P-4  | PN1622240772 | 2 | HW100*100*6*8   | 1904   | 50.09  | 100.17 | 0 |  |
| 963 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3623 | 44P-5  | PN1622240773 | 1 | HW200*200*8*12  | 1800   | 126.24 | 126.24 | 0 |  |
|     | TB2-SDC.VP101-00UHA-A-M1A-DTE-3624 | 37HB-1 | PN1622240774 | 1 | HW300*300*10*15 | 6190.7 | 575.63 | 575.63 | 0 |  |



|      |                                    |         |              |   |                 |        |        |         |   |  |
|------|------------------------------------|---------|--------------|---|-----------------|--------|--------|---------|---|--|
| 965  | TB2-SDC.VP101-00UHA-A-M1A-DTE-3625 | 37HB-2  | PN1622240775 | 1 | HW300*300*10*15 | 2948.1 | 274.12 | 274.12  | 0 |  |
| 966  | TB2-SDC.VP101-00UHA-A-M1A-DTE-3626 | 37HB-3  | PN1622240776 | 1 | BH300*300*10*20 | 6295.5 | 721.52 | 721.52  | 0 |  |
| 967  | TB2-SDC.VP101-00UHA-A-M1A-DTE-3627 | 37HB-4  | PN1622240777 | 2 | HW200*200*8*12  | 5136.3 | 259.18 | 518.36  | 0 |  |
| 968  | TB2-SDC.VP101-00UHA-A-M1A-DTE-3628 | 37HB-5  | PN1622240778 | 2 | HW200*200*8*12  | 5027.9 | 253.71 | 507.41  | 0 |  |
| 969  | TB2-SDC.VP101-00UHA-A-M1A-DTE-3629 | 37HB-6  | PN1622240779 | 1 | HW200*200*8*12  | 5027.9 | 253.71 | 253.71  | 0 |  |
| 970  | TB2-SDC.VP101-00UHA-A-M1A-DTE-3630 | 37HB-7  | PN1622240780 | 2 | HW300*300*10*15 | 5981.6 | 556.19 | 1112.38 | 0 |  |
| 971  | TB2-SDC.VP101-00UHA-A-M1A-DTE-3631 | 37HB-8  | PN1622240781 | 2 | HW300*300*10*15 | 6221.4 | 578.49 | 1156.98 | 0 |  |
| 972  | TB2-SDC.VP101-00UHA-A-M1A-DTE-3632 | 37HB-9  | PN1622240782 | 1 | HW200*200*8*12  | 5396.7 | 272.32 | 272.32  | 0 |  |
| 973  | TB2-SDC.VP101-00UHA-A-M1A-DTE-3633 | 37HB-10 | PN1622240783 | 2 | HW200*200*8*12  | 5396.7 | 272.31 | 544.63  | 0 |  |
| 974  | TB2-SDC.VP101-00UHA-A-M1A-DTE-3634 | 37HB-11 | PN1622240784 | 2 | HW200*200*8*12  | 5502.9 | 277.67 | 555.35  | 0 |  |
| 975  | TB2-SDC.VP101-00UHA-A-M1A-DTE-3635 | 37HB-12 | PN1622240785 | 2 | HW200*200*8*12  | 5136.4 | 259.18 | 518.36  | 0 |  |
| 976  | TB2-SDC.VP101-00UHA-A-M1A-DTE-3636 | 37HB-13 | PN1622240786 | 2 | HW100*100*6*8   | 2039.4 | 34.56  | 69.13   | 0 |  |
| 977  | TB2-SDC.VP101-00UHA-A-M1A-DTE-3637 | 37HB-14 | PN1622240787 | 1 | HW300*300*10*15 | 6190.7 | 575.63 | 575.63  | 0 |  |
| 978  | TB2-SDC.VP101-00UHA-A-M1A-DTE-3638 | 37HB-15 | PN1622240788 | 1 | BH300*300*10*20 | 6295.5 | 721.52 | 721.52  | 0 |  |
| 979  | TB2-SDC.VP101-00UHA-A-M1A-DTE-3639 | 37HB-16 | PN1622240789 | 2 | HW100*100*6*8   | 2300.7 | 38.99  | 77.99   | 0 |  |
| 980  | TB2-SDC.VP101-00UHA-A-M1A-DTE-3640 | 37HB-17 | PN1622240790 | 2 | HW100*100*6*8   | 1412   | 23.93  | 47.86   | 0 |  |
| 981  | TB2-SDC.VP101-00UHA-A-M1A-DTE-3641 | 37HB-18 | PN1622240791 | 4 | HW200*200*8*12  | 5866.8 | 296.04 | 1184.15 | 0 |  |
| 982  | TB2-SDC.VP101-00UHA-A-M1A-DTE-3642 | 37HB-19 | PN1622240792 | 1 | HW300*300*10*15 | 3732.7 | 347.07 | 347.07  | 0 |  |
| 983  | TB2-SDC.VP101-00UHA-A-M1A-DTE-3643 | 37HB-20 | PN1622240793 | 1 | BH300*300*10*20 | 5576   | 639.07 | 639.07  | 0 |  |
| 984  | TB2-SDC.VP101-00UHA-A-M1A-DTE-3644 | 37HB-21 | PN1622240794 | 2 | HW200*200*8*12  | 5502.9 | 277.67 | 555.35  | 0 |  |
| 985  | TB2-SDC.VP101-00UHA-A-M1A-DTE-3645 | 37HB-22 | PN1622240795 | 1 | HW300*300*10*15 | 2946.5 | 273.98 | 273.98  | 0 |  |
| 986  | TB2-SDC.VP101-00UHA-A-M1A-DTE-3646 | 37HB-23 | PN1622240796 | 1 | HW200*200*8*12  | 5396.7 | 272.32 | 272.32  | 0 |  |
| 987  | TB2-SDC.VP101-00UHA-A-M1A-DTE-3647 | 37HB-24 | PN1622240797 | 2 | HW300*300*10*15 | 6104   | 567.57 | 1135.13 | 0 |  |
| 988  | TB2-SDC.VP101-00UHA-A-M1A-DTE-3648 | 37HB-25 | PN1622240798 | 2 | HW100*100*6*8   | 1729.5 | 29.31  | 58.62   | 0 |  |
| 989  | TB2-SDC.VP101-00UHA-A-M1A-DTE-3649 | 37HB-26 | PN1622240799 | 1 | HW300*300*10*15 | 3732.7 | 347.07 | 347.07  | 0 |  |
| 990  | TB2-SDC.VP101-00UHA-A-M1A-DTE-3650 | 37HB-27 | PN1622240800 | 1 | HW200*200*8*12  | 5027.9 | 253.71 | 253.71  | 0 |  |
| 991  | TB2-SDC.VP101-00UHA-A-M1A-DTE-3651 | 37HB-28 | PN1622240801 | 1 | BH300*300*10*20 | 5569.3 | 638.3  | 638.3   | 0 |  |
| 992  | TB2-SDC.VP101-00UHA-A-M1A-DTE-3652 | 37HB-29 | PN1622240802 | 1 | HW150*150*7*10  | 5042.8 | 160.52 | 160.52  | 0 |  |
| 993  | TB2-SDC.VP101-00UHA-A-M1A-DTE-3653 | 37ZS-1  | PN1622240803 | 1 | PL20*872        | 1259.5 | 166.72 | 166.72  | 0 |  |
| 994  | TB2-SDC.VP101-00UHA-A-M1A-DTE-3654 | 37ZS-2  | PN1622240804 | 1 | PL16*678        | 694    | 85.42  | 85.42   | 0 |  |
| 995  | TB2-SDC.VP101-00UHA-A-M1A-DTE-3655 | 37ZS-3  | PN1622240805 | 2 | PL16*712        | 773.8  | 87.77  | 175.63  | 0 |  |
| 996  | TB2-SDC.VP101-00UHA-A-M1A-DTE-3656 | 37ZS-4  | PN1622240806 | 1 | PL16*678        | 694    | 83.68  | 83.68   | 0 |  |
| 997  | TB2-SDC.VP101-00UHA-A-M1A-DTE-3657 | 37ZS-5  | PN1622240807 | 2 | PL14*492        | 695    | 52.72  | 105.44  | 0 |  |
| 998  | TB2-SDC.VP101-00UHA-A-M1A-DTE-3658 | 37ZS-6  | PN1622240808 | 2 | PL14*492        | 695    | 52.72  | 105.44  | 0 |  |
| 999  | TB2-SDC.VP101-00UHA-A-M1A-DTE-3659 | 37ZS-7  | PN1622240809 | 4 | PL16*710        | 726.1  | 87.57  | 350.27  | 0 |  |
| 1000 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3660 | 37ZS-8  | PN1622240810 | 2 | PL16*709        | 694    | 87.48  | 174.96  | 0 |  |
| 1001 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3661 | 37ZS-9  | PN1622240811 | 2 | PL14*555        | 564.3  | 41.54  | 83.07   | 0 |  |
| 1002 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3662 | 37ZS-10 | PN1622240812 | 1 | PL14*555        | 564.3  | 41.54  | 41.54   | 0 |  |
| 1003 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3663 | 37ZS-11 | PN1622240813 | 4 | PL14*470        | 517.4  | 35.38  | 141.54  | 0 |  |
| 1004 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3664 | 37ZS-12 | PN1622240814 | 4 | PL14*478        | 648.9  | 35.81  | 143.26  | 0 |  |
| 1005 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3665 | 37ZS-13 | PN1622240815 | 1 | PL16*679        | 695    | 85.5   | 85.5    | 0 |  |
| 1006 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3666 | 37ZS-14 | PN1622240816 | 1 | PL16*679        | 695    | 83.77  | 83.77   | 0 |  |
| 1007 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3667 | 37ZS-15 | PN1622240817 | 1 | PL20*872        | 1260.3 | 166.86 | 166.86  | 0 |  |
| 1008 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3668 | 37ZS-16 | PN1622240818 | 4 | PL14*461        | 489.3  | 37.44  | 149.76  | 0 |  |
| 1009 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3669 | 37ZS-17 | PN1622240819 | 2 | PL14*461        | 496.7  | 37.93  | 75.85   | 0 |  |
| 1010 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3670 | 37ZS-18 | PN1622240820 | 2 | PL14*461        | 533.4  | 37.92  | 75.85   | 0 |  |
| 1011 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3671 | 37ZS-19 | PN1622240821 | 2 | PL20*955        | 975    | 182.64 | 365.28  | 0 |  |
| 1012 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3672 | 37ZS-20 | PN1622240822 | 1 | PL16*824        | 840    | 126.19 | 126.19  | 0 |  |
| 1013 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3673 | 37ZS-21 | PN1622240823 | 2 | PL14*526        | 566.7  | 37.49  | 74.98   | 0 |  |
| 1014 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3674 | 37ZS-22 | PN1622240824 | 2 | PL14*451        | 464.6  | 35.26  | 70.52   | 0 |  |
| 1015 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3675 | 37ZS-23 | PN1622240825 | 1 | PL16*709        | 725    | 90.89  | 90.89   | 0 |  |
| 1016 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3676 | 37ZS-24 | PN1622240826 | 1 | PL16*824        | 840    | 126.19 | 126.19  | 0 |  |
| 1017 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3677 | 37ZS-25 | PN1622240827 | 1 | PL16*709        | 725    | 90.89  | 90.89   | 0 |  |
| 1018 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3678 | 37ZS-26 | PN1622240828 | 1 | PL16*709        | 725    | 118.76 | 118.76  | 0 |  |
| 1019 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3679 | 37ZS-27 | PN1622240829 | 4 | PL10*288        | 271    | 12.1   | 48.42   | 0 |  |
| 1020 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3680 | 37ZS-28 | PN1622240830 | 2 | PL10*260        | 296.3  | 12.73  | 25.46   | 0 |  |
| 1021 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3681 | 37ZS-29 | PN1622240831 | 2 | PL10*288        | 301.5  | 11.31  | 22.61   | 0 |  |
| 1022 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3682 | 37ZS-30 | PN1622240832 | 1 | PL10*282        | 368.6  | 16.71  | 16.71   | 0 |  |
| 1023 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3683 | 37ZS-31 | PN1622240833 | 1 | PL10*282        | 368.6  | 16.71  | 16.71   | 0 |  |
| 1024 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3684 | 37ZS-32 | PN1622240834 | 1 | PL10*277        | 307.3  | 16.81  | 16.81   | 0 |  |
| 1025 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3685 | 37ZS-33 | PN1622240835 | 1 | PL10*550        | 537.3  | 33.24  | 33.24   | 0 |  |
| 1026 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3686 | 37ZS-34 | PN1622240836 | 1 | PL16*709        | 725    | 118.76 | 118.76  | 0 |  |
| 1027 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3687 | 37ZS-35 | PN1622240837 | 1 | PL14*577        | 589.5  | 60.73  | 60.73   | 0 |  |
| 1028 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3688 | 37ZS-36 | PN1622240838 | 1 | PL14*577        | 589.5  | 60.73  | 60.73   | 0 |  |
| 1029 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3689 | 37ZS-37 | PN1622240839 | 1 | PL14*577        | 720    | 60.73  | 60.73   | 0 |  |
| 1030 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3690 | 37ZS-38 | PN1622240840 | 1 | PL14*577        | 720    | 60.73  | 60.73   | 0 |  |
| 1031 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3691 | 37ZS-39 | PN1622240841 | 1 | PL16*716        | 732.3  | 90.89  | 90.89   | 0 |  |
| 1032 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3692 | 37ZS-40 | PN1622240842 | 2 | PL16*654        | 669.7  | 82.77  | 165.53  | 0 |  |
|      | TB2-SDC.VP101-00UHA-A-M1A-DTE-3693 | 37ZS-41 | PN1622240843 | 2 | PL16*654        | 669.7  | 82.77  | 165.53  | 0 |  |



|      |                                    |         |              |   |                  |        |        |         |   |  |
|------|------------------------------------|---------|--------------|---|------------------|--------|--------|---------|---|--|
| 1034 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3694 | 37ZS-42 | PN1622240844 | 1 | PL10*550         | 560    | 33.18  | 33.18   | 0 |  |
| 1035 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3695 | 37ZS-43 | PN1622240845 | 2 | PL14*475         | 458.6  | 33.11  | 66.21   | 0 |  |
| 1036 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3696 | 37ZS-44 | PN1622240846 | 2 | PL14*484         | 465    | 33.51  | 67.02   | 0 |  |
| 1037 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3697 | 37ZS-45 | PN1622240847 | 2 | PL14*526         | 496.7  | 35.41  | 70.83   | 0 |  |
| 1038 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3698 | 37ZS-46 | PN1622240848 | 2 | PL14*516         | 489.2  | 34.98  | 69.95   | 0 |  |
| 1039 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3699 | 37ZS-47 | PN1622240849 | 1 | PL16*716         | 732.3  | 90.89  | 90.89   | 0 |  |
| 1040 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3700 | 37ZS-48 | PN1622240850 | 1 | PL10*277         | 307.3  | 16.81  | 16.81   | 0 |  |
| 1041 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3701 | 37ZS-49 | PN1622240851 | 1 | PL14*496         | 564.3  | 41.54  | 41.54   | 0 |  |
| 1042 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3702 | 41HB-1  | PN1622240852 | 2 | HW250*250*9*14   | 7295.1 | 527.88 | 1055.77 | 0 |  |
| 1043 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3703 | 41HB-2  | PN1622240853 | 2 | HW200*200*8*12   | 6094.9 | 307.55 | 615.1   | 0 |  |
| 1044 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3704 | 41HB-3  | PN1622240854 | 2 | HW300*300*10*15  | 7452.7 | 692.98 | 1385.96 | 0 |  |
| 1045 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3705 | 41HB-4  | PN1622240855 | 2 | HW300*300*10*15  | 6084.5 | 565.76 | 1131.52 | 0 |  |
| 1046 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3706 | 41HB-5  | PN1622240856 | 2 | HW300*300*10*15  | 6747   | 627.36 | 1254.72 | 0 |  |
| 1047 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3707 | 41HB-6  | PN1622240857 | 2 | HW300*300*10*15  | 6109.8 | 568.11 | 1136.22 | 0 |  |
| 1048 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3708 | 41HB-7  | PN1622240858 | 1 | HW200*200*8*12   | 5810.5 | 293.2  | 293.2   | 0 |  |
| 1049 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3709 | 41HB-8  | PN1622240859 | 4 | HW300*300*10*15  | 6226.5 | 578.96 | 2315.83 | 0 |  |
| 1050 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3710 | 41HB-9  | PN1622240860 | 1 | HW175*175*7.5*11 | 5654.7 | 234.14 | 234.14  | 0 |  |
| 1051 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3711 | 41HB-10 | PN1622240861 | 1 | HW200*200*8*12   | 5932.5 | 299.35 | 299.35  | 0 |  |
| 1052 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3712 | 41HB-11 | PN1622240862 | 1 | HW300*300*10*15  | 6105.3 | 567.69 | 567.69  | 0 |  |
| 1053 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3713 | 41HB-12 | PN1622240863 | 4 | HW200*200*8*12   | 5021   | 253.36 | 1013.43 | 0 |  |
| 1054 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3714 | 41HB-13 | PN1622240864 | 4 | HW200*200*8*12   | 5129.2 | 258.82 | 1035.28 | 0 |  |
| 1055 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3715 | 41HB-22 | PN1622240865 | 1 | HW200*200*8*12   | 5932.5 | 299.35 | 299.35  | 0 |  |
| 1056 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3716 | 41HB-23 | PN1622240866 | 2 | HW200*200*8*12   | 6071.5 | 306.37 | 612.74  | 0 |  |
| 1057 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3717 | 41HB-24 | PN1622240867 | 2 | HW200*200*8*12   | 6025   | 304.02 | 608.04  | 0 |  |
| 1058 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3718 | 41HB-25 | PN1622240868 | 2 | HW250*250*9*14   | 6955   | 503.27 | 1006.54 | 0 |  |
| 1059 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3719 | 41HB-30 | PN1622240869 | 2 | HW300*300*10*15  | 7346.3 | 683.08 | 1366.16 | 0 |  |
| 1060 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3720 | 41HB-32 | PN1622240870 | 2 | BH240*240*12*20  | 5224.9 | 492.19 | 984.38  | 0 |  |
| 1061 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3721 | 41HB-33 | PN1622240871 | 1 | HW300*300*10*15  | 6105.3 | 567.69 | 567.69  | 0 |  |
| 1062 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3722 | 41ZS-3  | PN1622240872 | 2 | PL16*676         | 958.3  | 84.83  | 169.66  | 0 |  |
| 1063 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3723 | 41ZS-4  | PN1622240873 | 2 | PL16*679         | 999.9  | 87.94  | 175.87  | 0 |  |
| 1064 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3724 | 41ZS-5  | PN1622240874 | 1 | PL16*679         | 999.9  | 87.94  | 87.94   | 0 |  |
| 1065 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3725 | 41ZS-8  | PN1622240875 | 2 | PL16*687         | 958.3  | 85.79  | 171.58  | 0 |  |
| 1066 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3726 | 41ZS-9  | PN1622240876 | 2 | PL16*679         | 999.9  | 87.94  | 175.87  | 0 |  |
| 1067 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3727 | 41ZS-10 | PN1622240877 | 1 | PL14*608         | 883.9  | 66.11  | 66.11   | 0 |  |
| 1068 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3728 | 41ZS-11 | PN1622240878 | 1 | PL14*500         | 674.1  | 54.85  | 54.85   | 0 |  |
| 1069 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3729 | 41ZS-12 | PN1622240879 | 1 | PL14*500         | 715.1  | 57.11  | 57.11   | 0 |  |
| 1070 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3730 | 41ZS-13 | PN1622240880 | 1 | PL14*561         | 717.4  | 61.92  | 61.92   | 0 |  |
| 1071 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3731 | 41ZS-14 | PN1622240881 | 2 | PL20*844         | 766.4  | 147.6  | 295.2   | 0 |  |
| 1072 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3732 | 41ZS-15 | PN1622240882 | 1 | PL16*712         | 1002.8 | 92     | 92      | 0 |  |
| 1073 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3733 | 41ZS-26 | PN1622240883 | 1 | PL16*679         | 999.9  | 87.94  | 87.94   | 0 |  |
| 1074 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3734 | 41ZS-27 | PN1622240884 | 2 | PL16*680         | 980    | 84.69  | 169.38  | 0 |  |
| 1075 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3735 | 41ZS-28 | PN1622240885 | 2 | PL16*774         | 790    | 97.29  | 194.58  | 0 |  |
| 1076 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3736 | 41ZS-29 | PN1622240886 | 2 | PL16*774         | 790    | 98.07  | 196.13  | 0 |  |
| 1077 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3737 | 41ZS-30 | PN1622240887 | 1 | PL16*712         | 1002.8 | 92     | 92      | 0 |  |
| 1078 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3738 | 41ZS-31 | PN1622240888 | 4 | PL16*677         | 693.4  | 84.96  | 339.82  | 0 |  |
| 1079 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3739 | 41ZS-32 | PN1622240889 | 2 | PL16*680         | 696    | 84.69  | 169.38  | 0 |  |
| 1080 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3740 | 41ZS-33 | PN1622240890 | 2 | PL16*680         | 696    | 84.69  | 169.38  | 0 |  |
| 1081 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3741 | 41ZS-34 | PN1622240891 | 1 | PL16*680         | 980    | 84.69  | 84.69   | 0 |  |
| 1082 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3742 | 41ZS-35 | PN1622240892 | 1 | PL14*606         | 882.8  | 68.78  | 68.78   | 0 |  |
| 1083 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3743 | 41ZS-36 | PN1622240893 | 2 | PL16*680         | 696    | 84.96  | 169.91  | 0 |  |
| 1084 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3744 | 41ZS-37 | PN1622240894 | 1 | PL16*680         | 980    | 84.69  | 84.69   | 0 |  |
| 1085 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3745 | 41ZS-38 | PN1622240895 | 2 | PL20*836         | 992    | 136.98 | 273.96  | 0 |  |
| 1086 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3746 | 41ZS-39 | PN1622240896 | 4 | PL14*478         | 489.8  | 42.13  | 168.52  | 0 |  |
| 1087 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3747 | 41ZS-40 | PN1622240897 | 4 | PL14*473         | 568.3  | 41.82  | 167.26  | 0 |  |
| 1088 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3748 | 41ZS-41 | PN1622240898 | 6 | PL14*473         | 563    | 41.31  | 247.86  | 0 |  |
| 1089 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3749 | 41ZS-42 | PN1622240899 | 1 | PL14*451         | 516.3  | 39.62  | 39.62   | 0 |  |
| 1090 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3750 | 41ZS-43 | PN1622240900 | 2 | PL14*429         | 441    | 35.8   | 71.6    | 0 |  |
| 1091 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3751 | 41ZS-44 | PN1622240901 | 1 | PL14*428         | 440.1  | 35.73  | 35.73   | 0 |  |
| 1092 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3752 | 41ZS-45 | PN1622240902 | 1 | PL14*476         | 488.4  | 38.99  | 38.99   | 0 |  |
| 1093 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3753 | 41ZS-46 | PN1622240903 | 1 | PL14*429         | 441    | 36.18  | 36.18   | 0 |  |
| 1094 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3754 | 41ZS-49 | PN1622240904 | 1 | PL14*428         | 440    | 48.23  | 48.23   | 0 |  |
| 1095 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3755 | 41ZS-50 | PN1622240905 | 1 | PL14*425         | 462.6  | 32.22  | 32.22   | 0 |  |
| 1096 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3756 | 41ZS-51 | PN1622240906 | 1 | PL14*483         | 495.1  | 52.03  | 52.03   | 0 |  |
| 1097 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3757 | 41ZS-56 | PN1622240907 | 1 | PL14*428         | 440.1  | 38.38  | 38.38   | 0 |  |
| 1098 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3758 | 41ZS-57 | PN1622240908 | 1 | PL14*428         | 440.1  | 38.38  | 38.38   | 0 |  |
| 1099 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3759 | 41ZS-58 | PN1622240909 | 1 | PL14*428         | 440    | 48.23  | 48.23   | 0 |  |
| 1100 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3760 | 41ZS-59 | PN1622240910 | 2 | PL14*429         | 441    | 35.8   | 71.6    | 0 |  |
| 1101 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3761 | 41ZS-60 | PN1622240911 | 1 | PL14*428         | 440.1  | 35.73  | 35.73   | 0 |  |
|      | TB2-SDC.VP101-00UHA-A-M1A-DTE-3762 | 41ZS-61 | PN1622240912 | 1 | PL14*476         | 488.4  | 38.99  | 38.99   | 0 |  |



|      |                                    |          |              |   |                |        |        |         |   |  |
|------|------------------------------------|----------|--------------|---|----------------|--------|--------|---------|---|--|
| 1103 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3763 | 41ZS-62  | PN1622240913 | 1 | PL14*429       | 441    | 36.18  | 36.18   | 0 |  |
| 1104 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3764 | 41ZS-63  | PN1622240914 | 1 | PL14*502       | 674.1  | 52.77  | 52.77   | 0 |  |
| 1105 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3765 | 41ZS-64  | PN1622240915 | 1 | PL14*502       | 715.1  | 55.03  | 55.03   | 0 |  |
| 1106 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3766 | 41ZS-65  | PN1622240916 | 1 | PL14*563       | 717.4  | 59.86  | 59.86   | 0 |  |
| 1107 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3767 | 41ZS-66  | PN1622240917 | 1 | PL14*451       | 516.3  | 39.62  | 39.62   | 0 |  |
| 1108 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3768 | 46HB-6   | PN1622240918 | 1 | HW200*200*8*12 | 5816.4 | 293.49 | 293.49  | 0 |  |
| 1109 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3769 | 46HB-8   | PN1622240919 | 2 | HW250*250*9*14 | 6281.4 | 454.53 | 909.06  | 0 |  |
| 1110 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3770 | 46HB-9   | PN1622240920 | 3 | HW250*250*9*14 | 6167.2 | 446.27 | 1338.8  | 0 |  |
| 1111 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3771 | 46HB-10  | PN1622240921 | 2 | HW250*250*9*14 | 6706.6 | 485.3  | 970.6   | 0 |  |
| 1112 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3772 | 46HB-11  | PN1622240922 | 2 | HW250*250*9*14 | 6817.7 | 493.34 | 986.67  | 0 |  |
| 1113 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3773 | 46HB-14  | PN1622240923 | 1 | HW250*250*9*14 | 6282.8 | 454.63 | 454.63  | 0 |  |
| 1114 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3774 | 46HB-16  | PN1622240924 | 4 | HW250*250*9*14 | 7128   | 515.79 | 2063.15 | 0 |  |
| 1115 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3775 | 46HB-17  | PN1622240925 | 4 | HW250*250*9*14 | 6114.1 | 442.42 | 1769.69 | 0 |  |
| 1116 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3776 | 46HB-21  | PN1622240926 | 2 | HW200*200*8*12 | 6504.8 | 328.23 | 656.46  | 0 |  |
| 1117 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3777 | 46HB-22  | PN1622240927 | 2 | HW200*200*8*12 | 7159.5 | 361.27 | 722.54  | 0 |  |
| 1118 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3778 | 46HB-37  | PN1622240928 | 1 | HW250*250*9*14 | 6167.2 | 446.27 | 446.27  | 0 |  |
| 1119 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3779 | 46HB-38  | PN1622240929 | 1 | HW250*250*9*14 | 6282.8 | 454.63 | 454.63  | 0 |  |
| 1120 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3780 | 46HB-40  | PN1622240930 | 1 | HW200*200*8*12 | 5816.4 | 293.49 | 293.49  | 0 |  |
| 1121 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3781 | 46HB-44  | PN1622240931 | 1 | HW200*200*8*12 | 6337.4 | 319.78 | 319.78  | 0 |  |
| 1122 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3782 | 46ZS-1   | PN1622240932 | 1 | PL14*416       | 449.4  | 31.32  | 31.32   | 0 |  |
| 1123 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3783 | 46ZS-21  | PN1622240933 | 1 | PL14*542       | 583.1  | 50.46  | 50.46   | 0 |  |
| 1124 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3784 | 46ZS-22  | PN1622240934 | 1 | PL14*532       | 602.9  | 51.29  | 51.29   | 0 |  |
| 1125 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3785 | 46ZS-23  | PN1622240935 | 2 | PL14*574       | 535.9  | 48.66  | 97.31   | 0 |  |
| 1126 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3786 | 46ZS-24  | PN1622240936 | 2 | PL14*664       | 589.6  | 52.28  | 104.55  | 0 |  |
| 1127 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3787 | 46ZS-25  | PN1622240937 | 1 | PL14*495       | 677.7  | 52.28  | 52.28   | 0 |  |
| 1128 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3788 | 46ZS-26  | PN1622240938 | 2 | PL14*542       | 555.6  | 47.18  | 94.36   | 0 |  |
| 1129 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3789 | 46ZS-27  | PN1622240939 | 2 | PL14*574       | 582.9  | 48.85  | 97.69   | 0 |  |
| 1130 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3790 | 46ZS-28  | PN1622240940 | 1 | PL14*524       | 582.8  | 48.7   | 48.7    | 0 |  |
| 1131 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3791 | 46ZS-29  | PN1622240941 | 3 | PL14*521       | 564.7  | 47.09  | 141.27  | 0 |  |
| 1132 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3792 | 46ZS-30  | PN1622240942 | 3 | PL14*523       | 555.7  | 46.58  | 139.74  | 0 |  |
| 1133 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3793 | 46ZS-31  | PN1622240943 | 1 | PL14*576       | 627.7  | 49.82  | 49.82   | 0 |  |
| 1134 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3794 | 46ZS-32  | PN1622240944 | 1 | PL14*517       | 586.6  | 48.22  | 48.22   | 0 |  |
| 1135 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3795 | 46ZS-33  | PN1622240945 | 1 | PL14*501       | 678.6  | 52.61  | 52.61   | 0 |  |
| 1136 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3796 | 46ZS-34  | PN1622240946 | 1 | PL14*521       | 564.7  | 47.09  | 47.09   | 0 |  |
| 1137 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3797 | 46ZS-35  | PN1622240947 | 1 | PL14*529       | 539.1  | 46.58  | 46.58   | 0 |  |
| 1138 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3798 | 46ZS-36  | PN1622240948 | 3 | PL14*662       | 622.7  | 52.61  | 157.83  | 0 |  |
| 1139 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3799 | 46ZS-37  | PN1622240949 | 1 | PL14*495       | 677.7  | 52.28  | 52.28   | 0 |  |
| 1140 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3800 | 46ZS-44  | PN1622240950 | 1 | PL14*428       | 478.5  | 32.29  | 32.29   | 0 |  |
| 1141 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3801 | 46ZS-46  | PN1622240951 | 1 | PL14*451       | 511.5  | 38.61  | 38.61   | 0 |  |
| 1142 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3802 | 46ZS-48  | PN1622240952 | 1 | PL14*556       | 516.7  | 38.85  | 38.85   | 0 |  |
| 1143 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3803 | 46ZS-49  | PN1622240953 | 1 | PL14*479       | 445.7  | 33.78  | 33.78   | 0 |  |
| 1144 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3804 | 46ZS-50  | PN1622240954 | 1 | PL14*501       | 652.3  | 51.28  | 51.28   | 0 |  |
| 1145 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3805 | 46ZS-51  | PN1622240955 | 1 | PL14*547       | 674.4  | 54.39  | 54.39   | 0 |  |
| 1146 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3806 | 46ZS-68  | PN1622240956 | 1 | PL14*416       | 449.4  | 31.03  | 31.03   | 0 |  |
| 1147 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3807 | 46ZS-72  | PN1622240957 | 1 | PL14*542       | 583.1  | 50.46  | 50.46   | 0 |  |
| 1148 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3808 | 46ZS-73  | PN1622240958 | 1 | PL14*532       | 602.9  | 51.29  | 51.29   | 0 |  |
| 1149 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3809 | 46ZS-74  | PN1622240959 | 1 | PL14*517       | 586.6  | 48.22  | 48.22   | 0 |  |
| 1150 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3810 | 46ZS-76  | PN1622240960 | 1 | PL14*501       | 652.3  | 51.28  | 51.28   | 0 |  |
| 1151 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3811 | 46ZS-77  | PN1622240961 | 1 | PL14*547       | 674.4  | 54.39  | 54.39   | 0 |  |
| 1152 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3812 | 46ZS-86  | PN1622240962 | 1 | PL14*576       | 627.7  | 49.82  | 49.82   | 0 |  |
| 1153 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3813 | 46ZS-87  | PN1622240963 | 1 | PL14*455       | 514.1  | 30.25  | 30.25   | 0 |  |
| 1154 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3814 | 46ZS-88  | PN1622240964 | 1 | PL14*451       | 511.5  | 38.61  | 38.61   | 0 |  |
| 1155 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3815 | 46ZS-104 | PN1622240965 | 1 | PL14*556       | 516.7  | 38.85  | 38.85   | 0 |  |
| 1156 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3816 | 46ZS-106 | PN1622240966 | 1 | PL14*479       | 445.7  | 33.78  | 33.78   | 0 |  |
| 1157 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3817 | 46ZS-107 | PN1622240967 | 1 | PL14*428       | 478.5  | 32.29  | 32.29   | 0 |  |
| 1158 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3818 | 46ZS-113 | PN1622240968 | 1 | PL14*525       | 582.8  | 48.76  | 48.76   | 0 |  |
| 1159 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3819 | 46ZS-115 | PN1622240969 | 1 | PL14*501       | 650.9  | 51.24  | 51.24   | 0 |  |
| 1160 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3820 | 46ZS-116 | PN1622240970 | 1 | PL14*501       | 651.3  | 51.23  | 51.23   | 0 |  |
| 1161 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3821 | 46ZS-117 | PN1622240971 | 1 | PL14*501       | 651.3  | 51.23  | 51.23   | 0 |  |
| 1162 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3822 | 46ZS-118 | PN1622240972 | 1 | PL14*426       | 459.9  | 39.94  | 39.94   | 0 |  |
| 1163 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3823 | 46ZS-123 | PN1622240973 | 1 | PL14*501       | 650.9  | 51.24  | 51.24   | 0 |  |
| 1164 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3824 | 46ZS-124 | PN1622240974 | 1 | PL14*426       | 459.9  | 39.93  | 39.93   | 0 |  |
| 1165 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3825 | 34BR-1   | PN1622240975 | 4 | L75*6          | 1823.9 | 12.6   | 50.38   | 0 |  |
| 1166 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3826 | 34BR-2   | PN1622240976 | 2 | L75*6          | 2777.2 | 19.18  | 38.36   | 0 |  |
| 1167 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3827 | 39BR-1   | PN1622240977 | 2 | L75*6          | 1921.7 | 13.27  | 26.54   | 0 |  |
| 1168 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3828 | 39BR-2   | PN1622240978 | 2 | L75*6          | 1933.1 | 13.35  | 26.7    | 0 |  |
| 1169 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3829 | 39BR-3   | PN1622240979 | 2 | L75*6          | 1678.9 | 11.59  | 23.19   | 0 |  |
| 1170 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3830 | 40BR-1   | PN1622240980 | 2 | L75*6          | 2215.5 | 15.3   | 30.6    | 0 |  |
|      | 2-SDC.VP101-00UHA-A-M1A-DTE-3831   | 40BR-2   | PN1622240981 | 2 | L75*6          | 2229.4 | 15.4   | 30.79   | 0 |  |



|      |                                    |         |              |   |                  |        |         |         |   |  |
|------|------------------------------------|---------|--------------|---|------------------|--------|---------|---------|---|--|
| 1172 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3832 | 40BR-3  | PN1622240982 | 2 | L75*6            | 3051.1 | 21.07   | 42.14   | 0 |  |
| 1173 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3059 | 4VB-175 | PN1622140398 | 1 | HW300*300*10*15  | 2994.7 | 331.35  | 331.35  | 0 |  |
| 1174 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3060 | 4VB-176 | PN1622140399 | 1 | HW300*300*10*15  | 2994.7 | 331.35  | 331.35  | 0 |  |
| 1175 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3061 | 4VB-177 | PN1622140400 | 1 | HW300*300*10*15  | 2992.1 | 331.1   | 331.1   | 0 |  |
| 1176 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3062 | 4VB-178 | PN1622140401 | 1 | HW300*300*10*15  | 2992.1 | 331.1   | 331.1   | 0 |  |
| 1177 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3063 | 4VB-179 | PN1622140402 | 2 | HW150*150*7*10   | 5022.8 | 185.14  | 370.27  | 0 |  |
| 1178 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3064 | 4VB-180 | PN1622140403 | 1 | HW150*150*7*10   | 5052   | 186.13  | 186.13  | 0 |  |
| 1179 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3065 | 4VB-181 | PN1622140404 | 2 | HW250*250*9*14   | 2748.4 | 238.67  | 477.35  | 0 |  |
| 1180 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3072 | 4VB-182 | PN1622140405 | 1 | HW250*250*9*14   | 2563.2 | 225.27  | 225.27  | 0 |  |
| 1181 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3073 | 4VB-183 | PN1622140406 | 2 | HW250*250*9*14   | 2927.8 | 251.66  | 503.32  | 0 |  |
| 1182 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3074 | 4VB-184 | PN1622140407 | 1 | HW250*250*9*14   | 2563.2 | 225.27  | 225.27  | 0 |  |
| 1183 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3833 | 4VB-185 | PN1622140408 | 1 | HW250*250*9*14   | 2563.2 | 225.27  | 225.27  | 0 |  |
| 1184 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3834 | 4VB-186 | PN1622140409 | 1 | HW300*300*10*15  | 3700   | 929.55  | 929.55  | 0 |  |
| 1185 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3835 | 4VB-187 | PN1622140410 | 1 | HW300*300*10*15  | 3700   | 929.55  | 929.55  | 0 |  |
| 1186 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3836 | 4VB-188 | PN1622140411 | 1 | HW300*300*10*15  | 3700   | 913.96  | 913.96  | 0 |  |
| 1187 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3837 | 4VB-195 | PN1622140412 | 1 | HW300*300*10*15  | 3700   | 926.28  | 926.28  | 0 |  |
| 1188 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3838 | 4VB-196 | PN1622140413 | 1 | HW300*300*10*15  | 3700   | 926.28  | 926.28  | 0 |  |
| 1189 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3839 | 4VB-197 | PN1622140414 | 1 | HW300*300*10*15  | 3700   | 910.69  | 910.69  | 0 |  |
| 1190 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3840 | 4VB-198 | PN1622140415 | 1 | HW250*250*9*14   | 2563.2 | 225.27  | 225.27  | 0 |  |
| 1191 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3841 | 35G-1   | PN1622240983 | 1 | HM582*300*12*17  | 13260  | 2420.57 | 2420.57 | 0 |  |
| 1192 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3842 | 35G-2   | PN1622240984 | 1 | HM582*300*12*17  | 13260  | 2420.58 | 2420.58 | 0 |  |
| 1193 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3843 | 37G-63  | PN1622240985 | 1 | HN596*199*10*15  | 3460   | 381.76  | 381.76  | 0 |  |
| 1194 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3844 | 37G-64  | PN1622240986 | 1 | BH500*150*8*8    | 1701.5 | 101.14  | 101.14  | 0 |  |
| 1195 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3845 | 37G-65  | PN1622240987 | 1 | BH500*150*8*8    | 2943   | 165.4   | 165.4   | 0 |  |
| 1196 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3846 | 37G-66  | PN1622240988 | 1 | BH500*150*8*8    | 1648   | 101.64  | 101.64  | 0 |  |
| 1197 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3847 | 37G-67  | PN1622240989 | 1 | BH500*150*8*8    | 923.5  | 62.84   | 62.84   | 0 |  |
| 1198 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3848 | 37G-68  | PN1622240990 | 1 | BH500*150*8*8    | 1133   | 76.29   | 76.29   | 0 |  |
| 1199 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3849 | 37G-69  | PN1622240991 | 1 | BH500*150*8*8    | 1133   | 76.29   | 76.29   | 0 |  |
| 1200 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3850 | 37B-65  | PN1622240992 | 1 | BH500*150*8*8    | 1354   | 83.56   | 83.56   | 0 |  |
| 1201 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3851 | 37B-107 | PN1622240993 | 1 | C16A             | 2355   | 40.58   | 40.58   | 0 |  |
| 1202 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3852 | 37B-108 | PN1622240994 | 3 | C16A             | 817.5  | 14.09   | 42.26   | 0 |  |
| 1203 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3853 | 37B-109 | PN1622240995 | 3 | C16A             | 817.5  | 14.09   | 42.26   | 0 |  |
| 1204 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3854 | 41B-5   | PN1622240996 | 1 | HW200*200*8*12   | 3178   | 183.68  | 183.68  | 0 |  |
| 1205 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3855 | 41B-6   | PN1622240997 | 1 | HW200*200*8*12   | 3178   | 183.68  | 183.68  | 0 |  |
| 1206 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3856 | 41B-8   | PN1622240998 | 1 | BH600*200*8*10   | 3185   | 232.83  | 232.83  | 0 |  |
| 1207 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3857 | 41B-13  | PN1622240999 | 1 | BH600*200*8*10   | 2838   | 232.58  | 232.58  | 0 |  |
| 1208 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3858 | 41B-36  | PN1622241000 | 4 | HN350*175*7*11   | 1785   | 97.31   | 389.24  | 0 |  |
| 1209 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3859 | 41B-45  | PN1622241001 | 2 | BH600*200*8*10   | 3185   | 232.83  | 465.65  | 0 |  |
| 1210 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3860 | 41B-56  | PN1622241002 | 1 | BH600*150*8*8    | 2838   | 185.15  | 185.15  | 0 |  |
| 1211 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3861 | 41B-59  | PN1622241003 | 1 | HN350*175*7*11   | 3138   | 167.97  | 167.97  | 0 |  |
| 1212 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3862 | 41B-60  | PN1622241004 | 1 | BH600*150*8*8    | 2838   | 185.15  | 185.15  | 0 |  |
| 1213 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3863 | 41B-63  | PN1622241005 | 1 | HN596*199*10*15  | 18488  | 1791.21 | 1791.21 | 0 |  |
| 1214 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3864 | 41B-64  | PN1622241006 | 1 | BH1000*300*14*24 | 12486  | 2824.54 | 2824.54 | 0 |  |
| 1215 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3865 | 41B-68  | PN1622241007 | 1 | BH600*200*8*10   | 2838   | 232.58  | 232.58  | 0 |  |
| 1216 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3866 | 41B-69  | PN1622241008 | 2 | BH600*200*8*10   | 3138   | 240.09  | 480.17  | 0 |  |
| 1217 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3867 | 41B-77  | PN1622241009 | 1 | BH600*150*8*8    | 2838   | 177.99  | 177.99  | 0 |  |
| 1218 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3868 | 41B-83  | PN1622241010 | 1 | BH1000*300*14*30 | 12486  | 3144.92 | 3144.92 | 0 |  |
| 1219 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3869 | 41B-85  | PN1622241011 | 1 | BH450*150*8*8    | 3138   | 166.3   | 166.3   | 0 |  |
| 1220 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3870 | 41B-86  | PN1622241012 | 1 | HN350*175*7*11   | 3138   | 167.97  | 167.97  | 0 |  |
| 1221 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3871 | 41B-87  | PN1622241013 | 1 | BH450*150*8*8    | 3138   | 166.29  | 166.29  | 0 |  |
| 1222 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3872 | 41B-88  | PN1622241014 | 1 | BH1000*300*14*24 | 12486  | 2824.54 | 2824.54 | 0 |  |
| 1223 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3873 | 41B-89  | PN1622241015 | 2 | BH1000*300*14*20 | 9984   | 2045.2  | 4090.41 | 0 |  |
| 1224 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3874 | 41B-91  | PN1622241016 | 4 | BH450*150*8*8    | 3489   | 158.24  | 632.96  | 0 |  |
| 1225 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3875 | 41B-92  | PN1622241017 | 1 | BH1000*300*14*20 | 9984   | 2045.2  | 2045.2  | 0 |  |
| 1226 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3876 | 41B-93  | PN1622241018 | 1 | BH1000*300*14*20 | 9984   | 2045.2  | 2045.2  | 0 |  |
| 1227 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3877 | 41B-112 | PN1622241019 | 1 | HW200*200*8*12   | 1200   | 66.92   | 66.92   | 0 |  |
| 1228 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3878 | 41B-134 | PN1622241020 | 1 | BH600*200*8*10   | 3185   | 232.83  | 232.83  | 0 |  |
| 1229 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3879 | 41B-135 | PN1622241021 | 1 | BH1000*300*14*30 | 12486  | 3144.92 | 3144.92 | 0 |  |
| 1230 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3880 | 41B-137 | PN1622241022 | 2 | C16A             | 780    | 13.44   | 26.88   | 0 |  |
| 1231 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3881 | 41B-140 | PN1622241023 | 1 | BH600*150*8*8    | 2838   | 177.99  | 177.99  | 0 |  |
| 1232 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3882 | 41B-144 | PN1622241024 | 1 | HW200*200*8*12   | 1200   | 66.92   | 66.92   | 0 |  |
| 1233 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3883 | 41B-146 | PN1622241025 | 2 | BH450*150*8*8    | 3489   | 158.24  | 316.48  | 0 |  |
| 1234 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3884 | 41PB-4  | PN1622241026 | 1 | HW200*200*8*12   | 3178   | 183.68  | 183.68  | 0 |  |
| 1235 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3885 | 41PB-5  | PN1622241027 | 1 | HW200*200*8*12   | 3178   | 183.68  | 183.68  | 0 |  |
| 1236 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3886 | 42PB-2  | PN1622241028 | 1 | C16A             | 1415   | 75.29   | 75.29   | 0 |  |
| 1237 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3887 | 46B-14  | PN1622241029 | 1 | HN596*199*10*15  | 1784   | 191.97  | 191.97  | 0 |  |
| 1238 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3888 | 46B-50  | PN1622241030 | 2 | HN596*199*10*15  | 13490  | 1301.42 | 2602.84 | 0 |  |
| 1239 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3889 | 46B-52  | PN1622241031 | 2 | HN350*175*7*11   | 6490.5 | 332.98  | 665.95  | 0 |  |
|      | 2-SDC.VP101-00UHA-A-M1A-DTE-3890   | 46B-53  | PN1622241032 | 1 | HM582*300*12*17  | 9990   | 1386.74 | 1386.74 | 0 |  |



|      |                                    |         |              |   |                  |         |         |          |   |  |
|------|------------------------------------|---------|--------------|---|------------------|---------|---------|----------|---|--|
| 1241 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3891 | 46B-55  | PN1622241033 | 1 | BH500*250*10*14  | 5488    | 517.91  | 517.91   | 0 |  |
| 1242 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3892 | 46B-56  | PN1622241034 | 1 | BH500*200*8*10   | 5489    | 351.55  | 351.55   | 0 |  |
| 1243 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3893 | 46B-57  | PN1622241035 | 2 | BH1000*150*12*10 | 1130    | 196.69  | 393.39   | 0 |  |
| 1244 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3894 | 46B-58  | PN1622241036 | 2 | BH600*150*8*8    | 2984    | 219.77  | 439.55   | 0 |  |
| 1245 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3895 | 46B-59  | PN1622241037 | 1 | BH600*150*8*8    | 2984    | 219.77  | 219.77   | 0 |  |
| 1246 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3896 | 46B-61  | PN1622241038 | 1 | BH900*350*14*24  | 18488   | 4319.88 | 4319.88  | 0 |  |
| 1247 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3897 | 46B-65  | PN1622241039 | 2 | BH700*250*12*16  | 18488   | 2354.85 | 4709.71  | 0 |  |
| 1248 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3898 | 46B-68  | PN1622241040 | 1 | HN496*199*9*14   | 6787    | 566.25  | 566.25   | 0 |  |
| 1249 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3899 | 46B-69  | PN1622241041 | 1 | HN596*199*10*15  | 1784    | 191.96  | 191.96   | 0 |  |
| 1250 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3900 | 46B-82  | PN1622241042 | 1 | BH500*250*10*14  | 3183    | 321.31  | 321.31   | 0 |  |
| 1251 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3901 | 46B-83  | PN1622241043 | 1 | HN596*199*10*15  | 1784    | 192.12  | 192.12   | 0 |  |
| 1252 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3902 | 46B-84  | PN1622241044 | 1 | BH500*250*10*14  | 6787    | 652.96  | 652.96   | 0 |  |
| 1253 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3903 | 46B-87  | PN1622241045 | 2 | BH600*150*8*8    | 1484    | 106.07  | 212.14   | 0 |  |
| 1254 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3904 | 46B-88  | PN1622241046 | 2 | BH600*150*8*8    | 1784    | 120.65  | 241.3    | 0 |  |
| 1255 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3905 | 46B-89  | PN1622241047 | 1 | BH500*150*8*8    | 3183    | 236.23  | 236.23   | 0 |  |
| 1256 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3906 | 46B-104 | PN1622241048 | 2 | BH700*150*10*10  | 1484    | 146.88  | 293.77   | 0 |  |
| 1257 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3907 | 46B-113 | PN1622241049 | 1 | BH1900*450*20*36 | 15180   | 9337.95 | 9337.95  | 0 |  |
| 1258 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3908 | 46B-114 | PN1622241050 | 1 | BH1900*500*20*36 | 15180   | 9776.94 | 9776.94  | 0 |  |
| 1259 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3909 | 46B-115 | PN1622241051 | 2 | HN350*175*7*11   | 6489.5  | 333.03  | 666.07   | 0 |  |
| 1260 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3910 | 46B-116 | PN1622241052 | 1 | HN350*175*7*11   | 6490.5  | 332.98  | 332.98   | 0 |  |
| 1261 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3911 | 46B-118 | PN1622241053 | 1 | HN350*175*7*11   | 3189.5  | 177.89  | 177.89   | 0 |  |
| 1262 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3912 | 46B-119 | PN1622241054 | 1 | BH600*150*8*8    | 1484    | 102.56  | 102.56   | 0 |  |
| 1263 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3913 | 46B-120 | PN1622241055 | 1 | BH600*150*8*8    | 1484    | 102.56  | 102.56   | 0 |  |
| 1264 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3914 | 46B-122 | PN1622241056 | 2 | BH700*150*10*10  | 1130    | 120.25  | 240.49   | 0 |  |
| 1265 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3915 | 46B-123 | PN1622241057 | 2 | BH700*150*10*10  | 1130    | 120.25  | 240.49   | 0 |  |
| 1266 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3916 | 46B-124 | PN1622241058 | 2 | BH700*150*10*10  | 1130    | 158.88  | 317.77   | 0 |  |
| 1267 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3917 | 46B-125 | PN1622241059 | 2 | BH1000*150*12*10 | 1130    | 195.07  | 390.14   | 0 |  |
| 1268 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3918 | 46B-126 | PN1622241060 | 2 | BH1800*400*20*36 | 13480   | 7128.26 | 14256.52 | 0 |  |
| 1269 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3919 | 46B-127 | PN1622241061 | 2 | BH1800*450*20*36 | 13480   | 7502.03 | 15004.05 | 0 |  |
| 1270 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3920 | 46B-128 | PN1622241062 | 2 | BH700*150*10*10  | 1130    | 158.88  | 317.77   | 0 |  |
| 1271 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3921 | 46B-132 | PN1622241063 | 1 | HN596*199*10*15  | 1784    | 192.12  | 192.12   | 0 |  |
| 1272 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3922 | 46B-133 | PN1622241064 | 2 | BH600*150*8*8    | 1784    | 120.65  | 241.3    | 0 |  |
| 1273 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3923 | 46B-134 | PN1622241065 | 2 | BH500*150*8*8    | 3183    | 186.33  | 372.66   | 0 |  |
| 1274 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3924 | 46B-137 | PN1622241066 | 4 | BH700*150*10*10  | 1130    | 158.88  | 635.54   | 0 |  |
| 1275 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3925 | 46B-138 | PN1622241067 | 1 | BH500*200*8*10   | 5489    | 365.57  | 365.57   | 0 |  |
| 1276 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3926 | 46B-139 | PN1622241068 | 1 | BH600*150*8*8    | 1484    | 106.07  | 106.07   | 0 |  |
| 1277 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3927 | 46B-140 | PN1622241069 | 2 | BH600*150*8*8    | 2984    | 219.53  | 439.06   | 0 |  |
| 1278 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3928 | 46B-141 | PN1622241070 | 1 | BH500*150*8*8    | 3183    | 186.33  | 186.33   | 0 |  |
| 1279 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3929 | 46B-142 | PN1622241071 | 2 | BH500*150*8*8    | 3183    | 186.33  | 372.66   | 0 |  |
| 1280 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3930 | 46B-147 | PN1622241072 | 1 | HM582*300*12*17  | 9990    | 1386.74 | 1386.74  | 0 |  |
| 1281 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3931 | 46B-154 | PN1622241073 | 1 | BH500*200*8*10   | 5489    | 351.55  | 351.55   | 0 |  |
| 1282 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3932 | 46B-156 | PN1622241074 | 1 | BH600*150*8*8    | 2984    | 219.77  | 219.77   | 0 |  |
| 1283 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3933 | 46B-158 | PN1622241075 | 1 | HN496*199*9*14   | 6787    | 566.25  | 566.25   | 0 |  |
| 1284 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3934 | 46B-163 | PN1622241076 | 1 | BH500*250*10*14  | 3183    | 321.31  | 321.31   | 0 |  |
| 1285 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3935 | 46B-164 | PN1622241077 | 1 | BH500*250*10*14  | 6787    | 652.96  | 652.96   | 0 |  |
| 1286 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3936 | 46B-166 | PN1622241078 | 1 | BH500*150*8*8    | 3183    | 236.23  | 236.23   | 0 |  |
| 1287 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3937 | 46B-168 | PN1622241079 | 1 | BH900*350*14*24  | 18488   | 4319.88 | 4319.88  | 0 |  |
| 1288 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3938 | 46B-169 | PN1622241080 | 1 | BH1900*450*20*36 | 15180   | 9337.95 | 9337.95  | 0 |  |
| 1289 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3939 | 46B-171 | PN1622241081 | 1 | HN350*175*7*11   | 6490.5  | 332.98  | 332.98   | 0 |  |
| 1290 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3940 | 46B-172 | PN1622241082 | 1 | BH600*150*8*8    | 1484    | 102.56  | 102.56   | 0 |  |
| 1291 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3941 | 46B-173 | PN1622241083 | 1 | BH1900*500*20*36 | 15180   | 9776.94 | 9776.94  | 0 |  |
| 1292 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3942 | 46B-180 | PN1622241084 | 1 | BH500*200*8*10   | 5489    | 365.57  | 365.57   | 0 |  |
| 1293 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3943 | 46B-181 | PN1622241085 | 1 | BH600*150*8*8    | 1484    | 106.07  | 106.07   | 0 |  |
| 1294 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3944 | 46B-182 | PN1622241086 | 1 | BH500*150*8*8    | 3183    | 186.33  | 186.33   | 0 |  |
| 1295 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3945 | 46B-184 | PN1622241087 | 1 | HN350*175*7*11   | 3189.5  | 177.89  | 177.89   | 0 |  |
| 1296 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3946 | 46B-201 | PN1622241088 | 1 | BH500*250*10*14  | 5488    | 580.16  | 580.16   | 0 |  |
| 1297 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3947 | 46B-208 | PN1622241089 | 1 | HN350*175*7*11   | 2889    | 162.87  | 162.87   | 0 |  |
| 1298 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3948 | 46B-209 | PN1622241090 | 1 | HN350*175*7*11   | 2889    | 162.87  | 162.87   | 0 |  |
| 1299 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3949 | 46B-210 | PN1622241091 | 2 | HM482*300*11*15  | 12390.5 | 1460.67 | 2921.35  | 0 |  |
| 1300 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3950 | 46B-212 | PN1622241092 | 1 | BH600*150*8*8    | 1484    | 102.56  | 102.56   | 0 |  |
| 1301 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3951 | 37P-8   | PN1622241093 | 2 | BH450*265*14*22  | 4800    | 739.13  | 1478.26  | 0 |  |
| 1302 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3952 | 42P-9   | PN1622241094 | 1 | L75*6            | 640     | 14.09   | 14.09    | 0 |  |
| 1303 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3953 | 42P-10  | PN1622241095 | 1 | dddd             | 640     | 14.09   | 14.09    | 0 |  |
| 1304 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3954 | 42P-11  | PN1622241096 | 1 | L75*6            | 640     | 14.09   | 14.09    | 0 |  |
| 1305 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3955 | 37HB-30 | PN1622241097 | 1 | HW175*175*7.5*11 | 770.2   | 31.09   | 31.09    | 0 |  |
| 1306 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3956 | 37HB-31 | PN1622241098 | 1 | HW175*175*7.5*11 | 1649.8  | 66.61   | 66.61    | 0 |  |
| 1307 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3957 | 37HB-32 | PN1622241099 | 1 | HW150*150*7*10   | 1282.3  | 40.82   | 40.82    | 0 |  |
| 1308 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3958 | 37HB-33 | PN1622241100 | 1 | HW150*150*7*10   | 1647.7  | 52.45   | 52.45    | 0 |  |
|      | 2-SDC.VP101-00UHA-A-M1A-DTE-3959   | 37HB-34 | PN1622241101 | 1 | HW150*150*7*10   | 1309.1  | 41.67   | 41.67    | 0 |  |



|      |                                    |         |              |   |                  |        |        |         |   |  |
|------|------------------------------------|---------|--------------|---|------------------|--------|--------|---------|---|--|
| 1310 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3960 | 37ZS-50 | PN1622241102 | 1 | PL12*828         | 840    | 76.49  | 76.49   | 0 |  |
| 1311 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3961 | 37ZS-51 | PN1622241103 | 1 | PL12*375         | 391.5  | 21.9   | 21.9    | 0 |  |
| 1312 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3962 | 37ZS-52 | PN1622241104 | 2 | PL12*466         | 542.8  | 32.25  | 64.5    | 0 |  |
| 1313 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3963 | 37ZS-53 | PN1622241105 | 1 | PL12*468         | 542.1  | 32.38  | 32.38   | 0 |  |
| 1314 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3964 | 37ZS-54 | PN1622241106 | 1 | PL12*618         | 630    | 50.58  | 50.58   | 0 |  |
| 1315 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3965 | 37ZS-55 | PN1622241107 | 1 | PL12*387         | 541    | 28.3   | 28.3    | 0 |  |
| 1316 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3966 | 37ZS-56 | PN1622241108 | 1 | PL12*754         | 741.1  | 60.8   | 60.8    | 0 |  |
| 1317 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3967 | 37ZS-57 | PN1622241109 | 1 | PL12*415         | 406.6  | 23.38  | 23.38   | 0 |  |
| 1318 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3968 | 37ZS-58 | PN1622241110 | 1 | PL12*409         | 589.3  | 25.81  | 25.81   | 0 |  |
| 1319 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3969 | 37ZS-59 | PN1622241111 | 1 | PL10*625         | 635    | 39.63  | 39.63   | 0 |  |
| 1320 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3970 | 37ZS-60 | PN1622241112 | 1 | PL10*625         | 635    | 38.33  | 38.33   | 0 |  |
| 1321 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3971 | 41HB-14 | PN1622241113 | 2 | HW175*175*7.5*11 | 5186.1 | 206.65 | 413.31  | 0 |  |
| 1322 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3972 | 41HB-15 | PN1622241114 | 2 | HW150*150*7*10   | 2775.7 | 88.35  | 176.71  | 0 |  |
| 1323 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3973 | 41HB-16 | PN1622241115 | 4 | HW150*150*7*10   | 3419.9 | 108.86 | 435.45  | 0 |  |
| 1324 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3974 | 41HB-17 | PN1622241116 | 1 | HW175*175*7.5*11 | 4104.6 | 171.55 | 171.55  | 0 |  |
| 1325 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3975 | 41HB-18 | PN1622241117 | 2 | HW175*175*7.5*11 | 4118.6 | 172.12 | 344.24  | 0 |  |
| 1326 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3976 | 41HB-19 | PN1622241118 | 3 | HW175*175*7.5*11 | 4104.6 | 171.55 | 514.66  | 0 |  |
| 1327 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3977 | 41HB-21 | PN1622241119 | 2 | HW175*175*7.5*11 | 5265.6 | 218.43 | 436.85  | 0 |  |
| 1328 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3978 | 41HB-29 | PN1622241120 | 2 | HW175*175*7.5*11 | 3884.2 | 162.65 | 325.31  | 0 |  |
| 1329 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3979 | 41HB-31 | PN1622241121 | 4 | HW175*175*7.5*11 | 4100.3 | 171.38 | 685.52  | 0 |  |
| 1330 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3980 | 41ZS-1  | PN1622241122 | 1 | PL14*467         | 440    | 33.84  | 33.84   | 0 |  |
| 1331 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3981 | 41ZS-2  | PN1622241123 | 2 | PL12*458         | 468    | 34.18  | 68.36   | 0 |  |
| 1332 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3982 | 41ZS-6  | PN1622241124 | 2 | PL14*429         | 441    | 32.71  | 65.42   | 0 |  |
| 1333 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3983 | 41ZS-7  | PN1622241125 | 1 | PL14*476         | 488.4  | 34.44  | 34.44   | 0 |  |
| 1334 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3984 | 41ZS-16 | PN1622241126 | 4 | PL14*477         | 489.3  | 34.48  | 137.94  | 0 |  |
| 1335 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3985 | 41ZS-17 | PN1622241127 | 5 | PL14*449         | 461.3  | 33.06  | 165.3   | 0 |  |
| 1336 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3986 | 41ZS-18 | PN1622241128 | 1 | PL14*477         | 489.3  | 34.38  | 34.38   | 0 |  |
| 1337 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3987 | 41ZS-19 | PN1622241129 | 2 | PL14*477         | 489.3  | 34.48  | 68.97   | 0 |  |
| 1338 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3988 | 41ZS-20 | PN1622241130 | 2 | PL14*429         | 441    | 33.24  | 66.47   | 0 |  |
| 1339 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3989 | 41ZS-21 | PN1622241131 | 1 | PL14*476         | 488.4  | 34.44  | 34.44   | 0 |  |
| 1340 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3990 | 41ZS-22 | PN1622241132 | 3 | PL14*449         | 461.3  | 33.06  | 99.18   | 0 |  |
| 1341 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3991 | 41ZS-23 | PN1622241133 | 1 | PL14*477         | 489.3  | 34.38  | 34.38   | 0 |  |
| 1342 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3992 | 41ZS-24 | PN1622241134 | 1 | PL14*467         | 440    | 33.84  | 33.84   | 0 |  |
| 1343 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3993 | 41ZS-25 | PN1622241135 | 2 | PL12*458         | 468    | 34.18  | 68.36   | 0 |  |
| 1344 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3994 | 41ZS-47 | PN1622241136 | 1 | PL14*477         | 489.3  | 34.38  | 34.38   | 0 |  |
| 1345 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3995 | 41ZS-48 | PN1622241137 | 1 | PL14*477         | 489.3  | 34.38  | 34.38   | 0 |  |
| 1346 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3996 | 41ZS-52 | PN1622241138 | 2 | PL12*458         | 468    | 34.18  | 68.35   | 0 |  |
| 1347 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3997 | 41ZS-53 | PN1622241139 | 2 | PL12*458         | 468    | 34.18  | 68.35   | 0 |  |
| 1348 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3998 | 41ZS-54 | PN1622241140 | 1 | PL12*458         | 468    | 34.05  | 34.05   | 0 |  |
| 1349 | TB2-SDC.VP101-00UHA-A-M1A-DTE-3999 | 41ZS-55 | PN1622241141 | 1 | PL12*458         | 468    | 34.05  | 34.05   | 0 |  |
| 1350 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4000 | 41ZS-67 | PN1622241142 | 2 | PL12*448         | 420.6  | 25.83  | 51.65   | 0 |  |
| 1351 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4001 | 41ZS-68 | PN1622241143 | 1 | PL12*429         | 441    | 29.73  | 29.73   | 0 |  |
| 1352 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4002 | 41ZS-69 | PN1622241144 | 1 | PL12*429         | 441    | 29.73  | 29.73   | 0 |  |
| 1353 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4003 | 41ZS-70 | PN1622241145 | 4 | PL12*446         | 420.6  | 25.75  | 103     | 0 |  |
| 1354 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4004 | 41ZS-71 | PN1622241146 | 2 | PL12*379         | 392.6  | 27.87  | 55.74   | 0 |  |
| 1355 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4005 | 41ZS-72 | PN1622241147 | 2 | PL12*425         | 447.6  | 33.86  | 67.72   | 0 |  |
| 1356 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4006 | 46HB-1  | PN1622241148 | 2 | HW150*150*7*10   | 2499.5 | 79.56  | 159.13  | 0 |  |
| 1357 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4007 | 46HB-2  | PN1622241149 | 2 | HW150*150*7*10   | 1313.4 | 41.81  | 83.62   | 0 |  |
| 1358 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4008 | 46HB-3  | PN1622241150 | 2 | HW150*150*7*10   | 2294.4 | 73.03  | 146.07  | 0 |  |
| 1359 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4009 | 46HB-4  | PN1622241151 | 4 | HW150*150*7*10   | 2181.2 | 69.43  | 277.73  | 0 |  |
| 1360 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4010 | 46HB-5  | PN1622241152 | 2 | HW150*150*7*10   | 1391   | 44.28  | 88.56   | 0 |  |
| 1361 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4011 | 46HB-7  | PN1622241153 | 2 | HW150*150*7*10   | 1399.2 | 44.54  | 89.08   | 0 |  |
| 1362 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4012 | 46HB-12 | PN1622241154 | 2 | HW250*250*9*14   | 1190.1 | 86.12  | 172.24  | 0 |  |
| 1363 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4013 | 46HB-13 | PN1622241155 | 2 | HW150*150*7*10   | 1402.6 | 44.65  | 89.29   | 0 |  |
| 1364 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4014 | 46HB-15 | PN1622241156 | 4 | HW250*250*9*14   | 4021.9 | 291.03 | 1164.13 | 0 |  |
| 1365 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4015 | 46HB-18 | PN1622241157 | 1 | HW200*200*8*12   | 5823.4 | 293.85 | 293.85  | 0 |  |
| 1366 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4016 | 46HB-19 | PN1622241158 | 2 | HW200*200*8*12   | 6651.9 | 335.65 | 671.3   | 0 |  |
| 1367 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4017 | 46HB-20 | PN1622241159 | 1 | HW200*200*8*12   | 4125.1 | 208.15 | 208.15  | 0 |  |
| 1368 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4018 | 46HB-23 | PN1622241160 | 2 | HW250*250*9*14   | 3980.1 | 288    | 576.01  | 0 |  |
| 1369 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4019 | 46HB-24 | PN1622241161 | 2 | HW200*200*8*12   | 6752.9 | 340.75 | 681.5   | 0 |  |
| 1370 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4020 | 46HB-25 | PN1622241162 | 1 | HW200*200*8*12   | 5823.4 | 293.85 | 293.85  | 0 |  |
| 1371 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4021 | 46HB-26 | PN1622241163 | 1 | HW200*200*8*12   | 7013.8 | 353.92 | 353.92  | 0 |  |
| 1372 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4022 | 46HB-27 | PN1622241164 | 1 | HW200*200*8*12   | 7011.7 | 353.81 | 353.81  | 0 |  |
| 1373 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4023 | 46HB-28 | PN1622241165 | 1 | HW150*150*7*10   | 1472.1 | 46.86  | 46.86   | 0 |  |
| 1374 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4024 | 46HB-29 | PN1622241166 | 1 | HW150*150*7*10   | 1472.1 | 46.86  | 46.86   | 0 |  |
| 1375 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4025 | 46HB-30 | PN1622241167 | 5 | HW250*250*9*14   | 4862.7 | 351.87 | 1759.37 | 0 |  |
| 1376 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4026 | 46HB-31 | PN1622241168 | 2 | HW200*200*8*12   | 6553.7 | 330.7  | 661.4   | 0 |  |
| 1377 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4027 | 46HB-32 | PN1622241169 | 1 | HW250*250*9*14   | 4862.7 | 351.87 | 351.87  | 0 |  |
|      | TB2-SDC.VP101-00UHA-A-M1A-DTE-4028 | 46HB-33 | PN1622241170 | 2 | HW250*250*9*14   | 4862.7 | 351.87 | 703.75  | 0 |  |



|      |                                    |         |              |   |                |        |        |        |   |  |
|------|------------------------------------|---------|--------------|---|----------------|--------|--------|--------|---|--|
| 1379 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4029 | 46HB-34 | PN1622241171 | 2 | HW200*200*8*12 | 4036.4 | 203.68 | 407.36 | 0 |  |
| 1380 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4030 | 46HB-36 | PN1622241172 | 2 | HW250*250*9*14 | 3835.7 | 277.56 | 555.11 | 0 |  |
| 1381 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4031 | 46HB-39 | PN1622241173 | 1 | HW200*200*8*12 | 4125.1 | 208.15 | 208.15 | 0 |  |
| 1382 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4032 | 46HB-41 | PN1622241174 | 1 | HW200*200*8*12 | 7013.8 | 353.92 | 353.92 | 0 |  |
| 1383 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4033 | 46HB-42 | PN1622241175 | 1 | HW200*200*8*12 | 7011.7 | 353.81 | 353.81 | 0 |  |
| 1384 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4034 | 46ZS-2  | PN1622241176 | 1 | PL12*421       | 734.9  | 41.48  | 41.48  | 0 |  |
| 1385 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4035 | 46ZS-3  | PN1622241177 | 1 | PL12*380       | 554.1  | 27.63  | 27.63  | 0 |  |
| 1386 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4036 | 46ZS-4  | PN1622241178 | 1 | PL12*348       | 697.5  | 31.22  | 31.22  | 0 |  |
| 1387 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4037 | 46ZS-5  | PN1622241179 | 1 | PL12*507       | 695.7  | 42.52  | 42.52  | 0 |  |
| 1388 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4038 | 46ZS-6  | PN1622241180 | 1 | PL12*528       | 540    | 38.99  | 38.99  | 0 |  |
| 1389 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4039 | 46ZS-7  | PN1622241181 | 1 | PL12*477       | 538.9  | 26.46  | 26.46  | 0 |  |
| 1390 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4040 | 46ZS-8  | PN1622241182 | 1 | PL12*548       | 560    | 47.4   | 47.4   | 0 |  |
| 1391 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4041 | 46ZS-9  | PN1622241183 | 1 | PL12*403       | 479    | 26.31  | 26.31  | 0 |  |
| 1392 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4042 | 46ZS-10 | PN1622241184 | 1 | PL12*421       | 648.3  | 43.11  | 43.11  | 0 |  |
| 1393 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4043 | 46ZS-11 | PN1622241185 | 1 | PL12*342       | 738.2  | 32.21  | 32.21  | 0 |  |
| 1394 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4044 | 46ZS-12 | PN1622241186 | 1 | PL12*379       | 393.9  | 27.56  | 27.56  | 0 |  |
| 1395 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4045 | 46ZS-13 | PN1622241187 | 1 | PL12*404       | 417.6  | 31.5   | 31.5   | 0 |  |
| 1396 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4046 | 46ZS-14 | PN1622241188 | 1 | PL12*465       | 520    | 34.62  | 34.62  | 0 |  |
| 1397 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4047 | 46ZS-15 | PN1622241189 | 1 | PL12*403       | 483.9  | 27.85  | 27.85  | 0 |  |
| 1398 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4048 | 46ZS-16 | PN1622241190 | 6 | PL14*494       | 686.3  | 52.69  | 316.13 | 0 |  |
| 1399 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4049 | 46ZS-17 | PN1622241191 | 2 | PL14*494       | 621.5  | 52.69  | 105.38 | 0 |  |
| 1400 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4050 | 46ZS-18 | PN1622241192 | 1 | PL14*500       | 680.9  | 52.67  | 52.67  | 0 |  |
| 1401 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4051 | 46ZS-19 | PN1622241193 | 3 | PL14*494       | 682.5  | 52.35  | 157.06 | 0 |  |
| 1402 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4052 | 46ZS-20 | PN1622241194 | 1 | PL14*494       | 682.5  | 52.35  | 52.35  | 0 |  |
| 1403 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4053 | 46ZS-38 | PN1622241195 | 1 | PL14*474       | 458.1  | 33.6   | 33.6   | 0 |  |
| 1404 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4054 | 46ZS-39 | PN1622241196 | 1 | PL14*457       | 437.6  | 32.82  | 32.82  | 0 |  |
| 1405 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4055 | 46ZS-40 | PN1622241197 | 2 | PL14*447       | 453.7  | 32.3   | 64.62  | 0 |  |
| 1406 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4056 | 46ZS-41 | PN1622241198 | 1 | PL14*448       | 502.8  | 34.29  | 34.29  | 0 |  |
| 1407 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4057 | 46ZS-42 | PN1622241199 | 1 | PL14*440       | 453.8  | 32.92  | 32.92  | 0 |  |
| 1408 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4058 | 46ZS-43 | PN1622241200 | 1 | PL14*475       | 443    | 33.65  | 33.65  | 0 |  |
| 1409 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4059 | 46ZS-45 | PN1622241201 | 1 | PL14*429       | 488.8  | 33.21  | 33.21  | 0 |  |
| 1410 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4060 | 46ZS-47 | PN1622241202 | 1 | PL14*441       | 453.4  | 31.45  | 31.45  | 0 |  |
| 1411 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4061 | 46ZS-52 | PN1622241203 | 1 | PL14*716       | 847    | 73.07  | 73.07  | 0 |  |
| 1412 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4062 | 46ZS-53 | PN1622241204 | 1 | PL14*522       | 558.1  | 46.71  | 46.71  | 0 |  |
| 1413 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4063 | 46ZS-54 | PN1622241205 | 1 | PL14*523       | 554.1  | 46.99  | 46.99  | 0 |  |
| 1414 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4064 | 46ZS-55 | PN1622241206 | 1 | PL14*522       | 556.7  | 46.6   | 46.6   | 0 |  |
| 1415 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4065 | 46ZS-56 | PN1622241207 | 1 | PL14*523       | 551.4  | 46.33  | 46.33  | 0 |  |
| 1416 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4066 | 46ZS-57 | PN1622241208 | 2 | PL14*552       | 565.8  | 48.39  | 96.78  | 0 |  |
| 1417 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4067 | 46ZS-58 | PN1622241209 | 1 | PL14*512       | 616.1  | 49.92  | 49.92  | 0 |  |
| 1418 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4068 | 46ZS-59 | PN1622241210 | 1 | PL14*500       | 682.9  | 52.78  | 52.78  | 0 |  |
| 1419 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4069 | 46ZS-60 | PN1622241211 | 1 | PL14*531       | 538.8  | 46.68  | 46.68  | 0 |  |
| 1420 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4070 | 46ZS-61 | PN1622241212 | 1 | PL14*525       | 564.2  | 46.33  | 46.33  | 0 |  |
| 1421 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4071 | 46ZS-62 | PN1622241213 | 1 | PL14*548       | 548    | 47.42  | 47.42  | 0 |  |
| 1422 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4072 | 46ZS-63 | PN1622241214 | 1 | PL14*427       | 630.8  | 38.99  | 38.99  | 0 |  |
| 1423 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4073 | 46ZS-64 | PN1622241215 | 1 | PL14*412       | 468.8  | 34.02  | 34.02  | 0 |  |
| 1424 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4074 | 46ZS-65 | PN1622241216 | 1 | PL14*431       | 520.8  | 33.26  | 33.26  | 0 |  |
| 1425 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4075 | 46ZS-66 | PN1622241217 | 1 | PL14*421       | 441.6  | 31.12  | 31.12  | 0 |  |
| 1426 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4076 | 46ZS-67 | PN1622241218 | 1 | PL14*429       | 433.3  | 30.96  | 30.96  | 0 |  |
| 1427 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4077 | 46ZS-69 | PN1622241219 | 1 | PL12*421       | 734.9  | 41.48  | 41.48  | 0 |  |
| 1428 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4078 | 46ZS-70 | PN1622241220 | 1 | PL12*380       | 554.1  | 27.63  | 27.63  | 0 |  |
| 1429 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4079 | 46ZS-71 | PN1622241221 | 1 | PL12*348       | 697.5  | 31.22  | 31.22  | 0 |  |
| 1430 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4080 | 46ZS-75 | PN1622241222 | 1 | PL14*500       | 682.9  | 52.78  | 52.78  | 0 |  |
| 1431 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4081 | 46ZS-78 | PN1622241223 | 1 | PL14*716       | 847    | 73.07  | 73.07  | 0 |  |
| 1432 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4082 | 46ZS-79 | PN1622241224 | 1 | PL14*531       | 538.8  | 46.68  | 46.68  | 0 |  |
| 1433 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4083 | 46ZS-80 | PN1622241225 | 1 | PL14*523       | 554.1  | 46.99  | 46.99  | 0 |  |
| 1434 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4084 | 46ZS-81 | PN1622241226 | 1 | PL14*522       | 556.7  | 46.6   | 46.6   | 0 |  |
| 1435 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4085 | 46ZS-82 | PN1622241227 | 2 | PL14*523       | 551.4  | 46.33  | 92.66  | 0 |  |
| 1436 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4086 | 46ZS-83 | PN1622241228 | 1 | PL14*548       | 548    | 47.42  | 47.42  | 0 |  |
| 1437 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4087 | 46ZS-84 | PN1622241229 | 1 | PL14*512       | 616.1  | 49.92  | 49.92  | 0 |  |
| 1438 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4088 | 46ZS-85 | PN1622241230 | 1 | PL12*465       | 520    | 34.62  | 34.62  | 0 |  |
| 1439 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4089 | 46ZS-89 | PN1622241231 | 1 | PL14*427       | 630.8  | 38.99  | 38.99  | 0 |  |
| 1440 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4090 | 46ZS-90 | PN1622241232 | 1 | PL12*404       | 417.6  | 31.5   | 31.5   | 0 |  |
| 1441 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4091 | 46ZS-91 | PN1622241233 | 1 | PL12*421       | 648.3  | 43.11  | 43.11  | 0 |  |
| 1442 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4092 | 46ZS-92 | PN1622241234 | 1 | PL12*528       | 540    | 38.99  | 38.99  | 0 |  |
| 1443 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4093 | 46ZS-93 | PN1622241235 | 1 | PL12*477       | 538.9  | 26.46  | 26.46  | 0 |  |
| 1444 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4094 | 46ZS-94 | PN1622241236 | 1 | PL12*342       | 738.2  | 32.21  | 32.21  | 0 |  |
| 1445 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4095 | 46ZS-95 | PN1622241237 | 1 | PL12*403       | 479    | 26.31  | 26.31  | 0 |  |
| 1446 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4096 | 46ZS-96 | PN1622241238 | 1 | PL12*379       | 393.9  | 27.56  | 27.56  | 0 |  |
|      | TB2-SDC.VP101-00UHA-A-M1A-DTE-4097 | 46ZS-97 | PN1622241239 | 1 | PL12*403       | 484    | 27.85  | 27.85  | 0 |  |



|      |                                    |          |              |      |                  |        |         |            |   |  |
|------|------------------------------------|----------|--------------|------|------------------|--------|---------|------------|---|--|
| 1448 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4098 | 46ZS-98  | PN1622241240 | 1    | PL14*474         | 458.1  | 33.6    | 33.6       | 0 |  |
| 1449 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4099 | 46ZS-99  | PN1622241241 | 1    | PL14*457         | 437.6  | 32.82   | 32.82      | 0 |  |
| 1450 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4100 | 46ZS-100 | PN1622241242 | 1    | PL14*447         | 453.7  | 32.3    | 32.3       | 0 |  |
| 1451 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4101 | 46ZS-101 | PN1622241243 | 1    | PL14*448         | 502.8  | 34.29   | 34.29      | 0 |  |
| 1452 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4102 | 46ZS-102 | PN1622241244 | 1    | PL14*440         | 453.8  | 32.92   | 32.92      | 0 |  |
| 1453 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4103 | 46ZS-103 | PN1622241245 | 1    | PL14*475         | 443    | 33.65   | 33.65      | 0 |  |
| 1454 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4104 | 46ZS-105 | PN1622241246 | 1    | PL14*441         | 453.4  | 31.45   | 31.45      | 0 |  |
| 1455 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4105 | 46ZS-108 | PN1622241247 | 1    | PL14*421         | 441.6  | 31.12   | 31.12      | 0 |  |
| 1456 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4106 | 46ZS-109 | PN1622241248 | 1    | PL14*429         | 433.3  | 30.96   | 30.96      | 0 |  |
| 1457 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4107 | 46ZS-110 | PN1622241249 | 1    | PL14*429         | 488.8  | 33.21   | 33.21      | 0 |  |
| 1458 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4108 | 46ZS-111 | PN1622241250 | 1    | PL14*428         | 479.6  | 32.29   | 32.29      | 0 |  |
| 1459 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4109 | 46ZS-112 | PN1622241251 | 1    | PL14*500         | 680.9  | 52.67   | 52.67      | 0 |  |
| 1460 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4110 | 46ZS-114 | PN1622241252 | 1    | PL12*507         | 695.7  | 42.52   | 42.52      | 0 |  |
| 1461 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4111 | 46ZS-119 | PN1622241253 | 1    | PL14*412         | 468.8  | 34.02   | 34.02      | 0 |  |
| 1462 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4112 | 46ZS-120 | PN1622241254 | 1    | PL12*548         | 560    | 47.4    | 47.4       | 0 |  |
| 1463 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4113 | 46ZS-121 | PN1622241255 | 1    | PL14*387         | 463    | 27.53   | 27.53      | 0 |  |
| 1464 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4114 | 46ZS-122 | PN1622241256 | 1    | PL14*522         | 558.1  | 46.71   | 46.71      | 0 |  |
| 1465 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4115 | 46ZS-125 | PN1622241257 | 1    | PL14*464         | 520.8  | 33.26   | 33.26      | 0 |  |
| 1466 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4116 | 46ZS-126 | PN1622241258 | 1    | PL14*387         | 463    | 27.53   | 27.53      | 0 |  |
| 1467 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4117 | 46ZS-127 | PN1622241259 | 4    | PL12*386         | 530.4  | 27.6    | 110.39     | 0 |  |
| 1468 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4118 | 46ZS-128 | PN1622241260 | 1    | PL12*388         | 560.9  | 28.76   | 28.76      | 0 |  |
| 1469 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4119 | 46ZS-129 | PN1622241261 | 1    | PL12*388         | 560.9  | 28.76   | 28.76      | 0 |  |
| 1470 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4120 | 46ZS-130 | PN1622241262 | 2    | PL12*379         | 504.6  | 27.44   | 54.89      | 0 |  |
| 1471 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4121 | 39PB-13  | PN1622241262 | 4    | C16A             | 517    | 8.91    | 35.63      | 0 |  |
| 1472 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4122 | 39PB-14  | PN1622241263 | 2    | C16A             | 850    | 17.78   | 35.56      | 0 |  |
| 1473 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4123 | 39PB-15  | PN1622241264 | 1    | C20A             | 4527   | 102.45  | 102.45     | 0 |  |
| 1474 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4124 | 39PB-16  | PN1622241265 | 1    | C20A             | 4600   | 104.11  | 104.11     | 0 |  |
| 1475 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4125 | 39P-15   | PN1622241266 | 1    | I16              | 2000   | 53.83   | 53.83      | 0 |  |
| 1476 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4126 | 4VB-199  | PN1622140416 | 1    | C16A             | 1740   | 139.91  | 139.91     | 0 |  |
| 1477 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4127 | 41HB-20  | PN1622241267 | 2    | HW175*175*7.5*11 | 4974.3 | 206.67  | 413.33     | 0 |  |
| 1478 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4128 | 41HB-26  | PN1622241268 | 2    | HW175*175*7.5*11 | 4965.2 | 206.3   | 412.6      | 0 |  |
| 1479 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4129 | 41ZS-73  | PN1622241269 | 1    | PL12*458         | 468    | 34.18   | 34.18      | 0 |  |
| 1480 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4130 | 41ZS-74  | PN1622241270 | 1    | PL12*458         | 468    | 34.18   | 34.18      | 0 |  |
| 1481 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4131 | 41ZS-75  | PN1622241271 | 1    | PL12*458         | 468    | 34.18   | 34.18      | 0 |  |
| 1482 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4132 | 41ZS-76  | PN1622241272 | 1    | PL12*458         | 468    | 34.18   | 34.18      | 0 |  |
| 1483 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4133 | 41B-70   | PN1622241273 | 4    | C16A             | 767.5  | 13.22   | 52.9       | 0 |  |
| 1484 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4134 | 41B-76   | PN1622241274 | 2    | C16A             | 905    | 15.59   | 31.19      | 0 |  |
| 1485 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4135 | 37HB-35  | PN1622241275 | 2    | HW300*300*10*15  | 6074.2 | 564.8   | 1129.59    | 0 |  |
| 1486 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4136 | 37ZS-61  | PN1622241276 | 2    | PL16*678         | 694    | 86.58   | 173.17     | 0 |  |
| 1487 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4137 | 37ZS-62  | PN1622241277 | 2    | PL16*858         | 874    | 120.21  | 240.42     | 0 |  |
| 1488 | TB2-SDC.VP101-00UHA-A-M1A-DTE-4138 | 41B-90   | PN1622241278 | 1    | HN596*199*10*15  | 18488  | 1792.21 | 1792.21    | 0 |  |
|      |                                    |          |              |      |                  |        |         |            |   |  |
|      |                                    |          |              | 2086 |                  |        |         | 1264717.06 |   |  |

